Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	October 13, 2009 WELL API NO.
District II 1625 N French Dr., Hobbs, NM 88240 District II 1301 W Grand Ave, Artesia, NM 88210 District III 1301 W Grand Ave, Artesia, NM 88210 1220 South St. Francis Dr.		30-025-33264
District III 1301 W Grand Ave, Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 APR 2 2 201220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 APR 22 2010 South St. Francis Dr. Santa Fe. NM 87505		STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S St Francis Dr , Santa Fe, NM HOBBSOCD 87505		B-2148
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number 147
2. Name of Operator SandRidge Exploration and Production, LLC		9. OGRID Number 270265
3. Address of Operator		10. Pool name or Wildcat
123 Robert S. Kerr Ave, Oklahoma City, OK 73102		Maljamar Grayburg San Andres
4. Well Location		
Unit Letter P :	1297 feet from the South line and 1	
Section 13 Township 17S Range 33E NMPM Lea County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4133' GR		
	4133 GK	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INT	FINTION TO: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
TEMPORARILY ABANDON	_	RILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	NT JOB 📙
DOWNHOLE COMMINGLE		
OTHER:	OTHER: CO & A	
13. Describe proposed or comple	tted operations. (Clearly state all pertinent details, a k). SEE RULE 19.15.7.14 NMAC. For Multiple C	and give pertinent dates, including estimated date
of starting any proposed wor	K). SEE RULE 19.13.7.14 NMAC. FOR MURUPIE C	omnienons. Allach wellbore diagram of
		ompletions. Ittaen weneble anglani of
proposed completion or reco	mpletion.	ompletions. Attach wencore diagram of
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg	mpletion. p. ND WH. NU BOP. in swabbing.	ompletions. Attach wencore diagram of
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not	mpletion. p. ND WH. NU BOP. in swabbing. ched collar & LD.	
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/19/10 RIH w/ 4-3/	mpletion. p. ND WH. NU BOP. tin swabbing. tiched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of	clean. RD reverse unit.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok.	mpletion. p. ND WH. NU BOP. cin swabbing. ched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of the collar with the collar	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g	mpletion. p. ND WH. NU BOP. tin swabbing. tiched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing.	mpletion. p. ND WH. NU BOP. pin swabbing. sched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1 2/25/10 RIH w/notched collar. RU va	mpletion. p. ND WH. NU BOP. gin swabbing. sched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of the collar o	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 1, max press 3600 psi. block. Set 10,000# on block. POOH w/ block.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1/2/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on ti	mpletion. p. ND WH. NU BOP. gin swabbing. sched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM LD. RIH w/ 2-7/8 tbg. POH w/ BHA. Ict truck. POH w/notched collar. RIH w/impression bbg. Tagged 4265'. Swedged out csg f/3'. Free up at	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 1, max press 3600 psi. block. Set 10,000# on block. POOH w/ block.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1/2/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on to 3/1/10 RU vac truck. RIH w/ 2-7/8", 6	mpletion. p. ND WH. NU BOP. cin swabbing. ched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM LD. RIH w/ 2-7/8 tbg. POH w/ BHA. cc truck. POH w/notched collar. RIH w/impression bg. Tagged 4265'. Swedged out csg f/3'. Free up at 6.5# tbg & set @ 4122". RDMO.	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 1, max press 3600 psi. block. Set 10,000# on block. POOH w/ block.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1/2/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on ti	mpletion. p. ND WH. NU BOP. cin swabbing. ched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM LD. RIH w/ 2-7/8 tbg. POH w/ BHA. cc truck. POH w/notched collar. RIH w/impression bg. Tagged 4265'. Swedged out csg f/3'. Free up at 6.5# tbg & set @ 4122". RDMO.	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 1, max press 3600 psi. block. Set 10,000# on block. POOH w/ block.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1/2/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on to 3/1/10 RU vac truck. RIH w/ 2-7/8", 6	mpletion. p. ND WH. NU BOP. cin swabbing. ched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM LD. RIH w/ 2-7/8 tbg. POH w/ BHA. cc truck. POH w/notched collar. RIH w/impression bg. Tagged 4265'. Swedged out csg f/3'. Free up at 6.5# tbg & set @ 4122". RDMO.	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 1, max press 3600 psi. block. Set 10,000# on block. POOH w/ block.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1/2/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on t 3/1/10 RU vac truck. RIH w/ 2-7/8", 6/3/12/10 29 BO, 7 MCF, 47 BW- 24 ho	mpletion. p. ND WH. NU BOP. gin swabbing. sched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM LD. RIH w/ 2-7/8 tbg. POH w/ BHA. Ice truck. POH w/notched collar. RIH w/impression of the bg. Tagged 4265'. Swedged out csg f/3'. Free up at 6.5# tbg & set @ 4122". RDMO. Dours	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 1, max press 3600 psi. block. Set 10,000# on block. POOH w/ block.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1/2/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on to 3/1/10 RU vac truck. RIH w/ 2-7/8", 6	mpletion. p. ND WH. NU BOP. cin swabbing. ched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM LD. RIH w/ 2-7/8 tbg. POH w/ BHA. cc truck. POH w/notched collar. RIH w/impression bg. Tagged 4265'. Swedged out csg f/3'. Free up at 6.5# tbg & set @ 4122". RDMO.	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 1, max press 3600 psi. block. Set 10,000# on block. POOH w/ block.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1/2/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on t 3/1/10 RU vac truck. RIH w/ 2-7/8", 6/3/12/10 29 BO, 7 MCF, 47 BW- 24 ho	mpletion. p. ND WH. NU BOP. gin swabbing. sched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM LD. RIH w/ 2-7/8 tbg. POH w/ BHA. Ice truck. POH w/notched collar. RIH w/impression of the bg. Tagged 4265'. Swedged out csg f/3'. Free up at 6.5# tbg & set @ 4122". RDMO. Dours	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 1, max press 3600 psi. block. Set 10,000# on block. POOH w/ block.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1 2/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on t 3/1/10 RU vac truck. RIH w/ 2-7/8", 6 3/12/10 29 BO, 7 MCF, 47 BW- 24 ho	mpletion. p. ND WH. NU BOP. gin swabbing. sched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM LD. RIH w/ 2-7/8 tbg. POH w/ BHA. Ice truck. POH w/notched collar. RIH w/impression of the bg. Tagged 4265'. Swedged out csg f/3'. Free up at 6.5# tbg & set @ 4122". RDMO. Dours	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 1, max press 3600 psi. block. Set 10,000# on block. POOH w/ block. 4268'. RIH to 4299'. Clean. POH. LD tools.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1 2/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on t 3/1/10 RU vac truck. RIH w/ 2-7/8", 6 3/12/10 29 BO, 7 MCF, 47 BW- 24 ho	mpletion. p. ND WH. NU BOP. gin swabbing. sched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of . RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM LD. RIH w/ 2-7/8 tbg. POH w/ BHA. Let truck. POH w/notched collar. RIH w/impression bg. Tagged 4265'. Swedged out csg f/3'. Free up at 6.5# tbg & set @ 4122". RDMO. Durs Rig Release Date:	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 1, max press 3600 psi. block. Set 10,000# on block. POOH w/ block. 4268'. RIH to 4299'. Clean. POH. LD tools.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1 2/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on t 3/1/10 RU vac truck. RIH w/ 2-7/8", 6 3/12/10 29 BO, 7 MCF, 47 BW- 24 ho	mpletion. p. ND WH. NU BOP. gin swabbing. sched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of . RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM LD. RIH w/ 2-7/8 tbg. POH w/ BHA. Let truck. POH w/notched collar. RIH w/impression bg. Tagged 4265'. Swedged out csg f/3'. Free up at 6.5# tbg & set @ 4122". RDMO. Durs Rig Release Date:	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 I, max press 3600 psi. block. Set 10,000# on block. POOH w/ block. 4268'. RIH to 4299'. Clean. POH. LD tools.
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 12/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on t 3/1/10 RU vac truck. RIH w/ 2-7/8", 6 3/12/10 29 BO, 7 MCF, 47 BW- 24 ho	mpletion. p. ND WH. NU BOP. gin swabbing. tched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of the collar o	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 I, max press 3600 psi. clock. Set 10,000# on block. POOH w/ block. 4268'. RIH to 4299'. Clean. POH. LD tools. dige and belief. DATE 4/21/10
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 1/2/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on t 3/1/10 RU vac truck. RIH w/ 2-7/8", 6/3/12/10 29 BO, 7 MCF, 47 BW- 24 ho	mpletion. p. ND WH. NU BOP. gin swabbing. tched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of the collar o	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 I, max press 3600 psi. block. Set 10,000# on block. POOH w/ block. 4268'. RIH to 4299'. Clean. POH. LD tools. lge and belief. DATE 4/21/10 com PHONE: 405-429-5682
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 12/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/ swedge, sub, jars on t 3/1/10 RU vac truck. RIH w/ 2-7/8", 6 3/12/10 29 BO, 7 MCF, 47 BW- 24 ho Spud Date: Type or print name	mpletion. p. ND WH. NU BOP. gin swabbing. sched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of RIH w/pkr to 3953'. Pickeled tbg w/350 gals acid gals 15% NEFE & 2850# rock salt. Max rate 5 BPM LD. RIH w/ 2-7/8 tbg. POH w/ BHA. sec truck. POH w/notched collar. RIH w/impression bg. Tagged 4265'. Swedged out csg f/3'. Free up at 65.5# tbg & set @ 4122". RDMO. Durs Rig Release Date: TITLE	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 I, max press 3600 psi. clock. Set 10,000# on block. POOH w/ block. 4268'. RIH to 4299'. Clean. POH. LD tools. dige and belief. ager DATE 4/21/10 com_ PHONE: 405-429-5682
proposed completion or record 2/16/10 MIRU. POOH w/rods & pum 2/17/10 Clean paraffin out of tbg. Beg 2/18/10 Tag fill @ 4132'. POH w/not 2/19/10 RIH w/ 4-3/4" bit, CD on 2-7/2/22/10 Hydrotest tbg & pkr to 6000# psi-ok. Acidize perfs @ 4062-4220' w/6000 g 2/23/10 SITP 700 psi. Swabbing. 2/24/10 SITP 600 psi. Release pkr & 12/25/10 RIH w/notched collar. RU va 2/26/10 RIH w/swedge, sub, jars on t 3/1/10 RU vac truck. RIH w/ 2-7/8", 6 3/12/10 29 BO, 7 MCF, 47 BW- 24 ho Spud Date: I hereby certify that the information all SIGNATURE Type or print name Terri Stathern	mpletion. p. ND WH. NU BOP. gin swabbing. tched collar & LD. /8". RU reverse unit. Clean out to 4335'. Circ hole of the collar o	clean. RD reverse unit. & reverse out. Set pkr & press annulus to 520 I, max press 3600 psi. clock. Set 10,000# on block. POOH w/ block. 4268'. RIH to 4299'. Clean. POH. LD tools. dge and belief. DATE 4/21/10 com PHONE: 405-429-5682