Submit 3 Copies To Appropriate District State of New Mexic	Form C-103
Office Energy, Minerals and Natural	Resources May 27, 2004
Submit 3 Copies To Appropriate District Office District 1 1625 N. French Dr , Hobbs, Mas 240 District II OH CONSERD VATION I	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 882101 ZOOU OIL CONSERVATION I District III 1220 South St. France	DIVISION 30-025-01276
District III 1220 South St. France	is Dr. 5. Indicate Type of Lease /
1000 Rio Brazos Rd., Aztec NM 87410 SOCD Santa Fe, NM 8750 District IV	05 STATE 😠 FEE 🗌
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
	E-9538
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) F PROPOSALS.)	PLUG BACK TO A STEATER TO 11261
1. Type of Well:	8. Well Number
Oil Well X Gas Well Other	001
2. Name of Operator	9. OGRID Number
CIMAREX ENERGY CO. OF COLORADO ATIN: ZENO FA	1
3. Address of Operator	10. Pool name or Wildcat
600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701	KEMNITZ, SOUTH (CISCO)
4. Well Location	1.0224115/ 50011 (01500)
Unit Letter A: 660feet from theNORTH	line and 660 feet from the EAST line
Section 26 Township 16S Ra	nge 33E NMPM County LEA
11. Elevation (Show whether DF 4,184'	R, RKB, RT, GR, etc.)
Pit or Below-grade Tank Application □ or Closure 🗵	
Pit type STEEL Depth to Groundwater Distance from nearest fresh w	vater well* Distance from nearest surface water*
	bbls; Construction Material * NONE WITHIN 1,000'
TEMPORARILY ABANDON CHANGE PLANS C PULL OR ALTER CASING CONDITIONS OF PA APPROVAL: Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. OCD Hobbs office needs C-103 "Check Off List for Surface Inspection". O4/08-14/10: FISH RODS X 2-7/8" TUBING FROM WELL; TOP	SUBSEQUENT REPORT OF: EMEDIAL WORK ALTERING CASING OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND ABANDONMENT ASING TEST AND EMENT JOB THER: PART details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion OF FISH @ 5,927'; M. BROWN W/ NMOCD OK'D TO PXA WELL.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS CO PULL OR ALTER CASING CONDITIONS OF PA APPROVAL: Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. OCD Hobbs office needs C-103 "Check Off List for Surface Inspection". O4/08-14/10: FISH RODS X 2-7/8" TUBING FROM WELL; TOP 04/15/10: PUMP A 50 SX. CMT. PLUG @ 5,927'; WCC - NO 104/16/10: TAG TOP OF CMT. PLUG @ 5,381'; CIRC.WELL W/ 04/17/10: PRES.UP ON CSG.CUT TO 1,000#-HELD; PUMP A 40 04/18/10: CUT X LAY DOWN 5-1/2" CSG. @ 3,011'; PUMP A A 40 SX. CMT. PLUG @ 1750'; WCC X TAG CMT. FUGCALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CIRC. OFF WH 3' B.G.L.; WELL ON STEEL PLATE X INST	SUBSEQUENT REPORT OF: EMEDIAL WORK ALTERING CASING OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: One of the proposed completion OF FISH @ 5,927'; M. EROWN W/ NMOCD OK'D TO PXA WELL. PAG; PUMP A 50 SX. CMT. PLUG W/ 2% CACL @ 5,927'; WCC PXA MUD; CUT 5-1/2" CSG. @ 4,533' - CSG. NOT FREE. SX. CMT. PLUG @ 4,575'; WCC X TAG CMT. PLUG @ 4,458'. 40 SX. CMT. PLUG @ 3,061'-2,910'(CALC.); MIX X PUMP PLUG @ 1,630'; PUMP A 40 SX. CMT. PLUG @ 395'-295' RC. TO SURF. A 60 SX. CMT. PLUG @ 63'-3'; DO X CUT PALL DRYHOLE MARKER. PLUGGED X ABANDONED 04/18/10.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS COMMITTENT CASING CHANGE PLANS CONDITIONS OF PA APPROVAL: Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. OCD Hobbs office needs C-103 "Check Off List for Surface Inspection". O4/08-14/10: FISH RODS X 2-7/8" TUBING FROM WELL; TOP 04/15/10: PUMP A 50 SX. CMT. PLUG @ 5,927'; WCC - NO 10 04/16/10: TAG TOP OF CMT. PLUG @ 5,927'; WCC - NO 10 04/16/10: TAG TOP OF CMT. PLUG @ 5,381'; CIRC.WELL W/ 04/17/10: PRES.UP ON CSG.CUT TO 1,000#-HELD; PUMP A 40 04/18/10: CUT X LAY DOWN 5-1/2" CSG. @ 3,011'; PUMP A A 40 SX. CMT. PLUG @ 1750'; WCC X TAG CMT. F (CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CIRC OFF WH 3' B.G.L.; WELD ON STEEL PLATE X INST	SUBSEQUENT REPORT OF: EMEDIAL WORK ALTERING CASING OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion OF FISH @ 5,927';M.EROWN W/ NMOCD OK'D TO PXA WELL. PAG; PUMP A 50 SX. CMT. PLUG W/ 2% CACL @ 5,927';WCC PXA MUD; CUT 5-1/2" CSG. @ 4,533' - CSG. NOT FREE. SX. CMT. PLUG @ 4,575';WCC X TAG CMT. PLUG @ 4,458'. 40 SX. CMT. PLUG @ 3,061'-2,910'(CALC.); MIX X PUMP PLUG @ 1,630'; PUMP A 40 SX. CMT. PLUG @ 395'-295' RC. TO SURF. A 60 SX. CMT. PLUG @ 63'-3'; DO X CUT PALL DRYHOLE MARKER. PLUGGED X ABANDONED 04/18/10. Test of my knowledge and belief. I further certify that any pit or below- X, a general permit or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS CONDITIONS OF PA APPROVAL: Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. OCD Hobbs office needs C-103 "Check Off List for Surface Inspection". 04/08-14/10: FISH RODS X 2-7/8" TUBING FROM WELL; TOP 04/15/10: PUMP A 50 SX. CMT. PLUG @ 5,927'; WOC - NO TO 04/16/10: TAG TOP OF CMT. PLUG @ 5,381'; CIRC.WELL W/ 04/17/10: PRES.UP ON CSG.CUT TO 1,000#-HELD; PUMP A 40 04/18/10: CUT X LAY DOWN 5-1/2" CSG. @ 3,011'; FUMP A A 40 SX. CMT. PLUG @ 1750'; WOC X TAG CMT. FLUG (CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CIRC OFF WH 3' B.G.L.; WELD ON STEEL PLATE X INSTITUTE. TITLE: SIGNATURE TITLE:	SUBSEQUENT REPORT OF: EMEDIAL WORK ALTERING CASING OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND ABANDONMENT THER: Pent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion OF FISH @ 5,927';M.BROWN W/ NMOCD OK'D TO PXA WELL. PAG; PUMP A 50 SX. OMT. PLUG W/ 2% CACL @ 5,927';WOC PXA MUD; CUT 5-1/2" CSG. @ 4,533' - CSG. NOT FREE. SX. OMT. PLUG @ 4,575';WOC X TAG OMT. PLUG @ 4,458'. 40 SX. OMT. PLUG @ 3,061'-2,910'(CALC.); MIX X PUMP PLUG @ 1,630'; PUMP A 40 SX. OMT. PLUG @ 395'-295' RC. TO SURF. A 60 SX. OMT. PLUG @ 63'-3'; DO X CUT PALL DRYHOLE MARKER. PLUGGED X ABANDONED 04/18/10. EST OF My knowledge and belief. I further certify that any pit or below-X, a general permit or an (attached) alternative OCD-approved plan AGENT DATE 04/20/10
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS CONDITIONS OF PA APPROVAL: Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. OCD Hobbs office needs C-103 "Check Off List for Surface Inspection". 04/08-14/10: FISH RODS X 2-7/8" TUBING FROM WELL; TOP 04/15/10: PUMP A 50 SX. CMT. PLUG @ 5,927'; WOC - NO TO 04/16/10: TAG TOP OF CMT. PLUG @ 5,381'; CIRC.WELL W/ 04/17/10: PRES.UP ON CSG.CUT TO 1,000#-HELD; PUMP A 40 04/18/10: CUT X LAY DOWN 5-1/2" CSG. @ 3,011'; FUMP A A 40 SX. CMT. PLUG @ 1750'; WOC X TAG CMT. FLUG (CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CIRC OFF WH 3' B.G.L.; WELD ON STEEL PLATE X INSTITUTE. TITLE: SIGNATURE TITLE:	SUBSEQUENT REPORT OF: EMEDIAL WORK ALTERING CASING OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND EMENT JOB THER: Inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion OF FISH @ 5,927';M.EROWN W/ NMOCD OK'D TO PXA WELL. PAG; PUMP A 50 SX. CMT. PLUG W/ 2% CACL @ 5,927';WCC PXA MUD; CUT 5-1/2" CSG. @ 4,533' - CSG. NOT FREE. SX. CMT. PLUG @ 4,575';WCC X TAG CMT. PLUG @ 4,458'. 40 SX. CMT. PLUG @ 3,061'-2,910'(CALC.); MIX X PUMP PLUG @ 1,630'; PUMP A 40 SX. CMT. PLUG @ 395'-295' RC. TO SURF. A 60 SX. CMT. PLUG @ 63'-3'; DO X CUT PALL DRYHOLE MARKER. PLUGGED X ABANDONED 04/18/10. Test of my knowledge and belief. I further certify that any pit or below- X, a general permit or an (attached) alternative OCD-approved plan
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS CONDITIONS OF PA APPROVAL: Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. OCD Hobbs office needs C-103 "Check Off List for Surface Inspection". O4/08-14/10: FISH RODS X 2-7/8" TUBING FROM WEIL; TOP 04/15/10: FUMP A 50 SX. CMT. PLUG @ 5,927'; WCC - NO TO 04/16/10: TAG TOP OF CMT. PLUG @ 5,381'; CIRC.WEIL W/ 04/17/10: PRES.UP CN CSG.CUT TO 1,000#-HEID; PUMP A 40 04/18/10: CUT X LAY DOWN 5-1/2" CSG. @ 3,011'; PUMP A A 40 SX. CMT. PLUG @ 1750'; WCC X TAG CMT. F (CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CI CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CI CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CI CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CI CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CI CALC.); TITLE E-mail	SUBSEQUENT REPORT OF: EMEDIAL WORK ALTERING CASING OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND ABANDONMENT THER: ABANDONMENT OF FISH @ 5,927';M.EROWN W/ NMOCD OK'D TO PXA WELL. PAG; PUMP A 50 SX. CMT. PLUG W/ 2% CACL @ 5,927';WCC PXA MID; CUT 5-1/2" CSG. @ 4,533' - CSG. NOT FREE. SX. CMT. PLUG @ 4,575';WCC X TAG CMT. PLUG @ 4,458'. 40 SX. CMT. PLUG @ 3,061'-2,910' (CALC.); MIX X PUMP PLUG @ 1,630'; PUMP A 40 SX. CMT. PLUG @ 395'-295' RC. TO SURF. A 60 SX. CMT. PLUG @ 63'-3'; DO X CUT PALL DRYHOLE MARKER. PLUGGED X ABANDONED 04/18/10. DESTORM DATE 04/20/10 AGENT DATE 04/20/10 DEYLER@MILACRO-RES.CCM Telephone No. (432) 687-3033
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS CONDITIONS OF PA APPROVAL: Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. OCD Hobbs office needs C-103 "Check Off List for Surface Inspection". O4/08-14/10: FISH RODS X 2-7/8" TUBING FROM WEIL; TOP 04/15/10: FUMP A 50 SX. CMT. PLUG @ 5,927'; WCC - NO TO 04/16/10: TAG TOP OF CMT. PLUG @ 5,381'; CIRC.WEIL W/ 04/17/10: PRES.UP CN CSG.CUT TO 1,000#-HEID; PUMP A 40 04/18/10: CUT X LAY DOWN 5-1/2" CSG. @ 3,011'; PUMP A A 40 SX. CMT. PLUG @ 1750'; WCC X TAG CMT. F (CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CI CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CI CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CI CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CI CALC.); PERF. 8-5/8" CSG. @ 63' X SQZ. X CI CALC.); TITLE E-mail	SUBSEQUENT REPORT OF: EMEDIAL WORK ALTERING CASING OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ASING TEST AND ABANDONMENT THER: Pent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion OF FISH @ 5,927';M.BROWN W/ NMOCD OK'D TO PXA WELL. PAG; PUMP A 50 SX. OMT. PLUG W/ 2% CACL @ 5,927';WOC PXA MUD; CUT 5-1/2" CSG. @ 4,533' - CSG. NOT FREE. SX. OMT. PLUG @ 4,575';WOC X TAG CMT. PLUG @ 4,458'. 40 SX. OMT. PLUG @ 3,061'-2,910'(CALC.); MIX X PUMP PLUG @ 1,630'; PUMP A 40 SX. OMT. PLUG @ 395'-295' RC. TO SURF. A 60 SX. OMT. PLUG @ 63'-3'; DO X CUT PALL DRYHOLE MARKER. PLUGGED X ABANDONED 04/18/10. THER: AGENT DATE 04/20/10 AGENT DATE 04/20/10