Submit 3 Copies To Appropriate District  Office  State of New M	
District! Energy, Minerals and Nat	well API NO.
	N DIVISION 30-025-34593
District II 1301 W Grand Ave., Artesia, NM PLONE GONSERVATION DISTRICT 1220 South St. Fra	5. Indicate Type of Lease STATE XX FEE
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV MAY 04 2010 Santa Fe, NM 8	6. State Oil & Gas Lease No.
1220 S St Francis Dr., Santa Fe, NM	AO-1118
SUNDRY NOTICES AND REPORTS ON WELL	S 7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLDIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) I	GOODWIN STATE  GOODWIN STATE
PROPOSALS.)	8. Well Number 1
1. Type of Well: Oil Well Gas Well Other xx SWD  2. Name of Operator	9. OGRID Number /
CHEYENNE WATER DISPOSAL SYSTEMS, LLC	269152
3. Address of Operator	10. Pool name or Wildcat
P. O. BOX 132, HOBBS, NM 88241	SWD;GB-SAN ANDRES-GLÖRIETA
4. Well Location	
Unit Letter D: 330 feet from the NORTH line and 330 feet from the WEST line  Section 6 Township 19S Range 37E NMPM LEA County	
11. Elevation (Show whether D.	
	The state of the s
Pit or Below-grade Tank Application or Closure	water well Distance from nearest surface water
Pit type Depth to Groundwater Distance from nearest fresh  Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls; Construction Material
12. Check Appropriate Box to Indicate	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐	CASING/CEMENT JOB
TOLL ON ALTER ORONO	
OTHER:	OTHER: XX CONVERT TO SWD
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p	OTHER: XX CONVERT TO SWD s, and give pertinent dates, including estimated date of starting any proposed work)
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p</li> <li>MIRU. NUBOP.</li> </ol>	OTHER: XX CONVERT TO SWD s, and give pertinent dates, including estimated date of starting any proposed work)
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1. MIRU. NUBOP.</li> <li>RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.</li> <li>Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to</li> </ol>	OTHER: XX CONVERT TO SWD  s, and give pertinent dates, including estimated date of starting any proposed work) roposed completion or recompletion  SWD - 827-B
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1.</li> <li>MIRU. NUBOP.</li> <li>RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.</li> <li>Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4.</li> <li>RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.</li> </ol>	other: XX convert to swd s, and give pertinent dates, including estimated date of starting any proposed work) roposed completion SWD - 827-B
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1.</li> <li>MIRU. NUBOP.</li> <li>RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.</li> <li>Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4.</li> <li>RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.</li> <li>Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Capped RD WL. RIH and set pkr. @ 5600'.</li> </ol>	other: XX convert to swd s, and give pertinent dates, including estimated date of starting any proposed work) roposed completion SWD - 827-B
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1.</li> <li>MIRU. NUBOP.</li> <li>RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.</li> <li>Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4.</li> <li>RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.</li> <li>Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Capped RD WL. RIH and set pkr. @ 5600'.</li> <li>Acidized w/4000 gals. 15% HCL-NE-FE &amp; 200 1.3 ball sealers @ 3-5 BPM.</li> </ol>	other: XX convert to swd s, and give pertinent dates, including estimated date of starting any proposed work) roposed completion SWD - 827-B
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. MIRU. NUBOP.</li> <li>RIH W/4 ¾" bit and casing scraper on 2 7/8" workstring.</li> <li>Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4. RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.</li> <li>Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Capper RD WL. RIH and set pkr. @ 5600'.</li> <li>Acidized w/4000 gals. 15% HCL-NE-FE &amp; 200 1.3 ball sealers @ 3-5 BPM.</li> <li>Release pkr. PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.</li> <li>Release pkr. &amp; POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p</li> </ol>	OTHER: XX CONVERT TO SWD  s, and give pertinent dates, including estimated date of starting any proposed work) roposed completion or recompletion  SWD - 827-B  1000 psi for 30 minutes. TOOH.  si for 15 min. OK. Spot 3 sx sand on RBP.
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1. MIRU. NUBOP.  2. RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. firesh water. Pressure tested csg. to 4. RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Capped RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr, PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p. 10. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and p. 11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze	OTHER: XX CONVERT TO SWD  s, and give pertinent dates, including estimated date of starting any proposed work) proposed completion or recompletion  Swb D - 827-B  1000 psi for 30 minutes. TOOH.  and w/35' cement.  si for 15 min. OK. Spot 3 sx sand on RBP.  compand 250 bbls. fresh water @ 1-4 BPM – achieved full returns.
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1. MIRU. NUBOP.  2. RIH W/4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4. RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Capper 6. RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr, PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p. 10. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and p. 11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze 12. Stung out of retainer. TOOH. WOC 48 hrs.	OTHER: XX CONVERT TO SWD  s, and give pertinent dates, including estimated date of starting any proposed work) proposed completion SWD - 827-B  1000 psi for 30 minutes. TOOH.  si for 15 min. OK. Spot 3 sx sand on RBP.  comped 250 bbls. fresh water @ 1-4 BPM – achieved full returns.  500 sxs Class C cement through holes in 5 ½" csg. @ 5100".
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1. MIRU. NUBOP.  2. RIH W/4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4. RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Cappe RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr. PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and p. 11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze. Stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4 ¾" bit and 6-3 ½" DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCI from 5606-2300'. TOC 2700'. Perforate 2	OTHER: XX CONVERT TO SWD  s, and give pertinent dates, including estimated date of starting any proposed work) proposed completion SWD - 827-B  1000 psi for 30 minutes. TOOH.  si for 15 min. OK. Spot 3 sx sand on RBP.  1000 psi for 30 minutes. TOOH.
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1. MIRU. NUBOP.  2. RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. firesh water. Pressure tested csg. to 4. RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Capper 6. RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr, PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 pth.  10. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and pth.  11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze 12. Stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4 ¾" bit and 6-3 ½" DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCl from 5606-2300'. TOC 2700'. Perforate 2 15. RD WL. RIH and set pkr. @ 5060'.  16. Acidize perfs. 5145-5690' w/4000 gals. 15% HCL-NE-FE + 150 ball sealers (6 15 15 15 15 15 15 15 15 15 15 15 15 15	OTHER: XX CONVERT TO SWD  s, and give pertinent dates, including estimated date of starting any proposed work) proposed completion SWD - 827-B  1000 psi for 30 minutes. TOOH.  and w/35' cement.  si for 15 min. OK. Spot 3 sx sand on RBP.  sumped 250 bbls. fresh water @ 1-4 BPM – achieved full returns.  500 sxs Class C cement through holes in 5 ½" csg. @ 5100'.  15594'. Circl. clean. Pressure tested to 500 psi.  spf @ 5145-69', 5206-39', 5638-90'.  20 5-8 BPM. Poor ball action Load tbg. w/6 bbls. fresh water, est. 1 BPJ inj.
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1. MIRU. NUBOP.  2. RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4. RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Capper 6. RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr. PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 pto 10. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and pto 11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4 ¾" bit and 6-3 ½" DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCl from 5606-2300'. TOC 2700'. Perforate 2 RD WL. RIH and set pkr. @ 5060'.  16. Acidize perfs. 5145-5690' w/4000 gals. 15% HCL-NE-FE + 150 ball sealers (Rate, pumped 130 bbls @ 1600 psi, ISIP 1500, 15 min 1100 psi. Acidized perfs. 6100 psi. Acidized perfs.	OTHER: XX CONVERT TO SWD  s, and give pertinent dates, including estimated date of starting any proposed work) proposed completion SWD - 827-B  1000 psi for 30 minutes. TOOH.  and w/35' cement.  si for 15 min. OK. Spot 3 sx sand on RBP.  sumped 250 bbls. fresh water @ 1-4 BPM – achieved full returns.  500 sxs Class C cement through holes in 5 ½" csg. @ 5100'.  15594'. Circl. clean. Pressure tested to 500 psi.  spf @ 5145-69', 5206-39', 5638-90'.  20 5-8 BPM. Poor ball action Load tbg. w/6 bbls. fresh water, est. 1 BPJ inj.
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. MIRU. NUBOP.  2. RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. firesh water. Pressure tested csg. to RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Cappe RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr, PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and p. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze.  12. Stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4 ¾" bit and 6-3 ½" DCs and TIH. Drilled cement retainer and cement to the RU WL. Ran GR/CNL/CBL/CCl from 5606-2300'. TOC 2700'. Perforate 2.  15. RD WL. RIH and set pkr. @ 5060'.  16. Acidize perfs. 5145-5690' w/4000 gals. 15% HCL-NE-FE + 150 ball sealers (2 Rate, pumped 130 bbls @ 1600 psi, ISIP 1500, 15 min 1100 psi. Acidized per brine; fair blocking action, ISIP 1540, 5 min 1390.  17. RU WL. Perforate San Andres 2 SPF 4370-82, 4392-95, 4506-20, 4544-57, 45	OTHER: XX CONVERT TO SWD  s, and give pertinent dates, including estimated date of starting any proposed work) proposed completion SWD - 827-B  1000 psi for 30 minutes. TOOH.  si for 15 min. OK. Spot 3 sx sand on RBP.  sumped 250 bbls. fresh water @ 1-4 BPM - achieved full returns.  500 sxs Class C cement through holes in 5 ½" csg. @ 5100".  15594'. Circl. clean. Pressure tested to 500 psi.  spf @ 5145-69', 5206-39', 5638-90'.  2 5-8 BPM. Poor ball action Load tbg. w/6 bbls. fresh water, est. 1 BPJ inj.  1 fs 5145-5690' w/ 7500 gals. 15% HCL-NE-FE + 2000# rock salt in gelled
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. MIRU. NUBOP.  2. RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. firesh water. Pressure tested csg. to RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Cappe RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr. PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p. 10. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and p. 11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze. 12. Stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4 ¾" bit and 6-3 ½" DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCl from 5606-2300'. TOC 2700'. Perforate 2. The Number of State Perforate 2. Stung out of perforate 2. Stung out of perforate 2. Stung out of retainer. TOOH. WOC 48 hrs.  14. RU WL. Ran GR/CNL/CBL/CCl from 5606-2300'. TOC 2700'. Perforate 2. RD WL. RIH and set pkr. @ 5060'.  15. RD WL. RIH and set pkr. @ 5060'.  16. Acidize perfs. 5145-5690' w/4000 gals. 15% HCL-NE-FE + 150 ball sealers (Rate, pumped 130 bbls @ 1600 psi, ISIP 1500, 15 min 1100 psi. Acidized per brine; fair blocking action, ISIP 1540, 5 min 1390.  17. RU WL. Perforate San Andres 2 SPF 4370-82, 4392-95, 4506-20, 4544-57, 4. RIH and set and tested RBP @ 5061', tested to 200 psi. Set pkr. @ 4776'.	other: XX convert to swd s, and give pertinent dates, including estimated date of starting any proposed work) proposed completion Swd - 827-B  1000 psi for 30 minutes. TOOH.  1000 psi for 30 minutes.  1000 psi for 30 minut
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. MIRU. NUBOP.  2. RIH W/4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. firesh water. Pressure tested csg. to 4. RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Capper RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr. PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p. 10. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and p. 11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze. 12. Stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4¾" bit and 6-3½" DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCl from 5606-2300'. TOC 2700'. Perforate 2. The pumped 130 bbls @ 1600 psi, ISIP 1500, 15 min 1100 psi. Acidized per brine; fair blocking action, ISIP 1540, 5 min 1390.  17. RU WL. Perforate San Andres 2 SPF 4370-82, 4392-95, 4506-20, 4544-57, 4. RIH and set and tested RBP @ 5061', tested to 200 psi. Set pkr. @ 4776'.  18. RIH and set and tested RBP @ 5061', tested to 200 psi. Set pkr. @ 4776'.  19. Acidize perforations interval 4854-4990' w/ 4200 gals. 15% HCL-NE-FE ac. 20. Reset RBP 4786' and pkr. @ 4456'. Acidized 4506-4660' w/ 4000 gals. 15%	OTHER: XX CONVERT TO SWD  s, and give pertinent dates, including estimated date of starting any proposed work) roposed completion SWD - 827-B  1000 psi for 30 minutes. TOOH.  si for 15 min. OK. Spot 3 sx sand on RBP.  bumped 250 bbls. fresh water @ 1-4 BPM - achieved full returns.  500 sxs Class C cement through holes in 5 ½" csg. @ 5100".  15594'. Circl. clean. Pressure tested to 500 psi.  spf @ 5145-69", 5206-39", 5638-90".  26 5-8 BPM. Poor ball action Load tbg. w/6 bbls. fresh water, est. 1 BPJ inj.  fs 5145-5690" w/ 7500 gals. 15% HCL-NE-FE + 2000# rock salt in gelled  14572-82, 4630-60, 4854-84, 4972-90".  id and 150 ball sealers.  6 HCL-NE-FE and 108 ball sealers.
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. MIRU. NUBOP.  2. RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. firesh water. Pressure tested csg. to RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Capped RD WL. RIH and set pkr. @ 5600'.  6. RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr. PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and p. 11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze. Stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4 ¾" bit and 6-3 ½" DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCl from 5606-2300'. TOC 2700'. Perforate 2. The RU WL. Ran GR/CNL/CBL/CCl from 5606-2300'. TOC 2700'. Perforate 2. Rate, pumped 130 bbls @ 1600 psi, ISIP 1500, 15 min 1100 psi. Acidized per brine; fair blocking action, ISIP 1540, 5 min 1390.  17. RU WL. Perforate San Andres 2 SPF 4370-82, 4392-95, 4506-20, 4544-57, 18. RIH and set and tested RBP @ 5061', tested to 200 psi. Set pkr. @ 4776'.  19. Acidize perforations interval 4854-4990' w/ 4200 gals. 15% HCL-NE-FE ac. 20. Reset RBP 4786' and pkr. @ 4456'. Acidized 4506-4660' w/ 4000 gals. 15% HCL-NE-FE. 20. Reset RBP 4786' and pkr. @ 4456'. Acidized 4506-4660' w/ 4000 gals. 15% HCL-NE-FE. 20. Reset RBP 4786' and acidized 4370-4660' w/ 4200 gals. 15% HCL-NE-FE. 20. Reset RBP 4786' and acidized 4370-4660' w/ 4200 gals. 15% HCL-NE-FE. 20. Reset RBP 4786' and acidized 4370-4660' w/ 4200 gals. 15% HCL-NE-FE. 20. Reset RBP 4786' and acidized 4370-4660' w/ 4200 gals. 15% HCL-NE-FE. 20. Reset RBP 4786' and acidized 4370-4660' w/ 4200 gals. 15% HCL-NE-FE. 20	OTHER: XX CONVERT TO SWD  s, and give pertinent dates, including estimated date of starting any proposed work) roposed completion SWD - 827-B  1000 psi for 30 minutes. TOOH.  si for 15 min. OK. Spot 3 sx sand on RBP.  bumped 250 bbls. fresh water @ 1-4 BPM - achieved full returns.  500 sxs Class C cement through holes in 5 ½" csg. @ 5100".  15594'. Circl. clean. Pressure tested to 500 psi.  spf @ 5145-69", 5206-39", 5638-90".  26 5-8 BPM. Poor ball action Load tbg. w/6 bbls. fresh water, est. 1 BPJ inj.  fs 5145-5690" w/ 7500 gals. 15% HCL-NE-FE + 2000# rock salt in gelled  14572-82, 4630-60, 4854-84, 4972-90".  id and 150 ball sealers.  6 HCL-NE-FE and 108 ball sealers.
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. MIRU. NUBOP.  2. RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4. RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Capper RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr, PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p. 10. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and p. 11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze 12. Stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4 ¾" bit and 6- 3 ½" DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCl from 5606-2300'. TOC 2700'. Perforate 2. The first blocking action, ISIP 1540, 5 min 1390.  16. Acidize perfs. 5145-5690' w/4000 gals. 15% HCL-NE-FE + 150 ball sealers (Rate, pumped 130 bbls @ 1600 psi, ISIP 1500, 15 min 1100 psi. Acidized per brine; fair blocking action, ISIP 1540, 5 min 1390.  17. RU WL. Perforate San Andres 2 SPF 4370-82, 4392-95, 4506-20, 4544-57, 41. RIH and set and tested RBP @ 5061', tested to 200 psi. Set pkr. @ 4776'.  19. Acidize perforations interval 4854-4990' w/ 4200 gals. 15% HCL-NE-FE acc.  20. Reset RBP 4786' and pkr. @ 4456'. Acidized 4506-4660' w/ 4000 gals. 15% HCL-NE-FE acc.  21. Reset pkr. @ 4296' and acidized 4370-4660' w/ 4200 gals. 15% HCL-NE-FE acc.  22. POOH. RIH and tag PBTD 5600'.  23. RIH and with 5 ½" Arrowset 1 pkr. and 133 jts. 2 7/8" plastic-coated tbg. Di	Some of the standard of the st
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1. MIRU. NUBOP.  2. RIH W/ 4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513". Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4. RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000". TOC 5350".  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230". Cappe 6. RD WL. RIH and set pkr. @ 5600".  6. RD WL. RIH and set pkr. @ 5600".  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr, PU and reset pkr. @ 5600". Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600". Tested RBP to 1000 p. 10. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100". NU on 5 ½" csg. and p. 11. TIH w cement retainer and set @ 4887". RU cementers and circulate/squeeze 12. Stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4 ¾" bit and 6-3 ½" DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCl from 5606-2300". TOC 2700". Perforate 2 15. RD WL. RIH and set pkr. @ 5060".  16. Acidize perfs. 5145-5690" w/4000 gals. 15% HCL-NE-FE + 150 ball sealers (Rate, pumped 130 bbls @ 1600 psi, ISIP 1500, 15 min 1100 psi. Acidized per brine; fair blocking action, ISIP 1540, 5 min 1390.  17. RU WL. Perforate San Andres 2 SPF 4370-82, 4392-95, 4506-20, 4544-57, 18. RIH and set and tested RBP @ 5061", tested to 200 psi. Set pkr. @ 4776".  19. Acidize perforations interval 4854-4990" w/ 4200 gals. 15% HCL-NE-FE ac 20. Reset RBP 4786" and pkr. @ 4456". Acidized 4506-4660" w/ 4000 gals. 159 (21. Reset pkr. @ 4296" and acidized 4370-4660" w/ 4200 gals. 15% HCL-NE-FE ac 20. Reset RBP 4786" and pkr. @ 4456". Acidized 4506-4660" w/ 4000 gals. 159 (21. Reset pkr. @ 4296" and acidized 4370-4660" w/ 4200 gals. 15% HCL-NE-FE 22. POOH. RIH and tag PBTD 5600".  23. RIH and with 5 ½" Arrowset 1 pkr. and 133 jts. 2 7/8" plastic-coated tbg. Di 24. Pressure tested annulus to 500 psi for 30 min. Chart attac	Some of the standard of the st
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1. MIRU. NUBOP.  2. RIH W/ 4 3/4" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4. RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Capper 6. RD WL. RIH and set pkr. @ 5600'.  6. RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr, PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p. 10. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and p. 11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze 12. Stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4 ¾" bit and 6- 3 ½" DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCI from 5606-2300'. TOC 2700'. Perforate 2 15. RD WL. RIH and set pkr. @ 5060'.  16. Acidize perfs. 5145-5690' w/4000 gals. 15% HCL-NE-FE + 150 ball sealers (8 Rate, pumped 130 bbls @ 1600 psi, ISIP 1500, 15 min 1100 psi. Acidized per brine; fair blocking action, ISIP 1540, 5 min 1390.  17. RU WL. Perforate San Andres 2 SPF 4370-82, 4392-95, 4506-20, 4544-57, 18. RIH and set and tested RBP @ 5061', tested to 200 psi. Set pkr. @ 4776'.  19. Acidize perforations interval 4854-4990' w/ 4200 gals. 15% HCL-NE-FE ac 20. Reset RBP 4786' and pkr. @ 4456'. Acidized 4506-4660' w/ 4000 gals. 159 (21. Reset pkr. @ 4296' and acidized 4370-4660' w/ 4200 gals. 15% HCL-NE-FE 22. POOH. RIH and tag PBTD 5600'.  23. RIH and with 5 ½" Arrowset 1 pkr. and 133 jts. 2 7/8" plastic-coated tbg. Di 24. Pressure tested annulus to 500 psi for 30 min. Chart attached. Est. inj. down 2500 psi for 30 min. Chart attached. Est. inj. down 2500 psi for 30 min. Chart attached. Est. inj. down 2500 psi for 30 min. Char	Some of the standard of the st
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1. MIRU. NUBOP.  2. RIH W/4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4. RU WL. Ran GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Cappe 6. RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM. 8. Release pkr, PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +. 9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p. 10. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½" csg. and p. 11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze 12. Stung out of retainer. TOOH. WOC 48 hrs. 13. PU 4¾" bit and 6- 3 ½" DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCI from 5606-2300'. TOC 2700'. Perforate 2. 15. RD WL. RIH and set pkr. @ 5060'.  16. Acidize perfs. 5145-5690' w/4000 gals. 15% HCL-NE-FE + 150 ball sealers (Rate, pumped 130 bbls @ 1600 psi, ISIP 1500, 15 min 1100 psi. Acidized per brine; fair blocking action, ISIP 1540, 5 min 1390.  17. RU WL. Perforate San Andres 2 SPF 4370-82, 4392-95, 4506-20, 4544-57, 4. RIH and set and tested RBP @ 5061', tested to 200 psi. Set pkr. @ 4776'. P. Acidize perforations interval 4854-4990' w/ 4200 gals. 15% HCL-NE-FE ac 20. Reset RBP 4786' and pkr. @ 4456'. Acidized 4506-4660' w/ 4000 gals. 159. POOH. RIH and tag PBTD 5600'.  23. RIH and with 5 ½" Arrowset 1 pkr. and 133 jts. 2 7/8" plastic-coated tbg. Di 24. Pressure tested annulus to 500 psi for 30 min. Chart attached. Est. inj. down 25. Well shut-in waiting on facility to be built.  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further or guidelines □, a general permit □ or an (attached) alternative OCD-approved plan □.	Some of the standard of the st
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1. MIRU. NUBOP.  2. RIH W/ 4 ½" bit and easing scraper on 2 7/8" workstring.  3. Tag @ 6513". Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4. RU WL. Ram GR/CNL/CBL/CCL from PBTD to 5000". TOC 5350".  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230". Cappe 6. RD WL. RIH and set pkr. @ 5600".  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr, PU and reset pkr. @ 5600". Injected 1 bpm @ 600 psi - B. Release pkr. & POOH. RIH w/ RBP and set @ 5600". Tested RBP to 1000 p. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100". NU on 5 ½" csg. and p. 11. TIH w cement retainer and set @ 4887". RU cementers and circulate/squeeze 12. Stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4 ¾" bit and 6-3 ½" DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCl from 5606-2300". TOC 2700". Perforate 2 St. RD WL. RIH and set pkr. @ 5060".  16. Acidize perfs. 5145-5690" w/4000 gals. 15% HCL-NE-FE + 150 ball sealers (Rate, pumped 130 bbls @ 1600 psi, ISIP 1500, 15 min 1100 psi. Acidized per brine; fair blocking action, ISIP 1540, 5 min 1390.  17. RU WL. Perforate San Andres 2 SPF 4370-82, 4392-95, 4506-20, 4544-57, 18. RIH and set and tested RBP @ 5061", tested to 200 psi. Set pkr. @ 4776".  18. RIH and set and tested RBP @ 5061", tested to 200 psi. Set pkr. @ 4776".  19. Acidize perforations interval 4854-4990" w/ 4200 gals. 15% HCL-NE-FE ac 20. Reset RBP 4786" and pkr. @ 4456". Acidized 4506-4660" w/ 4000 gals. 15% HCL-NE-FE 22. POOH. RIH and tag PBTD 5600".  23. RIH and with 5 ½" Arrowset 1 pkr. and 133 jts. 2 7/8" plastic-coated tbg. Di 24. Pressure tested annulus to 500 psi for 30 min. Chart attached. Est. inj. down 25 psi pkr. @ 4296" and acidized 4370-4660" w/ 4200 gals. 15% HCL-NE-FE 22. POOH. RIH and tag PBTD 5600".  24. Pressure tested annulus to 500 psi for 30 min. Chart at	Some of the standard of the st
13. Describe proposed or completed operations. (Clearly state all pertinent detail SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of p. 1. MIRU. NUBOP.  2. RIH W/4 ¾" bit and casing scraper on 2 7/8" workstring.  3. Tag @ 6513'. Displace hole w/140 bbls. fresh water. Pressure tested csg. to 4. RU WL. Ram GR/CNL/CBL/CCL from PBTD to 5000'. TOC 5350'.  5. Perforated 2 spf @ 5670-94, 5755-5810, 6020-44. Set CIBP @ 6230'. Cappe 6. RD WL. RIH and set pkr. @ 5600'.  6. RD WL. RIH and set pkr. @ 5600'.  7. Acidized w/4000 gals. 15% HCL-NE-FE & 200 1.3 ball sealers @ 3-5 BPM.  8. Release pkr. PU and reset pkr. @ 5600'. Injected 1 bpm @ 600 psi +.  9. Release pkr. & POOH. RIH w/ RBP and set @ 5600'. Tested RBP to 1000 p. 10. RU WL. Perforate 4 squeeze holes (4 spf) @ 5100'. NU on 5 ½' csg. and p. 11. TIH w cement retainer and set @ 4887'. RU cementers and circulate/squeeze. Stung out of retainer. TOOH. WOC 48 hrs.  13. PU 4 ¾'' bit and 6-3 ½' DCs and TIH. Drilled cement retainer and cement to 14. RU WL. Ran GR/CNL/CBL/CCl from 5606-2300'. TOC 2700'. Perforate 2. Rou WL. RIH and set pkr. @ 5060'.  16. Acidize perfs. 5145-5690' w/4000 gals. 15% HCL-NE-FE + 150 ball sealers (Rate, pumped 130 bbls @ 1600 psi, ISIP 1500, 15 min 1100 psi. Acidized per brine; fair blocking action, ISIP 1540, 5 min 1390.  17. RU WL. Perforate San Andres 2 SPF 4370-82, 4392-95, 4506-20, 4544-57, 19. Acidize perfsc and acidized 4854-4990' w/4200 gals. 15% HCL-NE-FE ac 20. Reset RBP 4786' and pkr. @ 4456'. Acidized 4506-4660' w/ 4000 gals. 159. Reset pkr. @ 4296' and acidized 4370-4660' w/ 4200 gals. 15% HCL-NE-FE ac 20. Reset RBP 4786' and pkr. @ 4456'. Acidized 4506-4660' w/ 4000 gals. 159. Reset pkr. @ 4296' and acidized 4370-4660' w/ 4200 gals. 15% HCL-NE-FE 2. POOH. RIH and tag PBTD 5600'.  23. RIH and with 5 ½' Arrowset 1 pkr. and 133 jts. 2 7/8' plastic-coated tbg. Di 24. Pressure tested annulus to 500 psi for 30 min. Chart attached. Est. inj. down 25. Well shut-in waiting on facility to be built.  1 hereby certify that th	Some of the starting and proposed work)  Some of the starting and proposed wor

