$O_{1} = (1, 0)$ To Assume which Distance $O_{1} = O_{1} = O_{1}$		
Submit 1 Copy To Appropriate District State of New Mexico	Form C-103 October 13, 2009	
Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 882142 A PROFESSION	30 025 31981 5. Indicate Type of Lease	
District II 1301 W. Grand Ave., Artesia, NM 882 CERVEGONSERVATION DIVISION District III 1000 Bin Deserve Bid. Actes. NM 87410	STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
District IV 1220 S. St. Francis Dr., Santa Fe, NM JUL 08 2010 87505		
SUNDRY NOTOFIS SUDDLEPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Caprock Maljamar Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS.) 1. Type of Well: Oil Well x Gas Well Other	8. Well Number 128	
2. Name of Operator	9. OGRID Number 270265 /	
SandRidge Exploration & Production, LLC 3. Address of Operator	10. Pool name or Wildcat G-SA	
123 Robert S Kerr Ave, OKC OK 73102-6406	Malianar	
4. Well Location	- 1 april	
Unit Letter_H:_1365feet from theN line and _1260	feet from theEline $\checkmark$	
Section 18 Township 17S Range 33E	NMPM LEA County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SU	BSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	RK X ALTERING CASING 🗌	
PULL OR ALTER CASING I MULTIPLE COMPL CASING/CEME		
OTHER: OTHER: Fish junk; c/o well		
13. Describe proposed of completed operations. (Clearly state an pertment details, c	and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C	and give pertinent dates, including estimated date completions: Attach wellbore diagram of	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion. 2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.	ompletions: Attach wellbore diagram of	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.</li> <li>2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.</li> <li>2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to</li> </ul>	ompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH.	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.</li> <li>2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.</li> <li>2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr &amp; 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs</li> </ul>	p of csg, but could not get inside. Pld sub. POH. 114-4789 w/6000 gals 15% nefe w/adds in 4	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.</li> <li>2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.</li> <li>2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr &amp; 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals &amp; rev out. Set pkr &amp; press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load.</li> </ul>	p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK.	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.</li> <li>2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.</li> <li>2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr &amp; 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals &amp; rev out. Set pkr &amp; press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load.</li> <li>2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set</li> </ul>	ompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK. TAC. SU WH. Ran pmp and rods. RU pmp trk.	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.</li> <li>2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.</li> <li>2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr &amp; 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals &amp; rev out. Set pkr &amp; press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load.</li> <li>2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set Loaded tbg &amp; press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production.</li> <li>2-26-10 Not pumping.</li> </ul>	ompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK. TAC. SU WH. Ran pmp and rods. RU pmp trk.	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.</li> <li>2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.</li> <li>2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr &amp; 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals &amp; rev out. Set pkr &amp; press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load.</li> <li>2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set Loaded tbg &amp; press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production.</li> <li>2-26-10 Not pumping.</li> <li>3-2-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. All</li> </ul>	ompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK. TAC. SU WH. Ran pmp and rods. RU pmp trk.	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.</li> <li>2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.</li> <li>2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr &amp; 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals &amp; rev out. Set pkr &amp; press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load.</li> <li>2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set Loaded tbg &amp; press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production.</li> <li>2-26-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. Al 3-3-10 Ran pmp and rods, replaced <sup>3</sup>/4". Hung well on. Press tbg to 500 psi – OK. RD PU</li> </ul>	ompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK. TAC. SU WH. Ran pmp and rods. RU pmp trk.	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.</li> <li>2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.</li> <li>2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr &amp; 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals &amp; rev out. Set pkr &amp; press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load.</li> <li>2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set Loaded tbg &amp; press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production.</li> <li>2-26-10 Not pumping.</li> <li>3-2-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. All</li> </ul>	ompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK. TAC. SU WH. Ran pmp and rods. RU pmp trk.	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.</li> <li>2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.</li> <li>2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr &amp; 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals &amp; rev out. Set pkr &amp; press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load.</li> <li>2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set Loaded tbg &amp; press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production.</li> <li>2-26-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. Al 3-3-10 Ran pmp and rods, replaced <sup>3</sup>/4". Hung well on. Press tbg to 500 psi – OK. RD PU (continued page 2)</li> </ul>	ompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK. TAC. SU WH. Ran pmp and rods. RU pmp trk.	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.</li> <li>2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.</li> <li>2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr &amp; 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals &amp; rev out. Set pkr &amp; press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load.</li> <li>2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set Loaded tbg &amp; press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production.</li> <li>2-26-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. Al 3-3-10 Ran pmp and rods, replaced <sup>3</sup>/4". Hung well on. Press tbg to 500 psi – OK. RD PU</li> </ul>	ompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK. TAC. SU WH. Ran pmp and rods. RU pmp trk.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion. 2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg. 2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr & 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals & rev out. Set pkr & press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load. 2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set Loaded tbg & press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production. 2-26-10 Not pumping. 3-2-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. Al 3-3-10 Ran pmp and rods, replaced <sup>3</sup> /4". Hung well on. Press tbg to 500 psi – OK. RD PU (continued page 2) Spud Date: Rig Release Date:	Pompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK. TAC. SU WH. Ran pmp and rods. RU pmp trk. II ¾" rods corkscrewed. RIH w/3/4" rods. U.	
<ul> <li>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.</li> <li>2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg.</li> <li>2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr &amp; 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals &amp; rev out. Set pkr &amp; press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load.</li> <li>2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set Loaded tbg &amp; press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production.</li> <li>2-26-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. Al 3-3-10 Ran pmp and rods, replaced <sup>3</sup>/4". Hung well on. Press tbg to 500 psi – OK. RD PU (continued page 2)</li> </ul>	Pompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK. TAC. SU WH. Ran pmp and rods. RU pmp trk. II ¾" rods corkscrewed. RIH w/3/4" rods. U.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion. 2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg. 2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr & 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals & rev out. Set pkr & press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load. 2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set Loaded tbg & press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production. 2-26-10 Not pumping. 3-2-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. Al 3-3-10 Ran pmp and rods, replaced ¾". Hung well on. Press tbg to 500 psi – OK. RD PU (continued page 2) Spud Date: Rig Release Date: Rig Release Date:	Tompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK. TAC. SU WH. Ran pmp and rods. RU pmp trk. Il ¾" rods corkscrewed. RIH w/3/4" rods. U.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion. 2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg. 2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/pkr & 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals & rev out. Set pkr & press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load. 2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set Loaded tbg & press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production. 2-26-10 Not pumping. 3-2-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. Al 3-3-10 Ran pmp and rods, replaced <sup>3</sup> /4". Hung well on. Press tbg to 500 psi – OK. RD PU (continued page 2) Spud Date: Rig Release Date:	Pompletions: Attach wellbore diagram of p of csg, but could not get inside. Pld sub. POH. 4114-4789 w/6000 gals 15% nefe w/adds in 4 – OK. TAC. SU WH. Ran pmp and rods. RU pmp trk. Il ¾" rods corkscrewed. RIH w/3/4" rods. U.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion. 2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg. 2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215". Wrkd sub, could set on to 2-15-10 RIH w/pkr & 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs <sup>-4</sup> stgs. AIR 4.7 BPM. Pickled tbg w/350 gals & rev out. Set pkr & press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load. 2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188". ND BOP. Set Loaded tbg & press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production. 2-26-10 Not pumping. 3-2-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. AI 3-3-10 Ran pmp and rods, replaced <sup>3</sup> /4". Hung well on. Press tbg to 500 psi – OK. RD PI (continued page 2) Spud Date: Rig Release Date: Rig Release Date: SIGNATURE Mut Mut Mut Mut Mat Manager Type or print name _Terri Stathem E-mail address:tdstathem@:	P of csg, but could not get inside. Pld sub. POH.         \$114-4789 w/6000 gals 15% nefe w/adds in 4         - OK.         TAC. SU WH. Ran pmp and rods. RU pmp trk.         Il ¾" rods corkscrewed. RIH w/3/4" rods.         U.         dge and belief.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion. 2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg. 2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215'. Wrkd sub, could set on to 2-15-10 RIH w/ptr & 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs 4 stgs. AIR 4.7 BPM. Pickled tbg w/350 gals & rev out. Set pkr & press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load. 2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'. ND BOP. Set Loaded tbg & press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production. 2-26-10 Not pumping. 3-2-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. Al 3-3-10 Ran pmp and rods, replaced <sup>3</sup> /4". Hung well on. Press tbg to 500 psi – OK. RD PI (continued page 2) Spud Date: Rig Release Date: Rig Release Date: Type or print name _Terri Stathem E-mail address:tdstathem@: For State Use Only	completions: Attach wellbore diagram of         p of csg, but could not get inside. Pld sub. POH.         4114-4789 w/6000 gals 15% nefe w/adds in 4         – OK.         TAC. SU WH. Ran pmp and rods. RU pmp trk.         Il ¾" rods corkscrewed. RIH w/3/4" rods.         U.	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion. 2-11-10 MI RU PU. Bled well dn. Pld pump. ND WH, NU BOP. Pld tbg. 2-12-10 RIH w/2-7/8" WS. Tgd @ 4209, worked dn to 4215". Wrkd sub, could set on to 2-15-10 RIH w/pkr & 2-7/8" WS, tstg to 6000 psi. RD testers. RU Rising Star. A/perfs <sup>-4</sup> stgs. AIR 4.7 BPM. Pickled tbg w/350 gals & rev out. Set pkr & press annulus to 480 psi 2-16-10 Flowed and swabbed well. Recovered all load. 2-17-10 Pld pkr. RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188". ND BOP. Set Loaded tbg & press to 500 psi – OK. RD pmp trk. RD PU. Returned well to production. 2-26-10 Not pumping. 3-2-10 MI RU PU. Pld rods. RIH w/fishing tool, caught fish, unseated pmp and POH. AI 3-3-10 Ran pmp and rods, replaced <sup>3</sup> /4". Hung well on. Press tbg to 500 psi – OK. RD PI (continued page 2) Spud Date: Rig Release Date: Rig Release Date: SIGNATURE Mut Mut Mut Mut Mat Manager Type or print name _Terri Stathem E-mail address:tdstathem@:	Pompletions: Attach wellbore diagram of         p of csg, but could not get inside. Pld sub. POH.         4114-4789 w/6000 gals 15% nefe w/adds in 4         – OK.         TAC. SU WH. Ran pmp and rods. RU pmp trk.         Il ¾" rods corkscrewed. RIH w/3/4" rods.         U.	

R	m
---	---

Caprock Maljamar Unit #128 30-025-31981 page 2 of 2

3-4/24-10 Tested well

3-25-10 Well not pumping

3-31-10 MI RU PU. Longstroked pump – no progress. Pld & LD pmp.

4-1-10 RIH w/pmp & rods. ND WH. NU BOP. Pld tbg. Tested tbg. Found split on jt #200. RD testers.

4-2-10 RIH w/134 jts 2-7/8" 6.5# J-55 EUE tbg and set @ 4188'.

4-5-10 Ran pmp & rods. Hung well on. Press to 500 psi – OK. RD PU.

4-6-10 RU pmp trk. P/165 gals scale inhibitor w/80 bbls FW down annulus. Overflushed w/150 bbls FW. SI 48 HRS.

4-8-10 Returned well to production.