Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	· W. S. Arab	WELL API NO. 30-025-30290
1301 W. Grand Ave., Artesia, NM 88210 District III AUG 0 6 20	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE 🛛
District IV 1220 S. St. Francis Dr., Santa Fe, NMBBSO 87505	Santa Fe, Nivi 87303	6. State Oil & Gas Lease No.
	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION PROPOSALS.)	TO DRILL OR TO DEEPEN OR PLUG BACK TO A ON FOR PERMIT" (FORM C-101) FOR SUCH	West Dollarhide Queen Sand Unit
	Well ☑ Other Injector ✔	8. Well Number 128
2. Name of Operator		9. OGRID Number
Chaparral Er 3. Address of Operator	nergy, L.L.C.	004115 /
701 Cedar Lake Blvd., Oklahoi	ma City. OK 73114	Dollarhide Queen
4. Well Location		Bollattide Queen
Unit Letter N : 66	60 feet from the South line and 2	feet from the West line
Section 19	Township 24S Range 38E	NMPM Lea County ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3158' GR		
Pit or Below-grade Tank Application or Clos		
	Distance from nearest fresh water well Dist	
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appr	ropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTE	NTION TO: SUB	SEQUENT REPORT OF:
	.UG AND ABANDON REMEDIAL WORI	
	HANGE PLANS COMMENCE DRI	_
PULL OR ALTER CASING MI	JLTIPLE COMPL $\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \$	「JOB 🗌
OTHER:	OTHER: MIT to	Return to Injection
OTHER: 13. Describe proposed or completed	operations. (Clearly state all pertinent details, and	Return to Injection XX I give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed of starting any proposed work).	OTHER: MIT to operations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Att	give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed	operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion.	operations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Att	give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874	operations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Att	I give pertinent dates, including estimated date cach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R	operations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Att (OA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" W	I give pertinent dates, including estimated date cach wellbore diagram of proposed completion well for night. SDON. /S. Tag CIBP @ 3636'.
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi	operations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Att '(OA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" Wivel & pump. DRill out CIBP & cleaned out to 3	d give pertinent dates, including estimated date cach wellbore diagram of proposed completion well for night. SDON. /S. Tag CIBP @ 3636'. 705'. Circ hole clean & SDON.
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weeekend.	operations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack (OA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" Wivel & pump. DRill out CIBP & cleaned out to 380 glew down pressure to truck. Drill ahead to 380 great statements.	well for night. SDON. /S. Tag CIBP @ 3636'. 705'. Circ hole clean & SDON. 05'. Plugged up bit. POOH w/tbg.
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weeekend. 5-17-2010 - SIWP = 200 psi.	operations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack (OA) init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" Wivel & pump. DRill out CIBP & cleaned out to 3 Blew down pressure to truck. Drill ahead to 380 Blew well down. Finish out of hole w/plugged	well for night. SDON. /S. Tag CIBP @ 3636'. 705'. Circ hole clean & SDON. /S. Plugged up bit. POOH w/tbg.
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weeekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805	operations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack (OA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" Wivel & pump. DRill out CIBP & cleaned out to 3 Blew down pressure to truck. Drill ahead to 380. Blew well down. Finish out of hole w/plugged '. Continue cleaning out wellbore to 3950'. Circ	well for night. SDON. /S. Tag CIBP @ 3636'. 705'. Circ hole clean & SDON. /S. Plugged up bit. POOH w/tbg.
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weeekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi.	coperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack (OA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" Wivel & pump. DRill out CIBP & cleaned out to 3 Blew down pressure to truck. Drill ahead to 380 Blew well down. Finish out of hole w/plugged '. Continue cleaning out wellbore to 3950'. Circ DN. Bled down pressure. POOH w/ bit & WS. Tally	well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /5'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 43/4" c hole clean while making short trip.
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weeekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le	coperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of COA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" We will be wi	well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /5'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4¾" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO.
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le	doperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of COA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 43/4" tooth bit, 8 DC's, & 108 jts 2-3/8" Wivel & pump. DRill out CIBP & cleaned out to 3 Blew down pressure to truck. Drill ahead to 380 Blew well down. Finish out of hole w/plugged '. Continue cleaning out wellbore to 3950'. Circ DN. Bled down pressure. POOH w/ bit & WS. Tally eft packer hanging in well and WOO to decide by & AD-1 packer. PU & RIH w/ AD-1 plastic complete the second process.	well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /5'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4¾" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. coated packer & 116 its 2-3/8" Internally
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weeekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le 6-10-2010 - POOH w/ IPC the Ceramic Coated tubing. NDE	doperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of COA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" Wivel & pump. DRill out CIBP & cleaned out to 38 lew down pressure to truck. Drill ahead to 380 lew down pressure to truck. Drill ahead to 380 lew down pressure. POOH w/ bit & WS. Tally eft packer hanging in well and WOO to decide by & AD-1 packer. PU & RIH w/ AD-1 plastic of BOP. NU WH. Circ 80 Bbl 2% KCI water as pa	well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /5'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4¾" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. cated packer & 116 jts 2-3/8" Internally cker fluid. Ran pre-MIT OK. RDMO.
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weeekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le 6-10-2010 - POOH w/ IPC the Ceramic Coated tubing. NDE	coperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of COA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" Well with a pump. DRill out CIBP & cleaned out to 3 Blew down pressure to truck. Drill ahead to 380 blew down pressure to truck. Drill ahead to 380 blew down pressure. POOH w/ bit & WS. Tally eft packer hanging in well and WOO to decide bog & AD-1 packer. PU & RIH w/ AD-1 plastic components of the packer as pawer. Pooh w/ bit & WS. Tally eft packer backer. PU & RIH w/ AD-1 plastic components of the packer as pawer. Pooh w/ bit & WS. Tally eft packer backer. PU & RIH w/ AD-1 plastic components of the packer as pawer. Pooh w/ bit & WS. Tally eft packer backer. PU & RIH w/ AD-1 plastic components of the packer as pawer. Pooh w/ bit & WS. Tally eft packer backer. PU & RIH w/ AD-1 plastic components of the packer as pawer. Pooh w/ bit & WS. Tally eft packer backer. PU & RIH w/ AD-1 plastic components of the packer as pawer. Pooh w/ bit & WS. Tally eft packer backer. PU & RIH w/ AD-1 plastic components of the packer as pawer. Pooh w/ bit & WS. Tally eft packer backer. PU & RIH w/ AD-1 plastic components of the packer as pawer. Pooh w/ bit & WS. Tally eft packer. Pub. WH. Circ 80 Bbl 2% KCI water as pawer.	well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /5'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4¾" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. cated packer & 116 jts 2-3/8" Internally cker fluid. Ran pre-MIT OK. RDMO.
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weeekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le 6-10-2010 - POOH w/ IPC tb Ceramic Coated tubing. NDE 7-28-2010 - Ran witnessed N	doperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of COA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" Wivel & pump. DRill out CIBP & cleaned out to 38 lew down pressure to truck. Drill ahead to 380 lew down pressure to truck. Drill ahead to 380 lew down pressure. POOH w/ bit & WS. Tally eft packer hanging in well and WOO to decide by & AD-1 packer. PU & RIH w/ AD-1 plastic of SOP. NU WH. Circ 80 Bbl 2% KCI water as pa MIT to return to Injection. Packer set @ 3649 hart enclosed.	well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /5'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4¾" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. chated packer & 116 jts 2-3/8" Internally cker fluid. Ran pre-MIT OK. RDMO. w/ 12 pts tension. MIT witnessed by
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le 6-10-2010 - POOH w/ IPC the Ceramic Coated tubing. NDE 7-28-2010 - Ran witnessed NMOCD's Mark Whitaker. Cl	doperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of COA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" Well with a pump. DRill out CIBP & cleaned out to 3 Blew down pressure to truck. Drill ahead to 380 blew down pressure to truck. Drill ahead to 380 blew well down. Finish out of hole w/plugged '. Continue cleaning out wellbore to 3950'. Circ ON. Bled down pressure. POOH w/ bit & WS. Tally left packer hanging in well and WOO to decide by & AD-1 packer. PU & RIH w/ AD-1 plastic complete to the best of my knowledge hart enclosed.	well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /5'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4³/4" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. cated packer & 116 jts 2-3/8" Internally cker fluid. Ran pre-MIT OK. RDMO. w/ 12 pts tension. MIT witnessed by
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le 6-10-2010 - POOH w/ IPC the Ceramic Coated tubing. NDE 7-28-2010 - Ran witnessed NMOCD's Mark Whitaker. Cl	doperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of COA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" Wivel & pump. DRill out CIBP & cleaned out to 38 lew down pressure to truck. Drill ahead to 380 lew down pressure to truck. Drill ahead to 380 lew down pressure. POOH w/ bit & WS. Tally eft packer hanging in well and WOO to decide by & AD-1 packer. PU & RIH w/ AD-1 plastic of SOP. NU WH. Circ 80 Bbl 2% KCI water as pa MIT to return to Injection. Packer set @ 3649 hart enclosed.	well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /5'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4³/4" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. cated packer & 116 jts 2-3/8" Internally cker fluid. Ran pre-MIT OK. RDMO. w/ 12 pts tension. MIT witnessed by
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le 6-10-2010 - POOH w/ IPC the Ceramic Coated tubing. NDE 7-28-2010 - Ran witnessed NMOCD's Mark Whitaker. Cl	doperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of COA) Init. SIWP = 0 psi. ND WH & NU BOP. Secure IH w/ 4¾" tooth bit, 8 DC's, & 108 jts 2-3/8" Well with a pump. DRill out CIBP & cleaned out to 3 Blew down pressure to truck. Drill ahead to 380 blew down pressure to truck. Drill ahead to 380 blew well down. Finish out of hole w/plugged '. Continue cleaning out wellbore to 3950'. Circ ON. Bled down pressure. POOH w/ bit & WS. Tally left packer hanging in well and WOO to decide by & AD-1 packer. PU & RIH w/ AD-1 plastic complete to the best of my knowledge hart enclosed.	I give pertinent dates, including estimated date each wellbore diagram of proposed completion well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /S. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4³/4" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. pated packer & 116 jts 2-3/8" Internally cker fluid. Ran pre-MIT OK. RDMO. // 12 pts tension. MIT witnessed by and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDG 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le 6-10-2010 - POOH w/ IPC the Ceramic Coated tubing. NDE 7-28-2010 - Ran witnessed NMOCD's Mark Whitaker. Cl	doperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of SEE RULE 1103. For Multiple Completions of SEE RULE 1103. For Multiple Completions: Attack of SEE RULE 1103. For Mult	well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /5'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 43/4" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. Dated packer & 116 jts 2-3/8" Internally cker fluid. Ran pre-MIT OK. RDMO. // 12 pts tension. MIT witnessed by and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan ory Affairs DATE 08-02-2010
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weeekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le 6-10-2010 - POOH w/ IPC the Ceramic Coated tubing. NDE 7-28-2010 - Ran witnessed NMOCD's Mark Whitaker. Cl	doperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of SEE RULE 1103. For Multiple Completions of SEE RULE 1103. For Multiple Completions: Attack of SEE RULE 1103. For Mult	digive pertinent dates, including estimated date each wellbore diagram of proposed completion well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /5'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4³/₄" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. pated packer & 116 jts 2-3/8" Internally cker fluid. Ran pre-MIT OK. RDMO. // 12 pts tension. MIT witnessed by e and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan □.
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weeekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le 6-10-2010 - POOH w/ IPC tb Ceramic Coated tubing. NDE 7-28-2010 - Ran witnessed N NMOCD's Mark Whitaker. Cl I hereby certify that the information above grade tank has been/will be constructed or closed. SIGNATURE Type or print name David P. Spencer For State Use Only	doperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of SEE RULE 1103. For Multiple Completions of SEE RULE 1103. For Multiple Completions: Attack of SEE RULE 1103. For Mult	well for night. SDON. /S. Tag CIBP @ 3636'. /TO5'. Circ hole clean & SDON. /S'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4³/4" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. bated packer & 116 jts 2-3/8" Internally cker fluid. Ran pre-MIT OK. RDMO. // 12 pts tension. MIT witnessed by and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan cory Affairs DATE 08-02-2010 Ochaparralenergy.cdralephone No. 405.426.4397
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDG 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le 6-10-2010 - POOH w/ IPC the Ceramic Coated tubing. NDE 7-28-2010 - Ran witnessed M NMOCD's Mark Whitaker. Cl	doperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of SEE RULE 1103. For Multiple Completions of SEE RULE 1103. For Multiple Completions: Attack of SEE RULE 1103. For Mult	well for night. SDON. /S. Tag CIBP @ 3636'. /705'. Circ hole clean & SDON. /5'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4³/4" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. cated packer & 116 jts 2-3/8" Internally cker fluid. Ran pre-MIT OK. RDMO. // 12 pts tension. MIT witnessed by and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan ory Affairs DATE 08-02-2010 Ochaparralenergy.cdralephone No. 405.426.4397
OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. TD: 3950' - Perfs 3702-3874 5-12-2010 - MIRU Service U 5-13-2010 - SIWP = 0 psi. R RU self contained power swi 5-14-2010 - SIWP 100 psi. B SDfor weather & weeekend. 5-17-2010 - SIWP = 200 psi. tooth bit, 121 jts WS to 3805 Lay down power swivel. SDC 5-18-2010 - SIWP = 100 psi. AD-1 packer. start in hole. Le 6-10-2010 - POOH w/ IPC tb Ceramic Coated tubing. NDE 7-28-2010 - Ran witnessed N NMOCD's Mark Whitaker. Cl I hereby certify that the information above grade tank has been/will be constructed or closed. SIGNATURE Type or print name David P. Spencer For State Use Only	doperations. (Clearly state all pertinent details, and SEE RULE 1103. For Multiple Completions: Attack of SEE RULE 1103. For Multiple Completions of SEE RULE 1103. For Multiple Completions: Attack of SEE RULE 1103. For Mult	well for night. SDON. /S. Tag CIBP @ 3636'. /TO5'. Circ hole clean & SDON. /S'. Plugged up bit. POOH w/tbg. bit. Cleaned out & RIH w/ 4³/4" chole clean while making short trip. / new 2-3/8" IPC coated tubing & about tubular string. SD- WOO. bated packer & 116 jts 2-3/8" Internally cker fluid. Ran pre-MIT OK. RDMO. // 12 pts tension. MIT witnessed by and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan cory Affairs DATE 08-02-2010 Ochaparralenergy.cdralephone No. 405.426.4397

