Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103	
Office District L	Energy, Minerals and Natural Resour	rces June 19, 2008	
District I 1625 N. French Dr., Hobbs, NM 88240	A'R 14 W.	WELL API NO.	
District II	ONSERVATION DIVISION DIVISION DE L'ARCIE DE	ON 30-025-26784	
1301 W. Grand Ave., Artesia, NM Strip	1220 South St. Francis Dr.	5. Indicate Type of Lease	
	2010 Santa Fe, NM 87505	STATE FEE	
1000 Rio Brazos Rd , Aztec, NM 87410 District IV 1220 S. St Francis Dr., Santa Fe, NM 87505	Eugla Santa Pe, Nivi 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	SOCD		
SUNDRYNOTICES	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR USE "APPLICATI	S TO DRILL OR TO DEEPEN OR PLUG BACK TO ON FOR PERMIT" (FORM C-101) FOR SUCH		
PROPOSALS)  1. Type of Well: Oil Well  Gas	Well Other	8. Well Number 22	
2. Name of Operator		9. OGRID Number 4323	
CHEVRON U.S.A. INC.		10. Pool name or Wildcat	
3. Address of Operator	\$ 70705	BLINEBRY OIL AND GAS	
15 SMITH ROAD, MIDLAND, TEXA		DENVERY OF THE GIR	
4. Well Location	All NODELL line and 000 feet from the	EAST line	
	the NORTH line and 990 feet from the		
Section 16 Township		MPM County LEA	
	1. Elevation (Show whether DR, RKB, RT,	GR, etc.)	
		ングは 2万元の高温を開発した。 子での高速ではまる かっとうご 第二十年上	
12. Check App	ropriate Box to Indicate Nature of	Notice, Report or Other Data	
	_		
NOTICE OF INTE		SUBSEQUENT REPORT OF:	
-		AL WORK ALTERING CASING	
		NCE DRILLING OPNS. □ P AND A □	
<u> </u>	ULTIPLE COMPL	/CEMENT JOB	
DOWNHOLE COMMINGLE			
OTHER: INTENT TO ADD BLINES	BRY PERFS & FRAC OTHER:		
13. Describe proposed or complete	d operations. (Clearly state all pertinent d	etails, and give pertinent dates, including estimated date	
of starting any proposed work).	SEE RULE 1103. For Multiple Comple	tions: Attach wellbore diagram of proposed completion	
or recompletion.			
CHEVRON I S A INC INTENDS	S TO ADD BLINEBRY PAY AND FRAC	٦	
CHEVRON U.S.A. INC. INTEND.	5 TO ADD BEINEBRI THE MILD FRANCE		
PLEASE FIND ATTACHED, THE INTENDED PROCEDURE, WELLBORE DIAGRAMS, AND C-144 INFORMATION.			
Spud Date:	Rig Release Date:		
Spad Date.			
I hereby certify that the information abo	ve is true and complete to the best of my l	knowledge and belief.	
A	\ ` ,		
SIGNATURE MANAGE	MKER TON TITLE REGULATOR	Y SPECIALIST DATE 09-01-2010	
SIGNATURE VIJOUR	THEE REGULATION	I SI DOMIDIOT BITTE US OT 2010	
Type or print name DENISE PINKE	RTON E-mail address: leakejd@chevi	ron.com PHONE: 432-687-7375	
For State Use Only		5-5 A 7 2010	
A DDD OVED BV:	TITLE PETROLEUR	DATE SEP 0 7 2010	
APPROVED BY: Conditions of Approval (if any):	THE	DAIL	

R. E. Cole (NCT-A) # 22 Blinebry Oil & Gas Field T22S, R37E, Section 16 Job: Add Perfs In Blinebry Formation And Frac

## **Procedure:**

- 1. This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office well files and computer databases as of 8/31/2010. Verify what is in the hole with the well file in the Eunice Field office. Discuss w/ WEO Engineer, Workover Rep, OS, ALS, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.
- 2. Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. Buried fiberglass lines will be tested with 300 psi. All polypipe (SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/1000 psi. If a leak is found, contact Donnie Ives for repair/replacement. If test is good, bleed off pressure and open valve at header. Document this process in the morning report. Note:

  Prior to performing this step of the procedure, ensure that all valves, pipe, and fittings that will be exposed to test pressure are rated higher than the planned test pressure.
- 3. MI & RU workover unit. Bleed pressure from well, if any. Pump down csg with 8.6 PPG cut brine water, if necessary to kill well. POH with rods and pump. Remove WH. Install BOP's and test as required. POH LD 2 3/8" tbg string. LD TAC.
- 4. PU and GIH with 4 ¾" MT bit and 2 7/8" work string to 5800'. MI&RU air unit. Establish circulation and clean out fill in casing to PBTD at 6203' using foam. Circulate well clean from 6203'. POH with work string and bit. LD bit.
- 5. MI & RU Baker Atlas electric line unit. Install lubricator and test to 1000 psi. GIH with 3 3/8" RHSC Gunslinger casing guns (0.42" EH & 47" penetration) and perforate from 5414-22', 5428-31', 5433-37', 5443-48', 5451-60', 5484-89', 5492-5502', 5509-15', 5520-24', 5530-39', 5544-48', 5572-81', 5590-93', 5596-5606', 5627-37', 5656-60', 5663-73', 5679-88', 5704-10', 5714-20', 5736-46', 5750-54', 5760-64', 5784-90', 5861-71', 5874-82', 5885-92', 5896-5905', and 5910-16' with 4 JSPF at 120 degree phasing, using 25 gram premium charges. POH. RD & release electric line unit. Note: Use casing collars from Zone Perforators Inc. Gamma Ray Log dated 7/8/1980 for depth correction.
- 6. PU and GIH w/ 5 ½" PPI pkr (with 12' element spacing) and SCV on 2 7/8" work string to approximately 5920'. Test tbg to 5500 psi while GIH.
- 7. MI & RU DS Services. Acidize perfs 5414-5916' with 5,600 gals anti-sludge 15% HCl acid \* at a maximum rate **as shown below** and a maximum surface pressure of **4500 psi**. Spot acid across perfs at beginning of each stage and let soak to lower breakdown pressure and prevent communication. Pump job as follows:

Interval	Amt. Acid	Max Rate	<b>PPI Setting</b>
5910-16'	200 gals	½ BPM	5436-48'
5896-5905'	200 gals	½ BPM	5400-12'
5885-92'	200 gals	½ BPM	5370-82'
5874-82'	200 gals	¹⁄₂ BPM	5340-52'
5861-71'	200 gals	½ BPM	5322-34'
5784-90'	200 gals	½ BPM	5286-98'
5760-64'	200 gals	½ BPM	5270-82'
5750-54'	200 gals	1/2 BPM	5235-47'
5736-46'	200 gals	½ BPM	5209-21'
5714-20'	200 gals	½ BPM	5182-94'
5704-10'	200 gals	½ BPM	5157-69'
5679-88'	200 gals	½ BPM	5137-49'
5663-73'	200 gals	½ BPM	5436-48'
5656-60'	200 gals	½ BPM	5400-12'
5627-37'	200 gals	½ BPM	5370-82'
5596-5606'	200 gals	½ BPM	5340-52'
5584-93'	200 gals	½ BPM	5322-34'
5572-81'	200 gals	½ BPM	5286-98'
5544-52'	200 gals	½ BPM	5270-82'
5530-39'	200 gals	½ BPM	5235-47'
5520-24'	200 gals	½ BPM	5209-21'
5509-15'	200 gals	½ BPM	5182-94'
5492-5502'	200 gals	½ BPM	5157-69'
5484-89'	200 gals	½ BPM	5137-49'
5451-60'	200 gals	½ BPM	5209-21'
5443-48'	200 gals	½ BPM	5182-94'
5428-37'	200 gals	½ BPM	5157-69'
5414-22'	200 gals	½ BPM	5137-49'

Displace acid with 8.6 PPG cut brine water -- do not overdisplace. Use a SCV to control displacement fluid. Record ISIP, 5 & 10 minute SIP's. RD and release DS services. Note: Pickle tubing in 1 run of 500 gals acid, prior to acidizing perfs. Pickle acid is to contain only 1/2 gal A264 and 1 gal W53. Also, if communication occurs during treatment of any interval, monitor casing pressure and attempt to complete stage w/o exceeding 500 psi csg pressure. If cannot, then move PPI to next setting depth and combine treatment volumes of the intervals.

*	Acid	system	is	to	contain:
---	------	--------	----	----	----------

1 GPT A264	Corrosion Inhibitor
8 GPT L63	Iron Control Agent
2 PPT A179	Iron Control Aid
20 GPT U66	Mutual Solvent
2 GPT W53	Non-Emulsifier

- 8. GIH and fish SCV. POH. Release PPI pkr. PUH with PPI pkr to 5400°. Set PPI pkr at 5400°. GIH and swab back all intervals together. Recover 100% of treatment and load volumes before shutting well in for night, if possible. Report recovered fluid volumes, pressures, and/or swabbing fluid levels. Note: Selectively swab perfs as directed by Engineering if excessive water is produced.
- 9. Open well. Release PPI pkr. POH with 2 7/8" work string and PPI packer. LD PPI tool.
- 10. PU and GIH w/ 5 ½" 10K treating pkr & On-Off tool w/ 2.25" "F" profile and 161 jts. of 3 ½" EUE 8R L-80 work string, testing to 8500 psi. Set pkr at approximately 5000'. Install frac head. Pressure annulus to 500 psi to test csg and pkr. Leave pressure on csg during frac job to observe for communication.
- 11. MI & RU DS Services. Frac well down 3 ½" tubing at **40 BPM** with 78,000 gals of 50 Quality CO2 Foamed WF150 and 167,000 lbs. 16/30 mesh Jordan Sand. Observe a maximum surface treating pressure of **8000 psi**. Pump job as follows:

Pump 14,000 gals WF150 50Q Foam pad
Pump 14,000 gals WF150 50Q Foam pad containing 0.5 PPG 16/30 mesh Jordan Sand
Pump 8,000 gals WF150 50Q Foam containing 1 PPG 16/30 mesh Jordan Sand
Pump 9,000 gals WF150 50Q Foam containing 2 PPG 16/30 mesh Jordan Sand
Pump 10,000 gals WF150 50Q Foam containing 3 PPG 16/30 mesh Jordan Sand
Pump 11,000 gals WF150 50Q Foam containing 4 PPG 16/30 mesh Jordan Sand and PROPNET
Pump 12,000 gals WF150 50Q Foam containing 5 PPG 16/30 mesh Jordan Sand and PROPNET.

Flush to 5330' with 2,157 gals WF150. <u>Do not overflush</u>. Shut well in. Record ISIP, 5, 10, and 15 minute SI tbg pressures. SWI. RD & Release DS Services. <u>Leave well SI overnight</u>. <u>Note:</u> DS should bring enough PropNet to location to add to 3 PPG sand stage if needed for pressure reduction.

- 12. Open well. Bleed off pressure. Pump down tbg with 8.6 PPG cut brine water if necessary to kill well. Release pkr and POH with 3 ½" work string. Lay down 3 ½" work string and pkr.
- 13. PU and GIH with 4 ¾" MT bit on 2 7/8" work string to 6230'. If fill is found, MI&RU air unit. Clean out to 6230' using foam. Circulate well clean from 6230'. POH LD 2 7/8" work string and bit.
- 14. PU and GIH w/ BP mud anchor jt of 2 7/8" tbg, 2 7/8" x 4' perforated sub, SN, 1 jt 2 7/8" EUE 8R J-55 IPC tbg, 22 jts 2 7/8" EUE 8R J-55 tbg, TAC, and 175 jts 2 7/8" EUE 8R J-55 tbg, testing to 5000 psi. Set TAC at 5355', with EOT at 6100' and SN at 6065'.
- 15. Remove BOP's and install WH. GIH with rods, weight bars, and pump per ALS recommended design. RD & release pulling unit.

16. Turn well over to production. Report producing rates, choke sizes, flowing pressures and/or fluid levels.

AMH 8/31/2010

COTD: 5846' PBTD: 6203' TD: 7940'

Updated: 8/25/2010 ·

By: A. M Howell

Cmt plug fr/ 7590-7940'

Updated: 8/25/2010

COTD: 6203' PBTD: 6203'

TD: 7940'

By: A M Howell

Cmt plug fr/ 7590-7940'