		2
Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
A	Energy, Minerals and Natural Resources	WELL API NO.
1625 N French Dr., Hobbs, NM 882	NED	30-025-27529
	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd , Aztec, NM 87410 2 2	ZUJU 220 South St. Francis Dr.	STATE FEE V
1000 Rio Brazos Rd , Aztec, NM 87410 LP 2 Z <u>District IV</u> 1220 S St. Francis Dr., Santa Fe, NM 10BBS 87505	OCD Salita Fe, NM 87303	6. State Oil & Gas Lease No.
	AND REPORTS ON WELLS O DRILL OR TO DEEPEN OR PLUG BACK TO A N FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name H.T. MATTERN NCT-C
1. Type of Well: Oil Well Gas Well Other		8. Well Number 15
2. Name of Operator		9. OGRID Number 4323
CHEVRON U.S.A. INC. 3. Address of Operator		10. Pool name or Wildcat
15 SMITH ROAD, MIDLAND, TEXAS	79705	PENROSE SKELLY GRAYBURG
4. Well Location		
Unit Letter B: 660 feet from the NORTH line and 1980 feet from the EAST line		
Section 18 Township	21-S Range 37-E NMPN	
	Elevation (Show whether DR, RKB, RT, GR, e	etc.)
Control and the control of the contr		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ RF TEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON CHA	ANGE PLANS 📙 🌈 🗘 'CE (DRILLING OPNS. □ P AND A □
PULL OR ALTER CASING MUI	LTIPLE COMPL U	T JOB □
DOWNHOLE COMMINGLE	e 24 ho	Of App
OTHER: INTENT TO TEMPORARIL	Y ABANDON OTHER:	Urs prioral: A
13. Describe proposed or completed operations. (Clearly state all pertinent details, and gorto completed operations). SEE RULE 1103. For Multiple Completions: Attach we corroposed completion		
or recompletion.		
Test Test		
PERFORM REMEDIAL WORK PLUG AND ABANDON REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REPORT OF: PERFORM REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS PAND A PAND A PULL OR ALTER CASING MULTIPLE COMPL OFFICE		
II 6.0 Packer shall be set within or less then 100 feet		
Spud Date:	Rig Release Date:	permost injection perfs or open hole.
		Set los OR Less-FROM TOP
	Perter	Set loo'ORless-From Top CAPW/35'Cont
I hereby certify that the information above	is true and complete to the best of my knowle	edge and belief.
SIGNATURE VINUSES WITH RESULATORY SPECIALIST DATE 09-21-2010		
Type or print name DENISE PINKERTON E-mail address: <u>leakejd@chevron.com</u> PHONE: 432-687-7375		
For State Use Only		
APPROVED BY THE TITLE STAFF MOR DATE 9-23-10		
Conditions of Approval (if any):		
t .		

H.T. Mattern NCT-C #15 Penrose-Skelly Field T21S, R37E, Sec.18, 1980' FEL 660' FNL Job: Temporarily plug and abandon (T&A)

Procedure:

- 1. This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland office well files and computer databases as of September 16, 2010. Verify what is in the hole with the well file in the Eunice field office. Discuss with WEO Engineer, Workover Rep, OS, ALCR, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.
- 2. Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. Buried fiberglass lines will be tested with 300 psi. All polypipe (SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/1000 psi. If a leak is found, contact Donnie Ives for repair/replacement. If test is good, bleed off pressure and open valve at header. Document this process in the morning report. Note: Prior to performing this step of the procedure, ensure that all valves, pipe, and fittings that will be exposed to test pressure are rated higher than the planned test pressure.
- 3. MI & RU pulling unit. Verify sub pump has been shut off and that all electrical connections have been disconnected from the wellhead. Bleed pressure from well, if any. Pump down casing with 8.6 PPG cut brine water, if necessary to kill well. ND wellhead. NU BOP's and annular BOP's and test as necessary. Contact Carlos Loaiza with Centrilift to get a cable spooler on-site for pulling the pump and tbg.
- 4. RU ESP cable spooler. POOH with 2 7/8" production tubing and sub pump. LD sub pump. Coordinate with Shannon Richardson (ALCR) for ESP teardown. Stand back 2 7/8" J-55 6.5# 8RD EUE production tbg.
- 6.5# 8RD EUE production tbg.
 5. PU 5 1/2" CIBP on 2 7/8" production tbg and 2 extra joints yellowband tbg. RIH and set CIBP at 3647. Note: Use casing collars from Baker Atlas compensated neutron gamma ray log dated March 1, 2005 for depth correlation. Pick up to 3590' and reverse circulate well clean from 3590' using corrosion-inhibited 2% KCl water. Pressure test with 550 psi for 30 minutes. In pressure holds, POH with 2 7/8" tbg. LD tbg and send to 1788 yard.
- 6. ND BOP's. NU wellhead. RD & MO pulling unit. Perform MIT with an NMOCD representative on-site. Give NMOCD 48 hours notice before performing MIT. Pressure test

as per MIT requirements. Turn in any charts and documentation to Denise Pinkerton (JLBM@chevron.com)

By: Felix Trevino

TOC @ 2425' by TS


FDID: 54501

6686'-6747' Below CIBP

Status

Drinkard Perfs:

, 🥹



Upuateu: 3-Jun-05

By: Felix Trevino