Submit 1 Copy To Appropriate District Office District I	ffice Energy Minerals and Netural Recourses		Form C-103 October 13, 2009
			WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	COLL CONSERVATION	DIVISION	30-041-20942
		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410 UEC 23 2016 Santa Fe NIM 87505		STATE X FEE	
1220 S. St. Francis Dr., Santa Fe, NM	Draw .	, 505	o. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM HOBBSOCT			
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		San Juan Mesa 16 State
PROPOSALS.)	PROPOSALS.)		
1. Type of Well: Oil Well 🗵 🔾	Gas Well 🔲 Other		8. Well Number 1
2. Name of Operator			9. OGRID Number
Torch Energy Services, Inc.		241401	
3. Address of Operator		10. Pool name or Wildcat	
1331 Lamar Ste. 1450 Houston, TX 77010			Wildcat
4. Well Location	550	-	-
Unit Letter A: 660 feet from the North line and 660 feet from the East line			
Section 16		ange 30E	NMPM Roosevelt County
	11. Elevation (Show whether DR,	, RKB, RT, GR, etc.)	
	4613.3' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK			
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	
DOWNHOLE COMMINGLE			
OTHER:		OTHER:	
	k). SEE RULE 19.15.7.14 NMAC		give pertinent dates, including estimated date upletions: Attach wellbore diagram of
• • •	•	ll begia/upon a	pproval of plugging procedure.
1. Set CIBP @ approx. 7820'( upper perf @ 7850'), dump 20- "H" cement on plug.			
2. PU tbg, TIH to top of plug, circ hole w/ 9.5# mud laden fld.			
3. Cut off csg @ 5700' ± (cmt top @ 5812') POOH w/ csg.			
4. TIH w/ tbg to 50' below csg cut off, mix 30 sxs "C" cmt, spot 100' plug.			
5. Pull out of plug, rev circ tbg displacement, allow cmt to set 2 hrs before tagging top of plug.			
6. Pull up to 2250', mix 40 sxs "C" cmt, spot 100' plug 50' below & 50' above base of inter string (2200').			
7. Pull out of plug, rev circ tbg displacement, allow cmt to set 2 hrs before tagging top of plug.			
8. Pull to 510', mix 30 sxs "C" cmt, spot 100' plug.			
9. Pull out of plug, rev circ		cmt to set 2 hr	s before tagging top of plug.
10.Pull to 500, Set 5000 plug @ surf.			
11.Install dry hole marker &	rig down. OCD will be no	tified for insp	ection after plugging is done.
G. ID.	7. 7. 7.	. Г	•
Spud Date:	Rig Release Da		
The Oil Conservation Division <b>Must be notified</b>			
			Prior to the beginning of plugging operations
I hereby certify that the information at	pove is true and complete to the be	est of my knowledge	and belief.
, ,			
SIGNATURE Lingola	ASINDO TITLE Regu	laroty Cons	ultant <u>DATE 12/<b>20</b>/2010</u>
Type or print name Angela Lig For State Use Only	(1)		
	, , , , ,	angela@rkf	ord.com_PHONE: 432-682-0440
5/7	htner E-mail address		
APPROVED BY	htner E-mail address	angela@rkf	
5/7	htner E-mail address		

## San Juan Mesa 16 State #1 Sec 16 - T4S - R30E Roosevelt County, NM API# 30-041-20942

