District I
 - (505) 393-6161

 1625 N. French Dr, Hobbs, NM 88240
 District II

 District II
 - (505) 748-1283

 1301 W. Grand Avenue, Artesia, NM 88210
 District III

 District III
 - (505) 334-6178

 1000 Rio Brazos Road, Aztec, NM 87410
 District IV

 District IV
 - (505) 476-3440

 1220 So. St. Francis Dr., Santa Fe, NM 87505

New Mexico Energy Minerals and Natural Resources Department

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, New Mexico 87505 (505) 476-3440

Form C-140 Revised June 10, 2003

SUBMIT ORIGINAL PLUS 2 COPIES TO APPROPRIATE DISTRICT OFFICE

H-04-00004

## APPLICATION FOR WELL WORKOVER PROJECT

| Operator name & address  |                   |                        | OGRID Number                    |  |
|--|-------------------|------------------------|---------------------------------|--|
| Chevron U.S.A. Inc.  |                   | 4323                   |                                 |  |
| 15 Smith Road  |                   |                        |                                 |  |
| Midland, Texas 79705   |                   |                        |                                 |  |
| Contact Party  |                   | Phone                  |                                 |  |
| Laura Skinner  |                   |                        | 432-687-7355                    |  |
| Property Name Well Numb  |                   | API Number             |                                 |  |
| Vacuum Grayburg San Andres Unit  | 28                | 30-025-0               | 02253                           |  |
|  |                   | st/West Line           | County                          |  |
| I 1 18-S 34-E 2310 South   | 330               | East                   | Lea                             |  |
| II. Workover   |                   |                        |                                 |  |
| Date Workover Commenced: Previous Producing Pool(s) (Prior to Workover):               |                   |                        |                                 |  |
| 06-17-03 Vacuum Grayburg San Andres  |                   |                        |                                 |  |
| Date Workover Completed:   |                   |                        |                                 |  |
| 07-11-03   |                   |                        |                                 |  |
| III. Attach a description of the Workover Procedures performed to increase production. |                   |                        |                                 |  |
| IV. Attach a production decline curve or table showing at least twel                   | ve months of pro  | duction prio           | r to the workover and at least  |  |
| three months of production following the workover reflecting a                         | ositive productio | on increase.           |                                 |  |
| V. AFFIDAVIT:  |                   |                        |                                 |  |
| State of <u>New Mexico</u> )   |                   |                        |                                 |  |
| ) ss.  |                   |                        |                                 |  |
| County of <u>Lea</u> )   |                   |                        |                                 |  |
| R. S. Pool, being first duly sworn, upon c   | ath states:       |                        |                                 |  |
| 1. I am the Operator, or authorized representative of the                              | Operator, of the  | e above-refe           | erenced Well.                   |  |
| 2. I have made, or caused to be made, a diligent search                                | of the production | on records a           | asonably available for this     |  |
| Well.  |                   | 3194                   | 2322                            |  |
| 3. To the best of my knowledge, this application and the                               | data used to pr   | enarê îhe pr           | oduction curve and/or table for |  |
| this Well are complete and accurate.   |                   | 19                     |                                 |  |
| 1000   |                   | 12                     | FEA 2000 B                      |  |
| Signature XIII Title Technical T   | eam Leader        | 12<br>12<br>14<br>Date | 07-19-04                        |  |
|  | cam Leaver        |                        |                                 |  |
| SUBSCRIBED AND SWORN TO before me this day of, 2004                                    |                   |                        |                                 |  |
|  |                   |                        |                                 |  |
| TAILA A PINNER 6   |                   |                        |                                 |  |
| LAURA SKINNER NY COMMISSION EXPIRES Notary Pub   | ic                |                        | 95782                           |  |
| My Commission expines June 1, 2004   |                   |                        |                                 |  |
|  |                   |                        |                                 |  |
|  |                   |                        |                                 |  |
|  |                   |                        |                                 |  |
| FOR OIL CONSERVATION DIVISION USE ONLY:  |                   |                        |                                 |  |

VI. CERTIFICATION OF APPROVAL:

This Application is hereby approved and the above-referenced well is designated a Well Workover Project and the Division hereby verifies the data shows a positive production increase. By copy hereof, the Division notifies the Secretary of the Taxation and Revenue Department of this Approval and certifies that this Well Workover Project was completed on

VII. DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT:

| Submit 3 Copies To Appropriate District State of New Mexico   | Earry C 102  |  |  |
|---|--|--|--|
| Submit 3 Copies To Appropriate District         State of New Mexico           Office         Energy, Minerals and Natural Resources   | Form C-103<br>Revised March 25, 1999   |  |  |
| District I<br>1625 N. French Dr., Hobbs, NM 87240   | WELL API NO.   |  |  |
| DIL CONSERVATION DIVISION   | 30-025-02253   |  |  |
| Bill South First, Artesia, NM 87210<br>District III 2040 South Pacheco  | 5. Indicate Type of Lease  |  |  |
| 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505   | STATE 🛛 FEE 🗌  |  |  |
| Distained TV  | 6. State Oil & Gas Lease No.   |  |  |
|   | 857948   |  |  |
| SUNDRY NOTICES AND REPORTS ON WELLS<br>DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A<br>DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH<br>PROPOSALS.)<br>1. Type of Well:   | 7. Lease Name or Unit Agreement Name:<br>Vacuum Grayburg San Andres Unit   |  |  |
| Oil Well 🕱 Gas Well 🗌 Other   |  |  |  |
|   | 8. Well No.  |  |  |
| hevron U.S.A. Inc.  | 28   |  |  |
|   | 9. Pool name or Wildcat  |  |  |
|   | Vacuum Grayburg San Andres   |  |  |
| 4. Well Location  |  |  |  |
| Unit Letter I feet from the South line and  | 330 feet from the East line  |  |  |
|   |  |  |  |
| Section         1         Township         18s         Range         34E           10. Elevation (Show whether DR, RKB, RT, GR, etc., 3993' GL  | NMPM County Lea  |  |  |
| 11. Check Appropriate Box to Indicate Nature of Notice, H   | Report, or Other Data  |  |  |
|   | EQUENT REPORT OF:  |  |  |
| ERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK   |  |  |  |
|   |  |  |  |
| EMPORARILY ABANDON 🛄 CHANGE PLANS 🔄 COMMENCE DRILLIN  |  |  |  |
| JLL OR ALTER CASING DIMULTIPLE CASING TEST AND CEMENT JOB   |  |  |  |
| COMPLETION  |  |  |  |
|   | La Agidigo Popular Caging  |  |  |
| THER: DTHER: Clean Out,   |  |  |  |
| THER: DTHER: Clean Out,   | e pertinent dates, including estimated date  |  |  |
| THER: OTHER: Clean Out,<br>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv<br>of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v<br>or recompilation.<br>06-17-03 MIRU. Move in frac tanks.<br>06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4   | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.  |  |  |
| THER: OTHER: Clean Out,<br>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv<br>of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v<br>or recompilation.<br>06-17-03 MIRU. Move in frac tanks.<br>06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4<br>06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN  | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.  |  |  |
| <ul> <li>THER: OTHER: Clean Out,</li> <li>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.</li> <li>06-17-03 MIRU. Move in frac tanks.</li> <li>06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4</li> <li>06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN 06-20-03 Acidize w/4000 gals 15% H15.</li> </ul>  | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.  |  |  |
| THER:       OTHER: clean Out,         12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.         06-17-03       MIRU. Move in frac tanks.         06-18-03       TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4         06-19-03       Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN         06-20-03       Acidize w/4000 gals 15% H15.         06-21-03       RU swab; ending fluid level @ 2400' from surface. RD swab.  | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>& WS to 4033' & set pkr @ 4033'.  |  |  |
| THER:       OTHER: clean Out,         12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.         06-17-03       MIRU. Move in frac tanks.         06-18-03       TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4         06-19-03       Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN         06-20-03       Acidize w/4000 gals 15% H15.         06-21-03       RU swab; ending fluid level @ 2400' from surface. RD swab.         06-22-03       Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,  | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>& WS to 4033' & set pkr @ 4033'.  |  |  |
| THER:       OTHER: clean Out,         12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.         06-17-03 MIRU. Move in frac tanks.         06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4         06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN         06-20-03 Acidize w/4000 gals 15% H15.         06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.  | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>" & WS to 4033' & set pkr @ 4033'.<br>flush w/400 bbls.<br>TIH w/CIBP pkr & WS to 4002'.  |  |  |
| <ul> <li>THER: OTHER: Clean Out,</li> <li>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.</li> <li>06-17-03 MIRU. Move in frac tanks.</li> <li>06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4</li> <li>06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN</li> <li>06-20-03 Acidize w/4000 gals 15% H15.</li> <li>06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.</li> <li>06-22-03 Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,</li> <li>06-23-03 Rel pkr @ 4002' &amp; TOH w/127 jts 2-7/8" tbg &amp; lay down pkr.</li> </ul>  | <pre>e pertinent dates, including estimated date vellbore diagram of proposed completion " bit &amp; 100 jts 2-7/8" WS to 3144'.     &amp; WS to 4033' &amp; set plor @ 4033'.     flush w/400 bbls. TIH w/CIBP, pkr &amp; WS to 4002'.</pre>  |  |  |
| <ul> <li>THER: OTHER: Clean Out,</li> <li>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.</li> <li>06-17-03 MIRU. Move in frac tanks.</li> <li>06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4</li> <li>06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN</li> <li>06-20-03 Acidize w/4000 gals 15% H15.</li> <li>06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.</li> <li>06-22-03 Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,</li> <li>06-23-03 Rel pkr @ 4002' &amp; TOH w/127 jts 2-7/8" tbg &amp; lay down pkr. 'Set CIEP @ 4002'. Set pkr @ 3992'; test CIEP to 500 psi (goo Isolated csg leak from 2274' to 2525'.</li> <li>06-24-03 Rel pkr @ 2274' &amp; TOH w/WS &amp; lay down pkr. TIH open ended w/</li> </ul>  | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>" & WS to 4033' & set plor @ 4033'.<br>" flush w/400 bbls.<br>TIH w/CIBP pkr & WS to 4002'.<br>od).<br>Hobbs<br>/WS & sub; bottom of tog @ 2526'.   |  |  |
| <ul> <li>THER: OTHER: Clean Out,</li> <li>2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.</li> <li>06-17-03 MIRU. Move in frac tanks.</li> <li>06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4</li> <li>06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN</li> <li>06-20-03 Acidize w/4000 gals 15% H15.</li> <li>06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.</li> <li>06-22-03 Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,</li> <li>06-23-03 Rel pkr @ 4002' &amp; TOH w/127 jts 2-7/8" tbg &amp; lay down pkr. 'Set CIBP @ 4002'. Set pkr @ 3992'; test CIBP to 500 psi (got Isolated csg leak from 2274' to 2525'.</li> </ul>  | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>" & WS to 4033' & set plor @ 4033'.<br>"<br>flush w/400 bbls.<br>TIH w/CIBP pkr & WS to 4002'.<br>od).<br>Hobbs<br>/WS & sub; bottom of the @ 2526'.  |  |  |
| <ul> <li>THER: OTHER: Clean Out,</li> <li>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.</li> <li>06-17-03 MIRU. Move in frac tanks.</li> <li>06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4</li> <li>06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN</li> <li>06-20-03 Acidize w/4000 gals 15% H15.</li> <li>06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.</li> <li>06-22-03 Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,</li> <li>06-23-03 Rel pkr @ 4002' &amp; TOH w/127 jts 2-7/8" tbg &amp; lay down pkr.</li> <li>Set CIBP @ 4002'. Set pkr @ 3992'; test CIBP to 500 psi (gou Isolated csg leak from 2274' to 2525'.</li> <li>06-24-03 Rel pkr @ 2274' &amp; TOH w/WS &amp; lay down pkr. TIH open ended w, RU on tbg to spot cement in 5-1/2" csg, holes from 2525'-227.</li> </ul>  | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>" & WS to 4033' & set plor @ 4033'.<br>"<br>flush w/400 bbls.<br>TIH w/CIBP pkr & WS to 4002'.<br>od).<br>Hobbs<br>/WS & sub; bottom of the @ 2526'.  |  |  |
| <ul> <li>THER: OTHER: Clean Out,</li> <li>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.</li> <li>06-17-03 MIRU. Move in frac tanks.</li> <li>06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4</li> <li>06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN</li> <li>06-20-03 Acidize w/4000 gals 15% H15.</li> <li>06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.</li> <li>06-22-03 Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,</li> <li>06-23-03 Rel pkr @ 4002' &amp; TOH w/127 jts 2-7/8" tbg &amp; lay down pkr. 'Set CIEP @ 4002'. Set pkr @ 3992'; test CIEP to 500 psi (goo Isolated csg leak from 2274' to 2525'.</li> <li>06-24-03 Rel pkr @ 2274' &amp; TOH w/WS &amp; lay down pkr. TIH open ended w/</li> </ul>  | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>" & WS to 4033' & set plor @ 4033'.<br>" flush w/400 bbls.<br>TIH w/CIBP pkr & WS to 4002'.<br>od).<br>Hobbs<br>/WS & sub; bottom of tog @ 2526'.   |  |  |
| <ul> <li>THER: OTHER: Clean Out,</li> <li>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.</li> <li>06-17-03 MIRU. Move in frac tanks.</li> <li>06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4</li> <li>06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN</li> <li>06-20-03 Acidize w/4000 gals 15% H15.</li> <li>06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.</li> <li>06-22-03 Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,</li> <li>06-23-03 Rel pkr @ 4002' &amp; TOH w/127 jts 2-7/8" tbg &amp; lay down pkr. 'Set CIBP @ 4002'. Set pkr @ 3992'; test CIBP to 500 psi (go Isolated csg leak from 2274' to 2525'.</li> <li>06-24-03 Rel pkr @ 2274' &amp; TOH w/WS &amp; lay down pkr. TIH open ended w, RU on tbg to spot cement in 5-1/2" csg, holes from 2525'-227.</li> </ul>   | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>" & WS to 4033' & set plor @ 4033'.<br>" flush w/400 bbls.<br>TIH w/CIBP pkr & WS to 4002'.<br>od).<br>Hobbs<br>/WS & sub; bottom of tog @ 2526'.   |  |  |
| <ul> <li>THER: OTHER: Clean Out,</li> <li>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.</li> <li>06-17-03 MIRU. Move in frac tanks.</li> <li>06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4</li> <li>06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN</li> <li>06-20-03 Acidize w/4000 gals 15% H15.</li> <li>06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.</li> <li>06-22-03 Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,</li> <li>06-23-03 Rel pkr @ 4002' &amp; TOH w/127 jts 2-7/8" tbg &amp; lay down pkr. 'Set CIBP @ 4002'. Set pkr @ 3992'; test CIBP to 500 psi (good isolated csg leak from 2274' to 2525'.</li> <li>06-24-03 Rel pkr @ 2274' &amp; TOH w/WS &amp; lay down pkr. TIH open ended w, RU on tbg to spot cement in 5-1/2" csg, holes from 2525'-227.</li> </ul>   | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>" & WS to 4033' & set plor @ 4033'.<br>" flush w/400 bbls.<br>TIH w/CIBP pkr & WS to 4002'.<br>od).<br>Hobbs<br>/WS & sub; bottom of tog @ 2526'.   |  |  |
| <ul> <li>THER: OTHER: Clean Out,</li> <li>2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.</li> <li>06-17-03 MIRU. Move in frac tanks.</li> <li>06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4</li> <li>06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN</li> <li>06-20-03 Acidize w/4000 gals 15% H15.</li> <li>06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.</li> <li>06-22-03 Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,</li> <li>06-23-03 Rel pkr @ 4002' &amp; TOH w/127 jts 2-7/8" tbg &amp; lay down pkr. 'Set CIBP @ 4002'. Set pkr @ 3992'; test CIBP to 500 psi (good isolated csg leak from 2274' to 2525'.</li> <li>06-24-03 Rel pkr @ 2274' &amp; TOH w/WS &amp; lay down pkr. 'TH open ended w, RU on thg to spot cement in 5-1/2" csg, holes from 2525'-227.</li> </ul>  | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>& WS to 4033' & set plac @ 4033'.<br>flush w/400 bbls.<br>TIH w/CIBP pkr & WS to 4002'.<br>od).<br>Hobbs<br>/WS & sub; bottom of the @ 2526'.<br>4' w/125 sx Class C cmt w/2% Cacl.                     |  |  |
| THER:       OTHER: Clean Out,         12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.         06-17-03 MIRU. Move in frac tanks.         06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TTH w/4-3/4         06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN         06-20-03 Acidize w/4000 gals 15% H15.         06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.         06-22-03 Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,         06-23-03 Rel pkr @ 4002' & TOH w/127 jts 2-7/8" tbg & lay down pkr.         Set CIBP @ 4002'. Set pkr @ 3992'; test CIBP to 500 psi (goo Isolated csg leak from 2274' to 2525'.         06-24-03 Rel pkr @ 2274' & TOH w/WS & lay down pkr. TIH open ended w,         RU on tbg to spot cement in 5-1/2" csg, holes from 2525'-227.         (continued on page 2)  | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>& WS to 4033' & set plor @ 4033'.<br>flush w/400 bbls.<br>TIH w/CIBP plor & WS to 4002'.<br>od).<br>Hobbs<br>/WS & sub; bottom of the @ 2526'.<br>A' w/125 sx Class C cmt w/2% CaCl.                    |  |  |
| THER:       OTHER: Clean Out,         12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.         06-17-03 MIRU. Move in frac tanks.         06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4         06-19-03 Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN         06-20-03 Acidize w/4000 gals 15% H15.         06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.         06-22-03 Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,         06-23-03 Rel pkr @ 4002' & TOH w/127 jts 2-7/8" tbg & lay down pkr.         Set CIBP @ 4002'. Set pkr @ 3992'; test CIBP to 500 psi (got Isolated csg leak from 2274' to 2525'.         06-24-03 Rel pkr @ 2274' & TOH w/WS & lay down pkr. TIH open ended w, RU on tbg to spot cement in 5-1/2" csg, holes from 2525'-227.         (continued on page 2)         ereby certify that the information above is true and complete to the best of my knowledge and belief.         GNATURE       Juma Skinner   | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>& WS to 4033' & set plor @ 4033'.<br>flush w/400 bbls.<br>TIH w/CIBP pkr & WS to 4002'.<br>A<br>Hobbs<br>/WS & sub; bottom of they @ 2526'.<br>A' w/125 sx Class C cmt w/2% CaCl.<br>List DATE 07-15-03 |  |  |
| THER:       OTHER: Clean Out,         12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.         06-17-03 MIRU. Move in frac tanks.         06-18-03 TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4         06-19-03 Finished TTH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN         06-20-03 Acidize w/4000 gals 15% H15.         06-21-03 RU swab; ending fluid level @ 2400' from surface. RD swab.         06-22-03 Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,         06-23-03 Rel pkr @ 4002'. & TOH w/127 jts 2-7/8" tbg & lay down pkr.         98 et CIEP @ 4002'. Set pkr @ 3992'; test CIEP to 500 psi (goo Isolated csg leak from 2274' to 2525'.         06-24-03 Rel pkr @ 2274' & TOH w/WS & lay down pkr. TIH open ended w, RU on tbg to spot cement in 5-1/2" csg, holes from 2525'-227.         (continued on page 2)         ereby certify that the information above is true and complete to the best of my knowledge and belief.         GNATURE       TITLE Regulatory Specia   | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>& WS to 4033' & set place @ 4033'.<br>flush w/400 bbls.<br>TIH w/CIBP pkr & WS to 4002'.<br>od).<br>/WS & sub; bottom of the @ 2526'.<br>A' w/125 sx Class C cmt w/2% CaCl.<br>List                     |  |  |
| THER:       OTHER: clean Out,         12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach v or recompilation.         06-17-03       MIRU. Move in frac tanks.         06-18-03       TOH w/144 jts 2-7/8" tbg. Changed rams on BOP. TIH w/4-3/4         06-19-03       Finished TIH w/WS to tag @ 4650'. TOH w/bit. TIH w/pkr, SN         06-20-03       Acidize w/4000 gals 15% H15.         06-21-03       RU swab; ending fluid level @ 2400' from surface. RD swab.         06-22-03       Chemical squeeze; 5 drums TH756 mixed w/12 bbls FW per drum,         06-23-03       Rel pkr @ 4002' & TOH w/127 jts 2-7/8" tbg & lay down pkr.         Set CIBP @ 4002'.       Set pkr @ 3992'; test CIBP to 500 psi (goo Isolated csg leak from 2274' to 2525'.         06-24-03       Rel pkr @ 2274' & TOH w/WS & lay down pkr.         RU on tbg to spot cement in 5-1/2" csg, holes from 2525'-227.         (continued on page 2)         ereby certify that the information above is true and complete to the best of my knowledge and belief.         GNATURE       Juma Skinner         his space for State use)       ORIGINAL SIGNED BY | e pertinent dates, including estimated date<br>vellbore diagram of proposed completion<br>" bit & 100 jts 2-7/8" WS to 3144'.<br>& WS to 4033' & set plor @ 4033'.<br>flush w/400 bbls.<br>TIH w/CIBP plor & WS to 4002'.<br>od).<br>/WS & sub; bottom of the @ 2526'.<br>A' w/125 sx Class C cmt w/2% CaCl.                             |  |  |

ł

## VACUUM GRAYBURG SAN ANDRES UNIT NO. 28 PAGE 2

- 06-25-03 TIH w/bit, DC & tbg to tag @ 1323'. Broke circulation; start drill cement to 1596'.
- 06-26-03 Continue drlg cement from 1596' to 2004'.
- 06-27-03 Drl cement to 2444'. TOH w/2-7/8" WS to 2556'.
- 06-30-03 TOH w/tbg, DC & bit. Bit worn out; change out. TIH w/new bit, DC & tbg to 2444'. Start drilling cement @ 2444' to 2530'.
- 07-01-03 TOH w/2-7/8" tbg. TIH open ended w/80 jts 2-7/8" tbg & sub to 2526'.
- 07-02-03 TOH w/WS; TIH w/pkr to 2525' & test below pkr to 300# (good). TOH w/WS & lay down pkr. TIH open ended w/2-7/8" WS to 2607'. Spot cement in 5-1/2" csg from 2607'-1600' w/120 sx Pecos Valley Lite. TOH w/WS to 1550'. Pressured up on csg to 500 psi & 1050 psi.
- 07-03-03 TIH w/bit, DC & 2-3/8" WS. Tag @ 1816'; drl'd & washed out cement to 1847'.
- 07-07-03 Open well & drl'd cement from 1847'-2350'.
- 07-08-03 Drl cement from 2381'-2623'. Chart & test to 300 psi for 1 hr.; pressure stabilized @ 150#.
- 07-09-03 Tag CIBP @ 4002'. Started drlg on CIBP & pushed down to BPTD 4650'.
- 07-10-03 TOH w/2-7/8" kill string & change rams in BOP. TIH w/motor, tbg & sub. Install QCI hanger. Test run sub for 30 mins (good).
- 07-11-03 RD. Start sub pump. FINAL REPORT.

Charts were sent in after fact on 8-5-23, after rec'd from. field last week.







## Yes