Size Section Section
Santa Fe, NM 87505 Subparable Succession Subparable Subparable Succession Subparable
Santa Fe, NM 87505 Sundry Notices AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS. I. Type of Well: Oil Well
Santa Fe, NM 87505 Sundry Notices AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS. I. Type of Well: Oil Well
SUNDRY NOTICES AND REPORTS ON WELLS To Lease Name or Unit Agreement Name Meteor BEM State
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFFEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well
Section PLOP Subsequent
2. Name of Operator Yates Petroleum Corporation 3. Address of Operator 10. South Fourth Street, Artesia, NM 88210 4. Well Location Unit Letter F : 1980 feet from the North line and 1980 feet from the West line Section 23 Township 11S Range 34E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE OTHER: Plugback and recomplete Multiple Completions: Attach wellbore diagram of proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion or 12/15/10 – MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6° GR/JB to 11,790°. Set a 5-1/2° 10K alpha CIBP at 11,750°. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980°-8990' (20), 9044°-9049' (12), 9056′-9063' (16) and 9082'-9096' (30). RIH and put 35° cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
3. Address of Operator 3. Address of Operator 105 South Fourth Street, Artesia, NM 88210 4. Well Location Unit Letter F : 1980 feet from the North line and 1980 feet from the West line Section 23 Township 118 Range 34E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4144'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JOB CASING/CEMENT JOB CASING/CEMENT JOB OTHER: DOWNHOLE COMMINGLE OTHER: Plugback and recomplete MULTIPLE COMPL OTHER:
Light Mile Draw; Abo
4. Well Location Unit Letter F : 1980 feet from the North line and 1980 feet from the West line Section 23 Township 118 Range 34E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4144'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB OTHER: OTHER: OTHER Plugback and recomplete 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 12/15/10 – MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6" GR/JB to 11,790". Set a 5-1/2" 10K alpha CIBP at 11,750". Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
Unit Letter F : 1980 feet from the North line and 1980 feet from the West line Section 23 Township 11S Range 34E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4144'GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P AND A OTHER: OTHER: Plugback and recomplete Seminary proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 12/15/10 - MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 - RIH with 4.6° GR/JB to 11,790'. Set a 5-1/2" 10K alpha CIBP at 11,750'. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 - Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING ALTERING CASING COMMENCE DRILLING OPNS. PAND A COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JOB OTHER: OTHER: OTHER: OTHER: Plugback and recomplete MILITIPLE COMPL OTHER: Plugback and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 12/15/10 – MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6" GR/JB to 11,790'. Set a 5-1/2" 10K alpha CIBP at 11,750'. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING ALTERING CASING COMMENCE DRILLING OPNS. PAND A COMMENCE DRILLING OPNS. PAND A CASING/CEMENT JOB OTHER: OTHER: OTHER: OTHER: Plugback and recomplete MILITIPLE COMPL OTHER: Plugback and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 12/15/10 – MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6" GR/JB to 11,790'. Set a 5-1/2" 10K alpha CIBP at 11,750'. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A DOWNHOLE CASING MULTIPLE COMPL CASING/CEMENT JOB CASING/CEMENT JOB TOTHER: Plugback and recomplete STATE OF Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 12/15/10 – MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6" GR/JB to 11,790". Set a 5-1/2" 10K alpha CIBP at 11,750". Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980"-8990" (20), 9044"-9049" (12), 9056"-9063" (16) and 9082"-9096" (30). RIH and put 35" cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
TEMPORARILY ABANDON
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB OTHER: Plugback and recomplete 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 12/15/10 – MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6" GR/JB to 11,790'. Set a 5-1/2" 10K alpha CIBP at 11,750'. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
OTHER: Plugback and recomplete 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 12/15/10 – MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6" GR/JB to 11,790'. Set a 5-1/2" 10K alpha CIBP at 11,750'. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 12/15/10 – MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6" GR/JB to 11,790'. Set a 5-1/2" 10K alpha CIBP at 11,750'. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 12/15/10 – MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6" GR/JB to 11,790'. Set a 5-1/2" 10K alpha CIBP at 11,750'. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
proposed completion or recompletion. 12/15/10 – MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6" GR/JB to 11,790'. Set a 5-1/2" 10K alpha CIBP at 11,750'. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
12/15/10 – MIRU pulling unit. Bled down well. Loaded casing with 41 bbls. Tested to 1000 psi, good. Bled down pressure. Pumped 60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6" GR/JB to 11,790'. Set a 5-1/2" 10K alpha CIBP at 11,750'. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
60 bbls down tubing. Released packer and on/off tool. NU BOP. 12/16/10 – RIH with 4.6" GR/JB to 11,790'. Set a 5-1/2" 10K alpha CIBP at 11,750'. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
12/16/10 – RIH with 4.6" GR/JB to 11,790'. Set a 5-1/2" 10K alpha CIBP at 11,750'. Loaded hole with 215 bbls. Tested plug to 1000 psi, held good for 15 min. Perforated Abo 8980'-8990' (20), 9044'-9049' (12), 9056'-9063' (16) and 9082'-9096' (30). RIH and put 35' cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
cement on top of CIBP. 12/17-19/10 – Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
12/17-19/10 - Spotted 5 bbls across Abo perfs. ND BOP. Tested casing to 1500 psi, good. Acidized Abo with 8000g 15% NEFE HCL.
Spud Date: Rig Release Date:
· ·
I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE (Circa Hurta) TITLE Regulatory Compliance Supervisor DATE January 19, 2011
Type or print name Tina Huerta E-mail address: <u>tinah@yatespetroleum.com</u> PHONE: 575-748-4168_
For State Use Only
APPROVED BY: TITLE PETROLEM ENGLISH DATE Conditions of Approval (if any): PA Four Lakes Atoka North (GAS)
Conditions of Approval (if any): PA Four Lakes Macke Mack (GAS)