Submit Copy To Appropriate District Softice	State of New Mexico	****		n C-103 r 13, 2009
Office <u>District 1</u> ~ 1625 N. French Dr., Hobbs, NM 88 RECE FORED District II	Amerais and Natural Resou	WELL AP	I NO.	. 15, 2005
District II	NSERVATION DIVISION	ON	30-025-05145	
District III 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Bergag Rd, Artes NM 87410	0 South St. Francis Dr.	5. Indicate	Type of Lease	1
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		I & Gas Lease No.	
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPO	, ,			
SUNDRY NOTICES AND REPO	ORTS ON WELLS	7. Lease N	lame or Unit Agreemen	Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OD DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM		D A T D Pope 2	26	
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well 0	Other	8. Well Nu	10	
2. Name of Operator Celero Energy II, LP		9. OGRID	Number 247128	
3. Address of Operator 400 W. Illinois, Ste. 1601			ame or Wildcat	
4. Well Location		Denton; De	evonian	
	from the <u>South</u> line	and <u>660</u> f	eet from the East	line
Section 26 Tow	nship 14S Range 37E	NMPM	CountyLea	
11. Elevation 3805' GR	(Show whether DR, RKB, RT,	<i>GR</i> , <i>etc.</i>)		
	· · · · · · · · · · · · · · · · · · ·			
12. Check Appropriate B	ox to Indicate Nature of 1	Notice, Report or (Other Data	
NOTICE OF INTENTION T	O:	SUBSEQUEN	T REPORT OF:	
		AL WORK		
TEMPORARILY ABANDON CHANGE PLA		NCE DRILLING OPNS	S. P AND A	
PULL OR ALTER CASING 🔲 MULTIPLE CO	DMPL 🗌 CASING	CEMENT JOB		
		OEMENT OOD		
DOWNHOLE COMMINGLE		Return to production		
DOWNHOLE COMMINGLE	OTHER: (Clearly state all pertinent d	Return to production etails, and give pertine		mated dat
DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE	OTHER: (Clearly state all pertinent d	Return to production etails, and give pertine		mated dat
DOWNHOLE COMMINGLE	Clearly state all pertinent d 07HER: 0 (Clearly state all pertinent d 05 19.15.7.14 NMAC. For Mu	Return to production etails, and give pertine ltiple Completions: A	ttach wellbore diagram	nated dat of
DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 3/1/11 - 3/25/11 - POOH w/ all tbg & pkr. RIH w	OTHER: OTHER:	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,	.ttach wellbore diagram 000'. Dump 8 cubic feet	nated dat of of sand
 DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 3/1/11 - 3/25/11 - POOH w/ all tbg & pkr. RIH w & gravel mixture down tbg. RIH to 12,541'. No ta 267 jts of tbg to plug, rest of tbg clean. Drop 16 cd 	OTHER: OTHER:	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,0 nping sand & gravel m xture down tbg, flush	ttach wellbore diagram 000'. Dump 8 cubic feet hixture, tbg bridged off. tbg w/ 20 BFW. RIH w	nated dat of of sand POH w/ ' 386 jts
 DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 3/1/11 - 3/25/11 - POOH w/ all tbg & pkr. RIH w & gravel mixture down tbg. RIH to 12,541'. No ta 267 jts of tbg to plug, rest of tbg clean. Drop 16 c of tbg, tag gravel @ 12,488'. Wash down to 12,55 	OTHER: OTHER:	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12, nping sand & gravel n xture down tbg, flush mt containing 0.75 C-	ttach wellbore diagram 000'. Dump 8 cubic feet nixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38	nated dat of of sand POH w/ ' 386 jts @ 17
 DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 3/1/11 - 3/25/11 - POOH w/ all tbg & pkr. RIH w & gravel mixture down tbg. RIH to 12,541'. No ta 267 jts of tbg to plug, rest of tbg clean. Drop 16 cd 	OTHER: OTHER:	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12, nping sand & gravel n xture down tbg, flush mt containing 0.75 C- 4,000, unable to move	ttach wellbore diagram 000'. Dump 8 cubic feet nixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down	nated dat of POH w/ ' 386 jts @ 17 n tbg.
 DOWNHOLE COMMINGLE	OTHER: (Clearly state all pertinent de 19.15.7.14 NMAC. For Mu (2 7/8" notched collar, 371 j ag. POH to 12,000'. Start dun tubic feet of sand & gravel mi 30'. Mix 15 sx of Class "H" c tr, attempt to pull tbg, pull 14 (40 arm caliper. Run CIL frc g from 11,985' - 1530'. Circ v	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12, nping sand & gravel n xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. vell clean w/ 240 BFW	ttach wellbore diagram 000'. Dump 8 cubic feet nixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. J. Sting into CICR, esta	nated dat of POH w/ ' 386 jts @ 17 n tbg. POH w/ plish inj
 DOWNHOLE COMMINGLE	OTHER: (Clearly state all pertinent de 19.15.7.14 NMAC. For Mu (2 7/8" notched collar, 371 j ag. POH to 12,000'. Start dun tubic feet of sand & gravel mi 30'. Mix 15 sx of Class "H" cr tr, attempt to pull tbg, pull 14 (40 arm caliper. Run CIL frc g from 11,985' - 1530'. Circ w mix 80 sx of Class "H" cmt, .3	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12, nping sand & gravel n xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. vell clean w/ 240 BFW 5% C-20, 0.4% FL -1	ttach wellbore diagram 000'. Dump 8 cubic feet nixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. /. Sting into CICR, esta 0, 0.25% R-38 @ 15.6	nated dat of POH w/ ' 386 jts @ 17 n tbg. POH w/ plish inj ppg, 1.18
 DOWNHOLE COMMINGLE	OTHER: (Clearly state all pertinent de 19.15.7.14 NMAC. For Mu (2 7/8" notched collar, 371 j ag. POH to 12,000'. Start dun tubic feet of sand & gravel mi 30'. Mix 15 sx of Class "H" c tr, attempt to pull tbg, pull 14 (40 arm caliper. Run CIL frc g from 11,985' - 1530'. Circ w mix 80 sx of Class "H" cmt, .3 into CICR, continue displacem	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,1 nping sand & gravel m xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. vell clean w/ 240 BFW 5% C-20, 0.4% FL -1 nent of 64 bbls, pressu	ttach wellbore diagram 000'. Dump 8 cubic feet nixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. V. Sting into CICR, esta 0, 0.25% R-38 @ 15.6 ire up to 4500 psi, rate s	nated dat of POH w/ ' 386 jts @ 17 n tbg. POH w/ polish inj ppg, 1.18 lowed to
 DOWNHOLE COMMINGLE	OTHER: (Clearly state all pertinent de 19.15.7.14 NMAC. For Mu (2 7/8" notched collar, 371 j ag. POH to 12,000'. Start dun tubic feet of sand & gravel mi 30'. Mix 15 sx of Class "H" c tr, attempt to pull tbg, pull 14 (40 arm caliper. Run CIL frc g from 11,985' - 1530'. Circ w mix 80 sx of Class "H" cmt, .3 into CICR, continue displacem	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,1 nping sand & gravel m xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. vell clean w/ 240 BFW 5% C-20, 0.4% FL -1 nent of 64 bbls, pressu	ttach wellbore diagram 000'. Dump 8 cubic feet nixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. V. Sting into CICR, esta 0, 0.25% R-38 @ 15.6 ire up to 4500 psi, rate s	nated dat of POH w/ ' 386 jts @ 17 n tbg. POH w/ polish inj ppg, 1.18 lowed to
 DOWNHOLE COMMINGLE	OTHER: (Clearly state all pertinent de 19.15.7.14 NMAC. For Mu (2 7/8" notched collar, 371 j ag. POH to 12,000'. Start dun tubic feet of sand & gravel mi 30'. Mix 15 sx of Class "H" c tr, attempt to pull tbg, pull 14 (40 arm caliper. Run CIL frc g from 11,985' - 1530'. Circ w mix 80 sx of Class "H" cmt, .3 into CICR, continue displacem	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,1 nping sand & gravel m xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. vell clean w/ 240 BFW 5% C-20, 0.4% FL -1 nent of 64 bbls, pressu	ttach wellbore diagram 000'. Dump 8 cubic feet nixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. V. Sting into CICR, esta 0, 0.25% R-38 @ 15.6 ire up to 4500 psi, rate s	nated dat of POH w/ ' 386 jts @ 17 n tbg. POH w/ polish inj ppg, 1.18 lowed to
 DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 3/1/11 - 3/25/11 - POOH w/ all tbg & pkr. RIH v & gravel mixture down tbg. RIH to 12,541'. No ta 267 jts of tbg to plug, rest of tbg clean. Drop 16 c of tbg, tag gravel @ 12,488'. Wash down to 12,55 ppg. yield 1.0, 3.76 gal/sx. Displace w/ 71 bbls w Pressure up to 2000# psi, unable to move. RIH v tools. RIH w/ radial bond/GR/CCL. Run bond log rate of 0.8 BPM @ 2750 psi, sting out of CICR, r yield, 5.19 gal/sx. Displace w/ 48 bbls wtr, sting i. 6 BPM, wash up pump & lines, open tbg - 1900 bbls wtr, 4 bbls of cmt to pit. * Cöntinued on attached sheet 	OTHER: (Clearly state all pertinent de 19.15.7.14 NMAC. For Mu w/ 2 7/8" notched collar, 371 j ag. POH to 12,000'. Start dun cubic feet of sand & gravel mi 30'. Mix 15 sx of Class "H" cu tr, attempt to pull tbg, pull 14 w/ 40 arm caliper. Run CIL from g from 11,985' - 1530'. Circ w nix 80 sx of Class "H" cmt, .3 into CICR, continue displacen psi, hesitate 3 times, obtain 35	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,1 nping sand & gravel m xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. vell clean w/ 240 BFW 5% C-20, 0.4% FL -1 nent of 64 bbls, pressu	ttach wellbore diagram 000'. Dump 8 cubic feet nixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. V. Sting into CICR, esta 0, 0.25% R-38 @ 15.6 ire up to 4500 psi, rate s	of of sand POH w/ ' 386 jts @ 17 otbg. POH w/ olish inj opg, 1.18 lowed to
 DOWNHOLE COMMINGLE	OTHER: (Clearly state all pertinent de 19.15.7.14 NMAC. For Mu (2 7/8" notched collar, 371 j ag. POH to 12,000'. Start dun tubic feet of sand & gravel mi 30'. Mix 15 sx of Class "H" c tr, attempt to pull tbg, pull 14 (40 arm caliper. Run CIL frc g from 11,985' - 1530'. Circ w mix 80 sx of Class "H" cmt, .3 into CICR, continue displacem	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,1 nping sand & gravel m xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. vell clean w/ 240 BFW 5% C-20, 0.4% FL -1 nent of 64 bbls, pressu	ttach wellbore diagram 000'. Dump 8 cubic feet nixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. V. Sting into CICR, esta 0, 0.25% R-38 @ 15.6 ire up to 4500 psi, rate s	nated dat of POH w/ ' 386 jts @ 17 n tbg. POH w/ polish inj ppg, 1.18 lowed to
DOWNHOLE COMMINGLE	Clearly state all pertinent d (Clearly state all pertinent d 19.15.7.14 NMAC. For Mu (27/8" notched collar, 371 j ag. POH to 12,000'. Start dun cubic feet of sand & gravel mi 30'. Mix 15 sx of Class "H" c tr, attempt to pull tbg, pull 14 (40 arm caliper. Run CIL from g from 11,985' - 1530'. Circ v mix 80 sx of Class "H" cmt, .3 into CICR, continue displacen psi, hesitate 3 times, obtain 35 Rig Release Date:	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,0 nping sand & gravel n xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. vell clean w/ 240 BFW 5% C-20, 0.4% FL -1 nent of 64 bbls, pressu 500 psi squeeze, sting	Attach wellbore diagram 000'. Dump 8 cubic feet hixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. V. Sting into CICR, esta 0, 0.25% R-38 @ 15.6 ire up to 4500 psi, rate s out of CICR, rev clean	nated dat of POH w/ ' 386 jts @ 17 n tbg. POH w/ polish inj ppg, 1.18 lowed to
 DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 3/1/11 - 3/25/11 - POOH w/ all tbg & pkr. RIH v & gravel mixture down tbg. RIH to 12,541'. No ta 267 jts of tbg to plug, rest of tbg clean. Drop 16 c of tbg, tag gravel @ 12,488'. Wash down to 12,55 ppg. yield 1.0, 3.76 gal/sx. Displace w/ 71 bbls w Pressure up to 2000# psi, unable to move. RIH v tools. RIH w/ radial bond/GR/CCL. Run bond log rate of 0.8 BPM @ 2750 psi, sting out of CICR, r yield, 5.19 gal/sx. Displace w/ 48 bbls wtr, sting i. 6 BPM, wash up pump & lines, open tbg - 1900 bbls wtr, 4 bbls of cmt to pit. * Cöntinued on attached sheet 	Clearly state all pertinent d (Clearly state all pertinent d 19.15.7.14 NMAC. For Mu (27/8" notched collar, 371 j ag. POH to 12,000'. Start dun cubic feet of sand & gravel mi 30'. Mix 15 sx of Class "H" c tr, attempt to pull tbg, pull 14 (40 arm caliper. Run CIL from g from 11,985' - 1530'. Circ v mix 80 sx of Class "H" cmt, .3 into CICR, continue displacen psi, hesitate 3 times, obtain 35 Rig Release Date:	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,0 nping sand & gravel n xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. vell clean w/ 240 BFW 5% C-20, 0.4% FL -1 nent of 64 bbls, pressu 500 psi squeeze, sting	Attach wellbore diagram 000'. Dump 8 cubic feet hixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. V. Sting into CICR, esta 0, 0.25% R-38 @ 15.6 ire up to 4500 psi, rate s out of CICR, rev clean	nated dat of POH w/ ' 386 jts @ 17 n tbg. POH w/ polish inj ppg, 1.18 lowed to
DOWNHOLE COMMINGLE	Clearly state all pertinent d (Clearly state all pertinent d 19.15.7.14 NMAC. For Mu (27/8" notched collar, 371 j ag. POH to 12,000'. Start dun cubic feet of sand & gravel mi 30'. Mix 15 sx of Class "H" c tr, attempt to pull tbg, pull 14 (40 arm caliper. Run CIL from g from 11,985' - 1530'. Circ v mix 80 sx of Class "H" cmt, .3 into CICR, continue displacen psi, hesitate 3 times, obtain 35 Rig Release Date:	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,0 nping sand & gravel n xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. vell clean w/ 240 BFW 5% C-20, 0.4% FL -1 nent of 64 bbls, pressu 500 psi squeeze, sting	Attach wellbore diagram 000'. Dump 8 cubic feet hixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. V. Sting into CICR, esta 0, 0.25% R-38 @ 15.6 ire up to 4500 psi, rate s out of CICR, rev clean	nated dat of POH w/ ' 386 jts @ 17 n tbg. POH w/ polish inj ppg, 1.18 lowed to
DOWNHOLE COMMINGLE	Clearly state all pertinent d (Clearly state all pertinent d 19.15.7.14 NMAC. For Mu (27/8" notched collar, 371 j ag. POH to 12,000'. Start dun cubic feet of sand & gravel mi 30'. Mix 15 sx of Class "H" c tr, attempt to pull tbg, pull 14 (40 arm caliper. Run CIL from g from 11,985' - 1530'. Circ v mix 80 sx of Class "H" cmt, .3 into CICR, continue displacen psi, hesitate 3 times, obtain 35 Rig Release Date:	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12, nping sand & gravel n xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. vell clean w/ 240 BFW 5% C-20, 0.4% FL -1 nent of 64 bbls, pressu 500 psi squeeze, sting	Attach wellbore diagram 000'. Dump 8 cubic feet hixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. V. Sting into CICR, esta 0, 0.25% R-38 @ 15.6 ire up to 4500 psi, rate s out of CICR, rev clean	nated dat of POH w/ ' 386 jts @ 17 n tbg. POH w/ polish inj ppg, 1.18 lowed to
DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 3/1/11 - 3/25/11 - POOH w/ all tbg & pkr. RIH w & gravel mixture down tbg. RIH to 12,541'. No ta 267 jts of tbg to plug, rest of tbg clean. Drop 16 c of tbg, tag gravel @ 12,488'. Wash down to 12,52 ppgyield 1.0, 3.76 gal/sx. Displace w/ 71 bbls w Pressure up to 2000# psi, unable to move. RIH w tools. RIH w/ radial bond/GR/CCL. Run bond log rate of 0.8 BPM @ 2750 psi, sting out of CICR, r yield, 5.19 gal/sx. Displace w/ 48 bbls wtr, sting i .6 BPM, wash up pump & lines, open tbg - 1900 bbls wtr, 4 bbls of cmt to pit. * Cöntinued on attached sheet Spud Date: SiGNATURE	OTHER:	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,0 nping sand & gravel m xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. well clean w/ 240 BFW 5% C-20, 0.4% FL -1 nent of 64 bbls, pressu 500 psi squeeze, sting	Attach wellbore diagram 000'. Dump 8 cubic feet nixture, tbg bridged off. tbg w/ 20 BFW. RIH w 37, 1% salt, .25% R-38 e, attempt to pump down Fluid level - 1530' FFS. /. Sting into CICR, esta 0, 0.25% R-38 @ 15.6 ire up to 4500 psi, rate so out of CICR, rev clean	nated dat of of sand POH w/ 386 jts @ 17 n tbg. POH w/ olish inj opg, 1.18 lowed to w/ 100
DOWNHOLE COMMINGLE	OTHER:	Return to production etails, and give pertine ltiple Completions: A ts of 2 7/8" tbg to 12,0 nping sand & gravel m xture down tbg, flush mt containing 0.75 C- 4,000, unable to move om 11,985' to surface. well clean w/ 240 BFW 5% C-20, 0.4% FL -1 nent of 64 bbls, pressu 500 psi squeeze, sting	DATE 04/15/2011	nated dat of of sand POH w/ ' 386 jts @ 17 n tbg. POH w/ olish inj opg, 1.18 lowed to w/ 100

1

<u>**T D Pope 26 #10**</u> – C103 continued

4/1/11 - RIH w/ GR/CCL/CNL. Run log from 12,350' - 11,350'.

4/4/11 - RIH w/ 3 1/8" slick gun, 0 degree phasing, correlate back to CNL, perf 1 shot per foot as follows:

12,054' - 12,134' = 80 holes 12,154' - 12,194' = 40 holes 12,216' - 12,246' = 30 holes 12,270' - 12,330' = 60 holes

<u>4/7/11</u> - RIH w/ 11 jts of 2 7/8" tbg to 12,343', spot 250 gal of 15% NEFE inhibited HCL across perfs. POH & set pkr @ 11,780', load backside & pressure up to 500# psi. establish injection rate of 6 BPM @ 3900# psi. Treat well w/ 26,000 gal of 15% NEFE inhibited HCL mixed w/ 208 gal inhibitor, 26 gal GP3 NG agent, 130 gal LCA liquid citric acid, 112 gal AFR. Drop 325- 7/8" 1.3 ball sealers evenly throughout acid, flush w/ 170 BFW, release pkr. RIH to 12,343' to knock off balls. POH LD 33 jts of 2 7/8" tbg.

<u>4/11/11 -</u> PU sub pump as follows: 1- Phoenix sensor, 1- 456 Dominator 156 Hp 2588V 38.5A motor, 2- LSBPB seals, 1- DRS intake, 3- DN725 pumps – 678 stages, 1- 2 3/8" Std SN, x-over, 231 jts of 2 7/8" 6.5# L-80 8rd tbg (7541.04'), x-over, 141 jts of 2 7/8" PH-6 tbg (4405.59').

 $\frac{4/12/11}{1}$ - Splice lower pigtail into new #4 flat lead cable, land donut into seaboard WH, WIR – 114,000. NDBOP, build new WH, setup drive, check rotation, start pump up @ 60 Hz straight frequency. Return to production.