NO. OF COPIES RECEIVED]	Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION		C-102 and C-103
FILE		Effective 1-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State 🕱 Fee
OPERATOR		5. State Oil & Gan Lease No.
	-	R-3210
(DO NOT USE THIS FORM FOR PRO USE "APPLICAT	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVO "ION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	IR. ANN AND A
1		7. Unit Agreement Name
OIL GAS WELL	OTHER-	
2. Name of Operator Lario Oil & Gas	Company	8, Farm or Lease Name State "B"
3. Address of Operator Box 1209, Odessa,	Texas- Phone 915-366-3361	9. Well No. 1
4. Location of Well		
-		10. Field and Pool, or Wildcat
-	60 FEET FROM THE South 660	Bar U-Pennsylvanian
-	1 9-8 B-32-E	
UNIT LETTER 6	1 9=8 B=32=E	FEET FROM
UNIT LETTER 6	on YOWNSHIP RANGE	PEET FROM
UNIT LETTER P 6	on 1 9-8 RANGE R-32-B 15. Elevation (Show whether DF, RT, GR, etc.) 4404 Ground level	PEET FROM BET U-Pennsylvenian I2. County Lea
UNIT LETTER P 6	on <u>1</u> <u>9-8</u> <u>RANGE</u> <u>R-32-E</u> 15. Elevation (Show whether DF, RT, GR, etc.) 4404 Ground level Appropriate Box To Indicate Nature of Notice, Rep	PEET FROM BET U-Pennsylvenian I2. County Lea
UNIT LETTER P 6	on <u>1</u> <u>9-8</u> <u>RANGE</u> <u>R-32-E</u> 15. Elevation (Show whether DF, RT, GR, etc.) 4404 Ground level Appropriate Box To Indicate Nature of Notice, Rep	PEET FROM I2. County Lea Ort or Other Data
UNIT LETTER 6	1 9-8 RANGE 15. Elevation (Show whether DF, RT, GR, etc.) 4404 Ground level Appropriate Box To Indicate Nature of Notice, Reportention TO: PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	PEET FROM BAT U-Pennsylvenian NMPM. 12. County Lea Ort or Other Data SEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
UNIT LETTER P 6	1 9-8 RANGE R-32-8 15. Elevation (Show whether DF, RT, GR, etc.) 4404 Ground level Appropriate Box To Indicate Nature of Notice, Rep NTENTION TO: SUB Plug AND ABANDON Remedial work CHANGE PLANS CASING TEST AND CEMENT J	PEET FROM BAT U-Pennsylvenian NMPM. 12. County Lea Ort or Other Data SEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT CB
THE East THE LINE, SECTION 16, Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	1 9-8 RANGE R-32-8 15. Elevation (Show whether DF, RT, GR, etc.) 4404 Ground level Appropriate Box To Indicate Nature of Notice, Rep NTENTION TO: SUB Plug AND ABANDON Remedial work CHANGE PLANS CASING TEST AND CEMENT J	PEET FROM BAT U-Pennsylvenian NMPM. 12. County Lea Ort or Other Data SEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
UNIT LETTER 6	1 9-8 RANGE R-32-8 15. Elevation (Show whether DF, RT, GR, etc.) 4404 Ground level Appropriate Box To Indicate Nature of Notice, Rep NTENTION TO: SUB Plug AND ABANDON Remedial work CHANGE PLANS CASING TEST AND CEMENT J	PEET FROM BAT U-Pennsylvenian NMPM. 12. County Lea Ort or Other Data SEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT CB

0-26-73- Set Halliburton cast iron bridge plug at 5950' & squeezed casing below that point w/40 acks. Perforated 4 holes at 4460'. Set Helliburton cast iron cement retainer at 4450. Pump into erforation at 4460 & hole circulated behind 44" csg. Condtioned hole w/15 B.W. mixed w/2 gals orflo followed by 500 gals of mud fluid flollowed by 50 B.W. w/2 gals of Morflo. Cemented w/325 acks, pumping first 225 sacks w/braden head open and good cirdulation and last 100 sacks w/braden ead closed. Max. squeeze pressure 2000#, holding pressure 80#. Temperature survey indicates top f cement behind 44" casing at 3650. Perforated from 4383-4435', 1 hole every 2'. Total of 27 holes an tubing w/RTTS tool, swabbed down, no shows of oil or gas. Acidized w/500 gals of breakdown acid ax. pressure 4500#, injection rate 2 3/4 bbls/min. at 4000#. Immediate shut down 3200#, 5 min. hut down 2800f, 10 min, shut down 2400f. Swabbed down to 2500'. Well made small amount of acid gas /no oil, gas or salt water. Picked up tbg. to 4320'. Reset RTTS tool & swabbed down again. Acidized n 3 stages- 1000 gals of 28% acid, 1000 gals of 15% acid, 1000 gals of 5% acid followed by 9 balls irst stage. Second stage- 1000 gals of 28% acid, 1000 gals of 15% acid, 1000 gals of 5% acid ollowed by 9 balls. Third stage- 1000 gals 28% acid, 1000 gals of 15% acid, 1000 gals of 5% acid ax. treating pressure 4400#, broke back to 3200# at 2 3/4 bbls/min. 10 min. shut in pressure 2200# wabbed 5 hrs. recovered approx. 50 bbls load water and acid residue. No show of oil or gas. Swabbe total of 155 bbls load water and acid residue.

18. I hereby certify that the in:	formation above is true and comple	te to the best of my knowledge and belief.	······································	
SIGNED C BLe	en herger	TITL District Prod. Supt.	DATE	
APPROVED BY	Or Joe D. Rented by	TITLE		
CONDITIONS OF APPROVAL, IF ANY:				