

| | | |
|------------------------|--|--|
| NO. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| SANTA FE | | |
| FILE | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

| |
|--|
| 5a. Indicate Type of Lease |
| State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator Cleary Petroleum Corporation | 8. Farm or Lease Name Zapata State |
| 3. Address of Operator P. O. Drawer 2358, Midland, Texas 79701 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER <u>A</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>10</u> TOWNSHIP <u>10S</u> RANGE <u>32E</u> NMPM. | 10. Field and Pool, or Wildcat N. Mescalero Cisco |
| 15. Elevation (Show whether DF, RT, GR, etc.) 4333 Gr. | 12. County Lea |

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

(This well was purchased from Cleary Petroleum Corporation to be plugged and salvaged by H & H Supply Company, P. O. Box 95226, Oklahoma City, Oklahoma 73109.)

1. Pull production equipment from well and on wire line run CTBP to 8775'. Set and cap with 35 ft. cement.
2. Circulate hole with 9.5 mud laden fluid.
3. Cut 5½" casing at free point. Pull out of hole.
- * 4. Run tubing to the 5½" stub. Spot 100' plug in and out. WOC and tag.
5. Pull tubing to 5400 and spot a 100' plug to 5300'. Pull tubing to ~~5324~~ 5324 and spot 100 plug to 3424. WOC and tag.
6. Cut 8-5/8" casing at free point. Pull out of hole. ($\pm 100'$)
7. Run tubing to stub and spot 100' plug in and out of stub. WOC and tag.
8. Spot 100' plug at 413' to 313'. Spot 10 sk. surf. plug. Install dry hole marker. Rig down
- * 9.5 mud laden fluid will be used to displace plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 9-25-78

APPROVED BY [Signature] TITLE Geologist DATE SEP 26 1978

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 26 1978

CIL CONSERVATION COMM.
HOBBS, N. M.