

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E 8834

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dual Oil & Gas	7. Unit Agreement Name
2. Name of Operator Sunray Oil Company	8. Farm or Lease Name N.M. State "F"
3. Address of Operator P.O. Box 128, Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER F , 1983 FEET FROM THE North LINE AND 1980 FEET FROM West LINE, SECTION 1 TOWNSHIP 10S RANGE 33E NMPM.	10. Field and Pool, or Wildcat Lane Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4250.9 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

11. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Load hole w/mud & place 30 sx cmt plug over perms 10,588-10,826.
2. Place 25 sx cmt plug over perms 9796-9807.
3. Cut off 5 1/2" csg @ 4145' & pull.
4. Place cmt plugs as follows:
 - a. 25 sx top of 5 1/2" csg stub @ 4145'.
 - b. 25 sx @ 6800'
 - c. 25 sx @ 5300'.
 - d. 25 sx @ bottom of 9 5/8" csg @ 3969'.
 - e. 10 sx @ surface.
5. Cut off csg at G.L. Install dry hole marker, fill pits, level location, and clear of junk.

hereby certify that the information above is true and complete to the best of my knowledge and belief.

C.T. McChesney
C.T. McChesney

1/10/65 Dist Engr.
District Engineer

DATE **1-8-65**

BY *Leslie A. Clements*
Leslie A. Clements

TITLE

DATE

ONS OF APPROVAL, IF ANY: