DISTRIBUTION								
DISTRIBUTION			NEW	MEXICO OL CONSER	RVATION COMMISSION		Form C-101	
ANTA FE						ı	Revised 1-1-65	Type of Lease
ILE							SA, Indicate	
S.G.S. AND OFFICE								Gas Lease No.
PERATOR							-	4104
							TÜHT	mminin
APPLIC	ATION	FOR PERM	IT TO	DRILL, DEEPEN, O	OR PLUG BACK			
Type of Work							7. Unit Agree	ement Name
DRIL	. []	RE-ENTRY	<u>K</u>	DEEPEN	PLUG E	BACK		
Type of Well			-	72			8. Farm or Le	
WELL X GAS		OTHER			SINGLE MUL ZONE	ZONE		co "K" State
Name of Operator							9. Well No.	•
MIDWEST O	IL COR	PORATION				· · · · · · · · · · · · · · · · · · ·	10 Field on	i Pool, or Wildcat
Address of Operator	S DI DC	MTDT AN	an we	VAC 79701			10. Table dire	/ / /
1500 WILCO				660	Nort	h	mm	mmm
UNI	T LETTER_	<u>A</u>	ьос	ATEDF	EET FROM THE NOTE	LINE		
660 FEE	T FROM TH	E East	LIN	€ O	wp. 10-S RGE. 3	3-E NMPM		
	11111	THIT	TITI			111111	12. County	
							Lea	
	11111	111111	1111					
				[[]]]]]]]]]		9A. Formatio	i	20. Rotary or C.T.
Elevations (Show when	that DE B		Wind	& Status Plug. Bond 2	9750	rennsy	lvanian	Rotary Date Work will start
Elevations (show whe	ther Dr, R	1, etc.)			Cactus Drlg. (<u>'</u> o	ZZ. Applox	. Date Work will start
			Ł	Active	Carring Mr 19. /	,		
			Р	ROFOSED CASING AND	CEMENT PROGRAM			
SIZE OF HOLE	<u> </u>	SIZE OF CA			CEMENT PROGRAM		- CEMENT	EST. TOP
SIZE OF HOLE	<u> </u>	SIZE OF CA					F CEMENT	EST. TOP
SIZE OF HOLE	<u> </u>	SIZE OF CA					F CEMENT	EST. TOP
ORMERLY AZTEC	STATE	. "LW" NO	ASING	WEIGHT FER FOOT	SETTING DEPTH	SACKS O		
ORMERLY AZTEC IGINAL COMPLE cmt. circd.; idge plug set tive producti 4550-4650; 25 -ENTRY PROCED [8" bit. Clea	STATE TION D 5-1/2" @ 976 on 51, sx p1 URE: in out	C''LW'' NO OATA (9-1 csg. se 3'; Boug 339 BO, ug @ 396 Move in inside 5 and 470	2) 2-57) t @ 98 h "C" 5-1/2" 0-404 and r -1/2"	weight fer foot 13-3/8" csg. 849 w/cmt. top perforated 964 " csg. shot and 0; 10 sx plug 6 ig up drlg. rig w/4 3/4" bit1/2", 17# casi	set @ 335' w/cr o @ 8210'; Bough i pulled from 40	sACKS OF	d.; 8-5/6 ne perfor ITION: Po sx plug 5-1/2": pull 5-	3" csg. set @ rated 9790'-98 kA 1-18-60; cu @ 9400-9750; stub @ 4600' w 1/2" from appr lean out insid
ORMERLY AZTEC IGINAL COMPLE cmt. circd.; idge plug set tive producti 4550-4650; 25 -ENTRY PROCED 8" bit. Clea	STATE TION D 5-1/2" @ 976 on 51, sx p1 URE: in out	C''LW'' NO OATA (9-1 csg. se 3'; Boug 339 BO, ug @ 396 Move in inside 5 and 470	2) 2-57) t @ 98 h "C" 5-1/2" 0-404 and r -1/2"	weight fer foot 13-3/8" csg. 849 w/cmt. top perforated 964 " csg. shot and 0; 10 sx plug 6 ig up drlg. rig w/4 3/4" bit1/2", 17# casi	set @ 335' w/cr o @ 8210'; Bougl i9'-9660'; PRESI i pulled from 40 is Surface. 3. Clean out to Wash over and ing. Test csg. T.D. to 8000',	sacks of	d.; 8-5/6 ne perfor ITION: Po sx plug 5-1/2": pull 5-	3" csg. set @ rated 9790'-98 iA 1-18-60; cu @ 9400-9750; stub @ 4600' w 1/2" from appr lean out insid
ORMERLY AZTEC IGINAL COMPLE cmt. circd.; idge plug set tive producti 4550-4650; 25 -ENTRY PROCED 8" bit. Clea 1/2" to 9750'	STATE TION D 5-1/2" @ 976 on 51, sx pl WRE: n out . Run	Cag. se 3'; Boug 339 BO, ag @ 396 Move in inside 5 and 470 gamma r	2) 2-57) t @ 9; h "C" 5-1/2' 0-404 and r -1/2" 0', 5	weight fer foot 13-3/8" csg. 849 w/cmt. top perforated 964 " csg. shot and 0; 10 sx plug 6 ig up drlg. rig w/4 3/4" bit1/2", 17# casi utron log from	set @ 335' w/cr p @ 8210'; Bougl g9'-9660'; PRESI pulled from 40 Surface. 3. Clean out to Wash over and Ing. Test csg. T.D. to 8000',	sacks of the same	d.; 8-5/6 ne perfor ITION: Po sx plug 5-1/2" pull 5- PSI. C l hydrau	3" csg. set @ rated 9790'-98 iA 1-18-60; cu @ 9400-9750; stub @ 4600' w 1/2" from appr lean out insid
ORMERLY AZTEC IGINAL COMPLE cmt. circd.; idge plug set tive producti 4550-4650; 25 -ENTRY PROCED 8" bit. Clea 1/2" to 9750'	STATE TION D 5-1/2" @ 976 on 51, sx pl WRE: n out . Run	"LW" NO ATA (9-1 csg. se i3'; Boug 339 BO, ug @ 396 Hove in inside 5 and 470 gamma r	2) 2-57) t @ 9; h "C" 5-1/2' 0-404 and r -1/2" 0', 5	WEIGHT FER FOOT 13-3/8" csg. 849 w/cmt. top perforated 964 " csg. shot and 0; 10 sx plug 6 ig up drlg. rig w/4 3/4" bit1/2", 17# casi utron log from	set @ 335' w/cr @ 8210'; Bougl in 9'-9660'; PRESI in pulled from 40 @ Surface. g. Clean out to Wash over and Ing. Test csg. T.D. to 8000',	sacks of the same	d.; 8-5/6 ne perfor ITION: Po sx plug 5-1/2" pull 5- PSI. C l hydrau	3" csg. set @ rated 9790'-98 iA 1-18-60; cu @ 9400-9750; stub @ 4600' w 1/2" from appr lean out insid lic pumping eq
CORMERLY AZTEC CORMERLY AZTEC CIGINAL COMPLE Cont. circd.; cidge plug set tive producti 4550-4650; 25 3-ENTRY PROCED 8" bit. Clea 700'. Run csg -1/2" to 9750'	STATE TION D 5-1/2" @ 976 on 51, sx pl WRE: n out . Run	"LW" NO ATA (9-1 csg. se i3'; Boug 339 BO, ug @ 396 Hove in inside 5 and 470 gamma r	2) 2-57) t @ 9; h "C" 5-1/2' 0-404 and r -1/2" 0', 5	WEIGHT FER FOOT 13-3/8" csg. 849 w/cmt. top perforated 964 " csg. shot and 0; 10 sx plug 6 ig up drlg. rig w/4 3/4" bit1/2", 17# casi utron log from	set @ 335' w/cr @ 8210'; Bougl in 9'-9660'; PRESI in pulled from 40 @ Surface. g. Clean out to Wash over and Ing. Test csg. T.D. to 8000',	sacks of the same	d.; 8-5/6 ne perfor ITION: Po sx plug 5-1/2" pull 5- PSI. C l hydrau	3" csg. set @ rated 9790'-98 iA 1-18-60; cu @ 9400-9750; stub @ 4600' w 1/2" from appr lean out insid
ORMERLY AZTEC IGINAL COMPLE cmt. circd.; idge plug set tive producti 4550-4650; 25 -ENTRY PROCED 8" bit. Clea 00'. Run csg 1/2" to 9750' ABOVE SPACE DESCRIZONE. GIVE BLOWOUT reby certify that the in	STATE TION D 5-1/2" @ 976 on 51, sx pl WRE: n out . Run	Cag. se 3'; Boug 339 BO, lug @ 396 Move in inside 5 and 470 gamma r	2) 2-57) t @ 9; h "C" 5-1/2' 0-404 and r -1/2" 0', 5	weight fer foot 13-3/8" csg. 849 w/cmt. top perforated 964 " csg. shot and 0; 10 sx plug 6 ig up drlg. rig w/4 3/4" bit1/2", 17# casi utron log from	set @ 335' w/cr @ 8210'; Bougl in 9'-9660'; PRESI in pulled from 40 @ Surface. g. Clean out to Wash over and Ing. Test csg. T.D. to 8000',	sacks of the same	d.; 8-5/8 ne perfor ITION: Po sx plug 5-1/2" pull 5- PSI. C l hydrau	3" csg. set @ rated 9790'-98 iA 1-18-60; cu @ 9400-9750; stub @ 4600' w 1/2" from appr lean out insid lic pumping ed
ORMERLY AZTEC IGINAL COMPLE cmt. circd.; idge plug set tive producti 4550-4650; 25 -ENTRY PROCED 8" bit. Clea 00'. Run csg 1/2" to 9750' ABOVE SPACE DESCRIZONE. GIVE BLOWOUT reby certify that the in	STATE TION D 5-1/2" @ 976 on 51, sx pl URE: n out bowl Run formation	Cag. se 3'; Boug 339 BO, lug @ 396 Move in inside 5 and 470 gamma r	2) 2-57) t @ 9; h "C" 5-1/2' 0-404 and r -1/2" 0', 5	WEIGHT FER FOOT 13-3/8" csg. 849 w/cmt. top perforated 964 " csg. shot and 0; 10 sx plug (c) ig up drlg. rig w/4 3/4" bit1/2", 17# casi utron log from PROPOSAL IS TO DEEPEN O	set @ 335' w/cr p @ 8210'; Bougl g'-9660'; PRESI pulled from 40 Surface. 3. Clean out to Wash over and Ing. Test csg. T.D. to 8000', preprint and belief. CTION CLERK	sacks of	d.; 8-5/8 ne perfor ITION: Po sx plug 5-1/2" pull 5- PSI. C l hydrau	3" csg. set @ rated 9790'-98 iA 1-18-60; cu @ 9400-9750; stub @ 4600' w 1/2" from appr lean out insid lic pumping eq
CORMERLY AZTEC CIGINAL COMPLE Cont. circd.; cidge plug set ative producti 4550-4650; 25 CENTRY PROCED (8" bit. Clea (00'. Run csg -1/2" to 9750' ABOVE SPACE DESCR E ZONE. GIVE BLOWOUT Breby certify that the in med	STATE TION D 5-1/2" @ 976 on 51, sx pl URE: n out bowl Run formation	Cag. se 3'; Boug 339 BO, lug @ 396 Move in inside 5 and 470 gamma r	2) 2-57) t @ 9; h "C" 5-1/2' 0-404 and r -1/2" 0', 5	WEIGHT FER FOOT 13-3/8" csg. 849 w/cmt. top perforated 964 " csg. shot and 0; 10 sx plug (c) ig up drlg. rig w/4 3/4" bit1/2", 17# casi utron log from PROPOSAL IS TO DEEPEN O	set @ 335' w/cr @ 8210'; Bougl in 9'-9660'; PRESI in pulled from 40 @ Surface. g. Clean out to Wash over and Ing. Test csg. T.D. to 8000',	sacks of	d.; 8-5/8 ne perfor ITION: Po sx plug 5-1/2" pull 5- PSI. C l hydrau	3" csg. set @ rated 9790'-98 iA 1-18-60; cu @ 9400-9750; stub @ 4600' w 1/2" from appr lean out insid lic pumping eq