

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Oil ☒ Gas ☐ Other ☐		7. Unit Agreement Name	
2. Name of Operator The Maurice L. Brown Company		8. Farm or Lease Name McNulty 7101 JVD	
3. Address of Operator Suite 200/Sutton Place Bldg. Wichita, Kansas 67202		9. Well No. 1	
4. Location of Well UNIT LETTER L 1976 FEET FROM THE South LINE AND 661 FEET FROM THE West LINE, SECTION 3 TOWNSHIP 9-S RANGE 34-E NMPM.		10. Field and Pool, or Whidout Vada Penn	
11. Elevation (Show whether DF, RT, GR, etc.) 4262 GR		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up PBCP Services, Inc. casing pulling rig.
2. Pick up cement retainer and 2 3/8" tubing and run in hole to 6100'.
3. Set retainer at 6100' and squeeze with 150 sacks cement. Wait on cement.
4. Load hole with salt gel mud.
5. Salvage 5 1/2" casing from free point anticipated to be at 5000'.
6. Spot 35 sacks cement through tubing from a point 50' below the 5 1/2" casing stub. Tag top of cement.
7. Spot 35 sacks cement through tubing at 4150' to form a 100' plug straddling the 8 5/8" casing shoe. Tag top of cement.
8. Spot 35 sacks cement through tubing at 2150' depth across top of salt section.
9. Salvage 8 5/8" casing from free point anticipated to be at 1000' depth.
10. Spot 60 sacks cement through tubing from a point 50' below top of the 8 5/8" casing stub. Tag top of cement.
11. Spot 60 sacks cement through tubing at 494' to form 100' cement plug straddling the 13 3/8" casing shoe. Tag top of cement.
12. Spot 10 sacks cement at surface and erect dry hole marker.
13. Rig down PBCP Services, Inc.
14. Fill pits and cellar and clean and level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. Groesbeck TITLE District Engineer DATE 5-28-81

APPROVED BY Jerry Deaton TITLE Dist. L. Supv. DATE JUN 2 1981

CONDITIONS OF APPROVAL, IF ANY: