- State of New Mexico Submit 3 Copies E1 /, Minerals and Natural Resources Departmen District Office	- Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	WELL API NO. 30-025-01822
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lesse No. VO-4510
SUNDRY NOTICES AND REPORTS ON WELLS	
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
I. Type of Well: OL GAS WELL WELL X OTHER	Sand Springs ASU State
2. Name of Operator	8. Well No.
YATES PETROLEUM CORPORATION	9. Pool name or Wildcat
3. Address of Operator 105 South 4th St., Artesia, NM 88210	Sand Springs Atoka (gas)
4. Well Location	
Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>66</u>	0 Feet From The East
Section 11 Township 11S Range 34E	NMPM Lea Coun
Section 11 10 Elevation (Show whether DF, RKB, RT, GR, etc.)	
4145.2' GR	
11. Check Appropriate Box to Indicate Nature of Notice,	Report, or Other Data
NOTICE OF INTENTION TO: SU	IBSEQUENT REPORT OF:
	ALTERING CASING
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI	
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLII   PULL OR ALTER CASING CASING TEST AND	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN CASING TEST AND	
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLII   PULL OR ALTER CASING CASING TEST AND   DTHER: OTHER: Re-en	
TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     DULL OR ALTER CASING   CASING TEST AND   CASING TEST AND     DTHER:   OTHER:   OTHER:   Re-en     12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, included)   Commence of the state all pertinent details, and give pertinent dates, included)	NG OPNS. PLUG AND ABANDONMEN CEMENT JOB
EMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     COMMENCE DRILLIN   CASING TEST AND   CASING TEST AND     OTHER:   OTHER:   OTHER:   Re-en     12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, ind   work) SEE RULE 1103.     9-21-99   Dig out cellar.   Removed dry hole marker.   Cut     Interfault 11"   X 5000 starting head.   Clean and level location	NG OPNS. PLUG AND ABANDONMEN CEMENT JOB
EMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     PULL OR ALTER CASING   CASING TEST AND   CASING TEST AND     OTHER:   OTHER:   OTHER:   Re-en     12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incoment, SEE RULE 1103.   OTHER:   Removed dry hole marker.   Cut     Install 11'' X 5000 starting head.   Clean and level location   Set   Set	NG OPNS. PLUG AND ABANDONMEN CEMENT JOB
TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     COLL OR ALTER CASING   CASING TEST AND   CASING TEST AND     OTHER:   OTHER:   OTHER:   Re-en     12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, incomercial states)   OTHER:   Re-en     12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, incomercial states)   OTHER:   Re-en     13. 9-21-99   Dig out cellar.   Removed dry hole marker.   Cut     Install 11" X 5000 starting head.   Clean and level locations   Set     9-22-99   Moved in and rigged up re-entry equipment.   Set     9-22-99   Noved in and rigged up nulling upit.   Nippled up	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB
EMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     COMMENCE DRILLIN   CASING TEST AND   CASING TEST AND     OTHER:   OTHER:   OTHER:   Re-end     12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, ind   other completed operations (Clearly state all pertinent details, and give pertinent dates, ind     9-21-99   Dig out cellar.   Removed dry hole marker.   Cut     Install 11" X 5000 starting head.   Clean and level locati   9-22-99     9-24-99   Moved in and rigged up re-entry equipment.   Set     9-24-99   Moved in and rigged up pulling unit.   Nippled up     Lipe from BOP to shale shaker.   Set racks and unloaded to	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB
TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     CASING TEST AND   CASING TEST AND     OTHER:   OTHER:   OTHER:     II2. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:     II2. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:     II2. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   Work) SEE RULE 1103.     9-21-99 - Dig out cellar.   Removed dry hole marker.   Cut     Install 11" X 5000 starting head.   Clean and level locati     9-22-99 - Moved in and rigged up re-entry equipment.   Set     9-24-99 - Moved in and rigged up pulling unit.   Nippled u     11ne from BOP to shale shaker.   Set racks and unloaded to     Sylvia w/OCD-Hobbs of intent to spud.   Set hold and to the state of t	NG OPNS. PLUG AND ABANDONMEN CEMENT JOB Atry cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified l collars. Drilled 3' of
EMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     PULL OR ALTER CASING   CASING TEST AND     OTHER:   OTHER:   OTHER:     Re-end   OTHER:   Re-end     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, ind   orther:     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, ind   work) SEE RULE 1103.     9-21-99   Dig out cellar. Removed dry hole marker. Cut   Install 11" X 5000 starting head. Clean and level locati     9-22-99   Moved in and rigged up re-entry equipment. Set   9-24-99     9-24-99   Moved in and rigged up pulling unit. Nippled u   line from BOP to shale shaker. Set racks and unloaded to     Sylvia w/OCD-Hobbs of intent to spud.   9-25-99   TIH with 7-7/8" mill tooth bit and 4-3/4" drill	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB atry cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified l collars. Drilled 3' of Drilled solid cement. Fell
EMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     CASING TEST AND   CASING TEST AND     DTHER:   OTHER:   Re-en     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:     13 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:     14 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   Work) SEE RULE 1103.     9-21-99 - Dig out cellar.   Removed dry hole marker.   Cut     Install 11" X 5000 starting head.   Clean and level locating   Set     9-24-99 - Moved in and rigged up re-entry equipment.   Set     9-24-99 - Moved in and rigged up pulling unit.   Nippled up     11 ne from BOP to shale shaker.   Set racks and unloaded to     Sylvia w/OCD-Hobbs of intent to spud.   9-25-99 - TIH with 7-7/8" mill tooth bit and 4-3/4" drill     cement and fell thru 10'.   Drilled 3' and fell thru 15'.     out of cement at 440'.   TIH and tagged up at 1095'.   Drill	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB atry cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified l collars. Drilled 3' of Drilled solid cement. Fell
EMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     PULL OR ALTER CASING   CASING TEST AND     OTHER:   OTHER:   OTHER:     12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc. work)   SEE RULE 1103.     9-21-99   Dig out cellar. Removed dry hqle marker. Cut   Install 11" X 5000 starting head. Clean and level locations (2000 starting head. Clean and level locations)     9-22-99   Moved in and rigged up re-entry equipment. Set     9-24-99   Moved in and rigged up pulling unit. Nippled up     11ne from BOP to shale shaker. Set racks and unloaded to     Sylvia w/OCD-Hobbs of intent to spud.     9-25-99   TIH with 7-7/8" mill tooth bit and 4-3/4" drill     cement and fell thru 10'. Drilled 3' and fell thru 15'.     out of cement at 440'. TIH and tagged up at 1095'. Drill     NOTE:   Spudded at 8:00 AM 9-24-99.	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified l collars. Drilled 3' of Drilled solid cement. Fell lling at 1130' and report time gh. Metal cuttings in returns
EMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     DULL OR ALTER CASING   CASING TEST AND     DTHER:   OTHER:   CASING TEST AND     DTHER:   OTHER:   OTHER:   CASING TEST AND     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:   Re-ent     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:   Re-ent     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:   Re-ent     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   Work) SEE RULE 1103.   OTHER:   Re-ent     9-21-99 - Dig out cellar.   Removed dry hole marker.   Cut   Install 11" X 5000 starting head.   Clean and level locating 9-22-99 - Moved in and rigged up re-entry equipment.   Set     9-24-99 - Moved in and rigged up pulling unit.   Nippled up   Nippled up   Nippled up     1ine from BOP to shale shaker.   Set racks and unloaded to   Sylvia w/OCD-Hobbs of intent to spud.   9-25-99 - TIH with 7-7/8" mill tooth bit and 4-3/4" drill cement and fell thru 10'.   Drilled 3' and fell thru 15'.   Out of cement at 440'.   TIH and tagged up at 1095'.   Drill<	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified l collars. Drilled 3' of Drilled solid cement. Fell lling at 1130' and report time gh. Metal cuttings in returns metal. Made 2nd run and
EMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     PULL OR ALTER CASING   OTHER:   CASING TEST AND     OTHER:   OTHER:   OTHER:   Re-en     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, ind   oTHER:   Re-en     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, ind   work) SEE RULE 1103.   OTHER:   Re-en     9-21-99   Dig out cellar.   Removed dry hole marker.   Cut     Install 11"   X 5000 starting head.   Clean and level locations (Clearly state all periment dates, ind     9-22-99   Moved in and rigged up re-entry equipment.   Set     9-24-99   Moved in and rigged up pulling unit.   Nippled up     1ine from BOP to shale shaker.   Set racks and unloaded to     Sylvia w/OCD-Hobbs of intent to spud.   9-25-99 - TIH with 7-7/8" mill tooth bit and 4-3/4" drill     cement and fell thru 10'.   Drilled 3' and fell thru 15'.   out of cement at 440'.     NOTE:   Spudded at 8:00 AM 9-24-99.   9-26-99 - Drilled cement down to 1137', bouncing and roug     TOOH.   TIH with 7" magnet.   Recovered several pieces of the several pieces o	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified l collars. Drilled 3' of Drilled solid cement. Fell lling at 1130' and report time gh. Metal cuttings in returns metal. Made 2nd run and Potated and circulated.
EMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     PULL OR ALTER CASING   OTHER:   CASING TEST AND     DTHER:   OTHER:   OTHER:   OTHER:     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:   Re-ent     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:   Re-ent     13 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:   Re-ent     14 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:   Re-ent     15 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:   Re-ent     16 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:   Re-ent     9-21-99 - Dig out cellar.   Removed dry hole marker.   Cut   Cut     9-22-99 - Moved in and rigged up re-entry equipment.   Set     9-24-99 - Moved in and rigged up pulling unit.   Nippled up     11 ine from BOP to shale shaker.   Set racks and unloaded tu     9-25-99 - TIH with 7-7/8" mill tooth bit and 4-3/4" drill	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified l collars. Drilled 3' of Drilled solid cement. Fell lling at 1130' and report time gh. Metal cuttings in returns metal. Made 2nd run and . Rotated and circulated. Had cement core but no metal.
TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     PULL OR ALTER CASING   CASING TEST AND   CASING TEST AND     OTHER:   OTHER:   OTHER:   Re-ent     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:   Re-ent     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   OTHER:   Re-ent     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc.   Work) SEE RULE 1103.   OTHER:   Re-ent     9-21-99 - Dig out cellar.   Removed dry hole marker.   Cut   Install 11" X 5000 starting head.   Clean and level locating     9-22-99 - Moved in and rigged up re-entry equipment.   Set   9-24-99 - Moved in and rigged up pulling unit.   Nippled up     11ne from BOP to shale shaker.   Set racks and unloaded to   Sylvia w/OCD-Hobbs of intent to spud.   9-25-99 - TIH with 7-7/8" mill tooth bit and 4-3/4" drill:   cement and fell thru 10'.   Drilled 3' and fell thru 15'.   out of cement at 440'.   TIH and tagged up at 1095'.   Drill     NOTE:   Spudded at 8:00 AM 9-24-99.   9-26-99 - Drilled cement down to 1137', bouncing and rou   TOOH.   TIH with 7" magnet.   Recovered several pieces of recovered more metal pieces.	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB atry cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified l collars. Drilled 3' of Drilled solid cement. Fell lling at 1130' and report time gh. Metal cuttings in returns metal. Made 2nd run and . Rotated and circulated. Had cement core but no metal. CONTINUED ON NEXT PAGE:
EMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     CASING TEST AND   CASING TEST AND     DTHER:   OTHER:   OTHER:     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc. work) SEE RULE 1103.   OTHER:   Removed dry hole marker. Cut     11 Install 11"   X 5000 starting head. Clean and level locatif 9-22-99 - Moved in and rigged up re-entry equipment. Set 9-24-99 - Moved in and rigged up pulling unit. Nippled up line from BOP to shale shaker. Set racks and unloaded to Sylvia w/OCD-Hobbs of intent to spud.     9-25-99 - TIH with 7-7/8" mill tooth bit and 4-3/4" drill cement and fell thru 10'. Drilled 3' and fell thru 15'. out of cement at 440'. TIH and tagged up at 1095'. Drill NOTE: Spudded at 8:00 AM 9-24-99.     9-26-99 - Drilled cement down to 1137', bouncing and roug TOOH. TIH with 7" magnet. Recovered several pieces of precovered more metal pieces. Ran cutlip guide on magnet TOOH. TIH with 7-3/4" globe basket and cut 3'. TOOH.	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified l collars. Drilled 3' of Drilled solid cement. Fell lling at 1130' and report time gh. Metal cuttings in returns metal. Made 2nd run and . Rotated and circulated. Had cement core but no metal.
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING OTHER: DTHER: DTHER: 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc work) SEE RULE 1103. 9-21-99 - Dig out cellar. Removed dry hole marker. Cut Install 11" X 5000 starting head. Clean and level locati 9-22-99 - Moved in and rigged up re-entry equipment. Set 9-24-99 - Moved in and rigged up pulling unit. Nippled u line from BOP to shale shaker. Set racks and unloaded tu Sylvia w/OCD-Hobbs of intent to spud. 9-25-99 - TIH with 7-7/8" mill tooth bit and 4-3/4" drill: cement and fell thru 10'. Drilled 3' and fell thru 15'. out of cement at 440'. TIH and tagged up at 1095'. Drill: NOTE: Spudded at 8:00 AM 9-24-99. 9-26-99 - Drilled cement down to 1137', bouncing and roug TOOH. TIH with 7" magnet. Recovered several pieces of a recovered more metal pieces. Ran cutlip guide on magnet TOOH. TIH with 7-3/4" globe basket and cut 3'. TOOH. 1 hereby certify that for formation above is nu and complete to the best of my knowledge and belief. SMNATURE	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB atry cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified l collars. Drilled 3' of Drilled solid cement. Fell lling at 1130' and report time gh. Metal cuttings in returns metal. Made 2nd run and . Rotated and circulated. Had cement core but no metal. CONTINUED ON NEXT PAGE:
ENPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     PULL OR ALTER CASING   CASING TEST AND     DTHER:   OTHER:   CASING TEST AND     12 Describe Proposed or Completed Operations (Clearly state all perimens details, and give periment dates, inc. work) SEE RULE 1103.   OTHER:   Re-ent     9-21-99   Dig out cellar.   Removed dry hole marker.   Cut     Install 11"   X 5000 starting head.   Clean and level locating     9-22-99   Moved in and rigged up re-entry equipment.   Set     9-24-99   Moved in and rigged up pulling unit.   Nippled up     1ine from BOP to shale shaker.   Set racks and unloaded to     Sylvia w/OCD-Hobbs of intent to spud.   9-25-99 - TIH with 7-7/8" mill tooth bit and 4-3/4" drill     cement and fell thru 10'.   Drilled 3' and fell thru 15'.   Drilled 3' and fell thru 15'.     out of cement at 440'.   TIH and tagged up at 1095'.   Drill     NOTE:   Spudded at 8:00 AM 9-24-99.   9-26-99 - Drilled cement down to 1137', bouncing and roup     TOOH.   TIH with 7-3/4" globe basket and cut 3'.   TOOH.     Ihereby certify that Be domention bove is try and complete to the best of my threwidege and belif.   SunATURE     SUNATURE   Mathematice tope is try and complete to t	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB htty cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified 1 collars. Drilled 3' of Drilled solid cement. Fell 11ing at 1130' and report time gh. Metal cuttings in returns metal. Made 2nd run and . Rotated and circulated. Had cement core but no metal. CONTINUED ON NEXT PAGE: Technician DATE Oct. 12, 19 TELEPHONE NO. 505/74
THE PORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     CASING TEST AND   CASING TEST AND   CASING TEST AND     DULL OR ALTER CASING   OTHER:   CASING TEST AND     DTHER:   OTHER:   OTHER:   Re-en     12 Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, inc.   OTHER:   Re-en     13 Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, inc.   OTHER:   Re-en     14 Describe Proposed or Completed Operations (Clearly state all perinent details, and give perinent dates, inc.   Work) SEE RULE 1103.   OTHER:   Re-en     9-21-99 - Dig out cellar.   Removed dry hole marker.   Cut   Install II" X 5000 starting head.   Clean and level locati     9-22-99 - Moved in and rigged up re-entry equipment.   Set   Set   9-24-99 - Moved in and rigged up pulling unit.   Nippled u     1 ine from BOP to shale shaker.   Set racks and unloaded to   Sylvia w/OCD-Hobbs of intent to spud.   9-25-99 - TIH with 7-7/8" mill tooth bit and 4-3/4" drill   cement and fell thru 10'.   Drilled 3' and fell thru 15'.   Out of cement at 440'.   TIH and tagged up at 1095'.   Dril     NOTE:   Spudded at 8:00 AM 9-24-99.   9-26-99 - Drilled cement down to 1137', bouncing and rou;	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB
TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLIN     DULL OR ALTER CASING   CASING TEST AND     DTHER:   OTHER:   CASING TEST AND     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc. work) SEE RULE 1103.   OTHER:   Re-ent     12 Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, inc. work) SEE RULE 1103.   OTHER:   Re-ent     9-21-99   Dig out cellar.   Removed dry hole marker.   Cut     Install 11" X 5000 starting head.   Clean and level locating   9-22-99     9-24-99   Moved in and rigged up re-entry equipment.   Set     9-24-99   Moved in and rigged up pulling unit.   Nippled up     1ine from BOP to shale shaker.   Set racks and unloaded to     Sylvia w/OCD-Hobbs of intent to spud.   9-25-99 - TIH with 7-7/8" mill tooth bit and 4-3/4" drill:     cement and fell thru 10'.   Drilled 3' and fell thru 15'.   Out of cement at 440'.     NOTE:   Spudded at 8:00 AM 9-24-99.   9-26-99 - Drilled cement down to 1137', bouncing and roup     TOOH.   TIH with 7-3/4" globe basket and cut 3'.   TOOH.     I hareby cardy that be domention hove is try and complete to the best of my trowledge and belld.   SUNATURE	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB htty cluding estimated date of starting any proposed off and dress 8-5/8" casing. ion. Dig pit. t anchors. up 10" 5000 BOP. Build 3" ubing. NOTE: Notified 1 collars. Drilled 3' of Drilled solid cement. Fell 11ing at 1130' and report time gh. Metal cuttings in returns metal. Made 2nd run and . Rotated and circulated. Had cement core but no metal. CONTINUED ON NEXT PAGE: Technician DATE Oct. 12, 19 TELEPHONE NO. 505/74

.

YATES PETROLEUM CORPORATION Sand Springs ASU State #1. Section 11-T11S-R34E Lea County, New Mexico

## SUNDRY NOTICE CONTINUED:

TIH with bit. Reamed from 1137-1140'. Drilled 5' of cement and quit making hole. Getting redbed back. NOTE: In 2 hours drilling, made about 6". 9-27-99 - TOOH with bit - all teeth worn off except outside row on cones. TIH with re-tipped bit and drill collars. Tagged up at 1145' and started drilling. Rotated 1 hour - rough. Did not make any hole. Had redbed and rocks in returns. TOOH several teeth broken off bit. TIH with 7-1/2" OD lead block and tagged up at 1145'. TOOH - no marks on blocks. Had chunks of redbed stuck to bottom of block. Shut well in and shut down.

9-28-99 - Decision was made not to continue on well due to redbed coming into 8-5/8" casing. NOTE: Casing is parted.

Rusty Klein

Operations Technician October 12, 1999