

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

WELL API NO.  
30-025-22066

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Tipperary Oil & Gas Corporation

3. Address of Operator  
800 N. Marienfeld, Suite 100 Midland, Texas 79701

4. Well Location  
Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line  
Section 18 Township 11S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
4312.9 G.L.

7. Lease Name or Unit Agreement Name

Huber Collier

8. Well No.  
1

9. Pool name or Wildcat  
North Bagley

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spot 270 sx cement across 4525' for bottom plug if unable to get below casing part at 4525'. After getting circulation, load hole with mud mixed at 25 sx gel per 100 bbls. Set 25 sx at 4525'. Cut 4 1/2" csg and pull as much as possible (+/-4200'). Set 100' plug (25 sx) 1/2 in and 1/2 out across the stub. Set 100' plug (30 sx) 1/2 in and 1/2 out across 8 5/8" shoe (3750'). Set 100' plug (35 sx) across anhydrite (1675' - 1575'). Cut 8 5/8" csg and pull as much as possible (+/- 650'). Set 100' plug (39 sx) 1/2 in and 1/2 out of stub. Set 100' plug (58 sx) 13 3/8" shoe (350'). WOC and tag. Set 10 sx plug at surface. Weld on dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W. Jeffrey Sparks TITLE Engineer DATE 1/4/96

TYPE OR PRINT NAME W. Jeffrey Sparks TELEPHONE NO. (915) 683-5203

(This space for State Use)

APPROVED BY DISTRICT I SUPERVISOR

TITLE \_\_\_\_\_ DATE FEB 06 1996

CONDITIONS OF APPROVAL, IF ANY

mp