

Plugging Procedure for NLJV, Pruitt A # 2

- 1) Move in rig up service unit
- 2) Pull rod, pump
- 3) Nipple up BOP
- 4) Pull tubing
- 5) Run sinker bar to check PBTD
- 6) Run gauge ring to 50 ft above perforations, perfs 8850 to 8874
- 7) Run and set cast iron bridge plug @ 8800ft
- 8) Cap CIBP with 35 ft of cement by dump bailer
- 9) Run tubing and displace hole with mud laden fluid
- 10) Pull tubing
- 11) Weld on pull nipple and stretch casing estimated TOC 7021ft
- 12) Cut and pull 5.5" casing from free point,
- 13) Run tubing to 50ft inside of 5.5" casing stub and spot 35 sx cement
- 14) Pull tubing and WOC , Run tubing and tag cement top
- 15) Cement top should be 50 feet above 5.5 casing stub
- 16) Pull tubing to 4100 ft and spot 35 sx cement
- 17) Pull tubing to 2200 ft spot 30 sx cement salt plug
- 18) Pull tubing
- 19) Weld on pull nipple and and stretch csg estimated TOC 1979ft
- 20) Cut and pull 8.625" casing from free point
- 21) Run tubing to 50 ft inside of 8.625 stub
- 22) Spot 45 sx cement
- 23) Pull tubing and WOC, Run tubing and tag cement
- 24) Cement top should be 50 feet above 8.625 stub
- 25) Pull tubing to 410 ft spot 50 sx cement,
- 26) Pull tubing and WOC
- 27) Run tubing and tag cement plug at + or – 308ft
- 28) Pull tbg to 30 and spot 10 sx surface plug
- 29) Cut off wellhead and erect PA marker
- 30)
- 31)