

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-5353	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Sun Oil Company		8. Farm or Lease Name <del>New Mexico</del> St. Tract "D"
3. Address of Operator P.O. Box 1861, Midland, Texas 79701		9. Well No. 2
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>510</u> FEET FROM THE <u>West</u> LINE, SECTION <u>8</u> TOWNSHIP <u>11S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat Inbe Penn
15. Elevation (Show whether DF, RT, GR, etc.) GR 4195.6		12. County Lea

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

## 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull Kobe equipment.
2. Wash 2 sx. sand down tubing and spot 50 sx. cmt. from 9855-9405' over perfs.
3. Locate free point of 5-1/2" OD csg. and pull.
4. Run tubing and spot 50 sx. cmt 50' in and out of 5-1/2" csg. stub.
5. Spot 50 sx. cmt. 5457-5282'.
6. Spot 75 sx. cmt. 3940-3678, 50' in and out of 8-5/8" csg. shoe.
7. Locate free point of 8-5/8" csg. and pull.
8. Run tubing and spot 70 sx. cmt 50' in and out of csg. stub.
9. Spot 75 sx. cmt. 435-320, 50' in and out of 13-3/8" csg. shoe.
10. Place 10' plug at surface, cut off pipe and erect marker.
11. Clean up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Gray TITLE Proration Clerk DATE 6-22-72

APPROVED BY Joe D. Ramey TITLE Dist. I, Supv. DATE JUN 26 1972

CONDITIONS OF APPROVAL, IF ANY: