C
$\overline{}$

ENERGY AND MINERALS DEPARTMENT

TUGE WAS INVERNITED IN	LITAN	TIVIC.
HS. OF COMITS RECEIVED		
DISTRIBUTION		
BANTA FZ		
FILE		
U.S.G.S.		
LAND OFFICE		l
MOTARNEO		

## OL CONSERVATION DIVISION P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Page1 of 2

Form C-103 Revised 10-1-78

FILE	5a. Indicate Type of Lease
U.S.G.3.	State X Fee
LANO CIFICE	5, State Oil 6 Gas Lease No.
OFERRION	K-6101
CHNODY MOTICES AND DEDOCTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS TOO NOT USE THIS FORM FOR PROJUCTIVE TO THILL OH I O BEFFER ON PLUE SHALL TO A DIFFERENT USE "MARRICATION FOR PERMIT -" LYCHM C-101) FOR SUCH PROPOSALS.	AL JERVOIR.
11.	7. Unit Agreement Name
OIL Y WELL OTHER-	
2. Name of Operator	B. Farm of Lease Name
The Maurice L. Brown Company	State "17" .
3, Address of Operator	9. Well No.
Suite 200/Sutton Place Bldg./Wichita, Kansas 6720	
4. Location of Well	10. Field end Pool, or Wildent
UNIT LETTER K . 1980 FEET FROM THE SOUTH LINE AND 198	Vada Penn
THE West LINE SECTION 17 TOWNSHIP 10-S HANGE 34	F-15 name: [[]]]]]]]]]]]]]]]
15. Elevation (Show whether DF, RT, GR, etc.) 4235! GR; 4248! KB	Lea ()
Check Appropriate Box To Indicate Nature of Notic	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMIDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLI	
PULL OR ALTER CASING CASING TEST AND	
отна <mark>Вера:</mark>	ir Casing & Drill out Packer [X]
OTHER	@ 98001.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent) SEE RULE 1103.	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103.	nent dates, including estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103.	nent dates, including estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) see Rule 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH without with 3 7/8" OD bottom swedge, BS, Jars, DC's	nent dates, including estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent) see NULE 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH without with 3 7/8" OD bottom swedge, BS, Jars, DC's	ith tubing. Started in on 2 3/8" tubing.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) see Rule 1703.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79	ith tubing. Started in on 2 3/8" tubing.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent) see Note 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared	ith tubing. Started in on 2 3/8" tubing.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) see Rolle 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.	ith tubing. Started in on 2 3/8" tubing.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) see Rolle 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.	ith tubing. Started in on 2 3/8" tubing. ent through tight spot at dup. POH. Started in hole
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) see Note 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past tight to mush	ith tubing. Started in on 2 3/8" tubing. ent through tight spot at dup. POH. Started in hole
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) see Note 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past tight to mush	ith tubing. Started in on 2 3/8" tubing. ent through tight spot at dup. POH. Started in hole
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) see Rolle 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH withole with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past till with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to	ith tubing. Started in on 2 3/8" tubing.  ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent)  11-12-79  Moved in and rigged up PBCP Services, Inc. POH withole with 3 7/8" OD bottom swedge, BS, Jars, DC's  11-13-79  Completed going in hole with 3 7/8" OD swedge. We with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past till with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to	ith tubing. Started in on 2 3/8" tubing.  ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent) see Note 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH withole with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past time with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did and the properties out. Ban 34" OD collar locator. Have the part of the	ith tubing. Started in on 2 3/8" tubing.  ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth dkick at 7123' (5' above
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent) see Note 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH with ole with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past time with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Have taper tapes a same appliance.	ith tubing. Started in on 2 3/8" tubing.  ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth encount-19949' (Perfs. 9925'-32').
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) see NULE 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past till WIH with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Ha collar at 7128'). Ran 3 arm caliper. Caliper she collar at 7128'. WIH with 3½" OD bottom swedge.	ith tubing. Started in on 2 3/8" tubing.  ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-10 depth spot at 7131' depth. government of the spot at 7131' depth. encount-10 depth spot at 7131' de
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent) see auterios.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH whole with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past time with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Ha collar at 7128'). Ran 3 arm caliper. Caliper sh separation at 7123'. WIH with 3½" OD bottom swed 2.7/8 OD string mill. Went through spot at 7131'	ith tubing. Started in on 2 3/8" tubing. ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  without feeling anything.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent) see auterios.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH whole with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past time with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Ha collar at 7128'). Ran 3 arm caliper. Caliper sh separation at 7123'. WIH with 3½" OD bottom swed 2.7/8 OD string mill. Went through spot at 7131'	ith tubing. Started in on 2 3/8" tubing. ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  without feeling anything.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent) see Aule 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH whole with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past time with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Has collar at 7128'). Ran 3 arm caliper. Caliper sh separation at 7123'. WIH with 3½" OD bottom swed 3 7/8 OD string mill. Went through spot at 7131' Torqued up once then was clear when rotating and	ith tubing. Started in on 2 3/8" tubing. ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  without feeling anything.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent) see No. 11-12-79  Moved in and rigged up PBCP Services, Inc. POH with a 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past time with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Ha collar at 7128'). Ran 3 arm caliper. Caliper sh separation at 7123'. WIH with 3½" OD bottom swed 3 7/8 OD string mill. Went through spot at 7131' Torqued up once then was clear when rotating and POH.	ith tubing. Started in on 2 3/8" tubing.  ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth encount-0949' (5' above owed possible hole or casing ge, 1 joint 2 3/8" OD tubing, without feeling anything. going through tight spot.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent) see Aule 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH whole with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past time with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Has collar at 7128'). Ran 3 arm caliper. Caliper sh separation at 7123'. WIH with 3½" OD bottom swed 3 7/8 OD string mill. Went through spot at 7131' Torqued up once then was clear when rotating and	ith tubing. Started in on 2 3/8" tubing.  ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth encount-0949' (5' above owed possible hole or casing ge, 1 joint 2 3/8" OD tubing, without feeling anything. going through tight spot.
11-12-79 Moved in and rigged up PBCP Services, Inc. POH whole with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79 Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe. 11-14-79 Continued GIH with rotary. Could not get past time with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79 Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Has collar at 7128'). Ran 3 arm caliper. Caliper sh separation at 7123'. WIH with 3½" OD bottom swed 3 7/8 OD string mill. Went through spot at 7131' Torqued up once then was clear when rotating and POH.	ith tubing. Started in on 2 3/8" tubing. ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  without feeling anything, without feeling anything. going through tight spot.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent) see No. 11-12-79  Moved in and rigged up PBCP Services, Inc. POH with a 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past time with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Ha collar at 7128'). Ran 3 arm caliper. Caliper sh separation at 7123'. WIH with 3½" OD bottom swed 3 7/8 OD string mill. Went through spot at 7131' Torqued up once then was clear when rotating and POH.	ith tubing. Started in on 2 3/8" tubing. ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (Perfs. 9925'-32').  without feeling anything, without feeling anything. going through tight spot.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) see nucle 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH withole with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past till WIH with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Has collar at 7128'). Ran 3 arm caliper. Caliper sh separation at 7123'. WIH with 3½" OD bottom swed 3 7/8 OD string mill. Went through spot at 7131' Torqued up once then was clear when rotating and POH.	ith tubing. Started in on 2 3/8" tubing. ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (723' (5' above owed possible hole or casing ge, 1 joint 2 3/8" OD tubing, without feeling anything. going through tight spot.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) see nuce 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH withole with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past till with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Has collar at 7128'). Ran 3 arm caliper. Caliper sh separation at 7123'. WIH with 3½" OD bottom swed 3 7/8 OD string mill. Went through spot at 7131' Torqued up once then was clear when rotating and POH.  16.1 Invely certify but the information above intrue and complete to the best of my knowledge and Orig. Signed by	ith tubing. Started in on 2 3/8" tubing. ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. encount-0949' (723' (5' above owed possible hole or casing ge, 1 joint 2 3/8" OD tubing, without feeling anything. going through tight spot.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) see nucle 1103.  11-12-79  Moved in and rigged up PBCP Services, Inc. POH withole with 3 7/8" OD bottom swedge, BS, Jars, DC's 11-13-79  Completed going in hole with 3 7/8" OD swedge. We 7131'. Worked through tight spot until it cleared with 3 13/16" OD rotary shoe.  11-14-79  Continued GIH with rotary. Could not get past till WIH with taper tap. Took 4 points weight to push ered packer 12' high to previous trip. Bumped to 11-15-79  Completed POH with taper tap. No recovery. Did while coming out. Ran 3½" OD collar locator. Has collar at 7128'). Ran 3 arm caliper. Caliper sh separation at 7123'. WIH with 3½" OD bottom swed 3 7/8 OD string mill. Went through spot at 7131' Torqued up once then was clear when rotating and POH.	ith tubing. Started in on 2 3/8" tubing. ent through tight spot at dup. POH. Started in hole  ght spot at 7131' depth. POH. through tight spot. Encount-9949' (Perfs. 9925'-32').  not feel tight spot at 7131' depth. without feeling anything, without feeling anything. going through tight spot.