

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. <u>32-025-22619</u>	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. <u>K-3905 OG-5846</u>	
7. Lease Name or Unit Agreement Name <u>Peggy Com.</u>	
8. Well No. <u>1</u>	
9. Pool name or Wildcat <u>North Bagley Perm Perm</u>	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator <u>Tipperary Oil and Gas Corporation</u>	
3. Address of Operator <u>800 N. Marienfeld, Suite 100, Midland, Tx 79701</u>	
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>29</u> Township <u>11S</u> Range <u>33E</u> NMPM LEA County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4313' KB</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Run tubing to about 7250'. Circulate hole with produced water. Mix and spot 20 sx of cement on bottom. WOC and tag. Load hole with mud mixed at 25 sx gel per 100 bbls. Pump 20 sx plug across 8 5/8" shoe (3780'-3530'). Cut 4 1/2" casing and pull as much as possible (+2350'). Set 100' plug (25sx) 1/2 in and 1/2 out across the stub. Cut 8 5/8" casing and pull as much as possible (+650'). Set 100' plug (40 sx) 1/2 in and 1/2 out of stub. Set 100' plug (60 sx) across 13 3/8" shoe (370'). Set 10 sx plug at surface. Weld on dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W. Jeffrey Sparks TITLE Engineer DATE
TYPE OR PRINT NAME W. Jeffrey Sparks TELEPHONE NO. (915) 683-5203

(This space for State Use)

APPROVED BY TITLE DATE FEB 15 1990

CONDITIONS OF APPROVAL, IF ANY