

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.

K-2217

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Monsanto Oil Company	8. Farm or Lease Name State "K"
3. Address of Operator One Midland National Center, Ste 1300 Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER) 0 360 FEET FROM THE S LINE AND 1980 FEET FROM THE E LINE, SECTION 5 TOWNSHIP T10S RANGE 34E N.M.P.M.	10. Field and Pool, or Acreage Vada Penn
11. Elevation (Show whether DF, RT, GR, etc.) 4252	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1.) POH with production equipment.
- 2.) Set CIBP @ 9860'. Cap with 25' of cement.
- 3.) Mix mud using 10# brine and 25# of salt gal per bbl.
- 4.) RIH with tubing to TD and circulate hole with mud.
- 5.) PUE to 8900' and spot a 35 sack plug.
- 6.) Cut and POH the 5 1/2" casing.
- 7.) RIH to 50' inside the 5 1/2" casing stub and spot a 40 sack plug. WOC and tag.
- 8.) PUE to 5420' and spot a 45 sack plug.
- 9.) PUE to 4040' and spot a 50 sack plug 50' inside and out of 8 5/8" shoe. WOC and tag.
- 10.) PUE to 2720' and spot a 35 sack plug.
- 11.) PUE to 2160' and spot a 35 sack plug.
- 12.) Cut and pull 8 5/8" casing.
- 13.) RIH with tubing to the 8 5/8" stub and spot a 65 sack plug 50' in and out of stub.
- 14.) PUE to 400' and spot a 75 sack plug. 50' in and out of the 11 3/4" shoe. WOC and tag.
- 15.) POH and cut off wellhead. Place a 10 sack surface plug.
- 16.) Install a dry hole marker.

NOTE: All plugs will be displaced with mud.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>E. C. Bonting</i></u>	TITLE <u>Agent</u>	DATE <u>8-23-83</u>
APPROVED BY <u>ORIGINAL SIGNED BY EDDIE SEAY</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>AUG 25 1983</u>
CONDITIONS OF APPROVAL, IF ANY:		