

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K 2728

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL CO., INC.	8. Farm or Lease Name Humble State
3. Address of Operator P. O. Box 1069 - Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER E , 2086 FEET FROM THE North LINE AND 554 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 10-S RANGE 34-E N.M.P.M.	10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4214' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MINU. Pull rods, pump and tubing.
2. Set CIBP @ 9900'. Spot 35' cement plug. Displaced hole w/mud laden brine.
3. Cut off 5-1/2" casing @ free point (4023'). Pulled 5-1/2" casing.
4. Circulated w/mud laden brine.
5. Spot 40 sk cement plug across top of 5-1/2" casing @ 4023.
6. Cut off and pulled 8-5/8" casing @ 1021'. Spotted 70 sk cement plug across top of 8-5/8".
7. Spotted 70 sk cement plug @ 435', across 12-3/4" casing shoe.
8. Cut off wellhead and capped w/10 sk cement plug. Installed dry hole marker.
9. Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original Signed by Lloyd Wright TITLE Area Superintendent DATE 9-21-73

APPROVED BY John W. Runyan TITLE Area Superintendent DATE 9-21-73
CONDITIONS OF APPROVAL, IF ANY: