

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K2728

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL CO., INC.	8. Farm or Lease Name Humble State
3. Address of Operator P. O. Box 1069 - Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER E , 2086 FEET FROM THE North LINE AND 554 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 10S RANGE 34E NMPM.	10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4214' GR	12. County Lee

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIREU. Pull rods, pump and tubing.
2. Set CIBP @ 9900'. Spot 30' cement plug. Displace hole w/brine. + gel
3. Cut off 5-1/2" casing @ free point. Pull 5-1/2" casing. 100' plug @ CIBP
4. Spot 100' (35 sks) cement plug across top of 5-1/2" casing.
5. Spot 100' (35 sks) cement plug across 8-5/8" casing shoe.
6. Cut off and pull 8-5/8" casing @ free point. Spot 100' (70 sk) cement plug across top of 8-5/8" casing.
7. Spot 100' (70 sks) cement plug across 12-3/4" casing shoe.
8. Cut off wellhead and cap w/10 sk cement plug. Install dry hole marker.
9. Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by C. R. Tilley TITLE Area Production Foreman DATE 7-25-73

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: