State of New Mexico

Submit 3 Copies to Appropriate District Office	OIL CONSERVATION DIVISION		Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240			WELL API NO.
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 DISTRICT II P.O. Drawer DD Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		\$8 \$7504_2088	30-025-22740
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			5. Indicate Type of Lease STATE X FEE
			6. State Oil & Gas Lease No.
CUNDRY NO	TICES AND REPORTS ON WEL	10	K91112
(DO NOT USE THIS FORM FOR P DIFFERENT RES	ROPOSALS TO DRILL OR TO DEEPEN ERVOIR. USE "APPLICATION FOR PE C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well:	_		
MEIT X MEIT	OTHER		Continental State
2. Name of Operator			8. Well No. #2
Read & Stevens, Inc. 3. Address of Operator	•		9. Pool name or Wildcat
1 ·	ell, New Mexico 88202-15	518	Vada Penn/Lane Abo
4. Well Location Unit Letter : 66	O Feet From The South	Line and 660	Feet From The West Line
Section 7	Township 10S Ra	nge 34E	NMPM Lea County
	4201		
11. Check	Appropriate Box to Indicate I		eport, or Other Data
	ITENTION TO:		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB
OTHER:		OTHER:	U
	rations (Clearly state all pertinent details, an	d give pertinent dates, inclu	ting estimated date of starting any proposed
work) SEE RULE 1103. Read & Stevens,	Inc. proposes to	plug and aba	andon the subject well as
follows:			
1) Set a CIBP @ 8,800' above the Abo formation, and cap with 2 sx of cement.			
2) Set a 150' cement plug @ 6,800', top of the Tubb formation. 3) Cut and pull 5 1/2" csg from 5,000'.			
4) Set a 100' cement plug @ 4,000' across the 8 5/8" casing shoe and the top			
of the San An	dres.	agrage the to	on of the Anhydrite
5) Set a 100' cement plug @ 2,000' across the top of the Anhydrite. 6) Set a 100' cement plug across the base of the 12 3/4" casing shoe @ 408'.			
7) Set a surface	plug and cut off t	he wellhead,	install a dry hole marker
and clean and	l level location.		
n !		airaulatad u	ith 0 nng mud laden fluid
Prior to plugging	s, the well will be spotted with mud 1	circulateu w aden fluid.	ith 9 ppg mud laden fluid.
I hereby certify that the information above is to	me and complete to the best of my knowledge and	belief.	
John (1)			ineer bate August 14, 1995
John C. Maxey,			
TYPE OR PRINT NAME			TELEPHONE NO.
(This space for State Use)	14		AUG 85 1935
A DESCRIPTION BY	mı		DATE
CONDITIONS OF APPROVAL, IF ANY:			
CONTROL OF THE CONTRO			