

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K 2370	

## SUNDRY NOTICES AND REPORTS ON WELLS



(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plug & Abandon		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name State BJ
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		9. Well No. 1
4. Location of Well UNIT LETTER E, 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 9 TOWNSHIP 10S RANGE 34E NMPM.		10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4240' DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and abandonment operations commenced on 4/15/74. Unable to pull tbq from Model D pkr @ 9898'. Cut tbq @ 9824'. Set 50 sk cmt plug 9380-9824'. Displaced hole w/heavy mud. Tagged cmt plug w/wireline @ 9380'. Cut 5 1/2" csg w/jet cutter @ 4656'. Unable to pull. Cut 5 1/2" csg w/jet cutter @ 4250', 3950, 3650, 3350, 3050, 2750'. Pulled 2750' of 5 1/2" csg. Set 50 sk cmt plug 4325-4750'. Set 50 sk cmt plug 3605-4172'. Set 70 sk cmt plug 2656-2880'. Set 70 sk cmt plug 1964-2188'. Cut 8-5/8" OD csg @ 1000' & pulled (30 jts). Set 140 sk cmt plug 331-489'. Set 10 sk cmt plug @ surface. Welded on plate & installed regulation marker. Clean & level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED 	TITLE Dist. Drlg. Supv.	DATE 5/6/74
APPROVED BY 	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		