

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator John S. Goodrich	5. State Oil & Gas Lease No.
3. Address of Operator 304 C & K Building, Midland, Texas 79701	7. Unit Agreement Name
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1935 FEET FROM THE East LINE, SECTION 33 TOWNSHIP 11-S RANGE 33-E NMPM.	8. Farm or Lease Name Mathers
	9. Well No. 1
	10. Field and Pool, or Wildcat Bagley Penn. North
15. Elevation (Show whether DF, RT, GR, etc.) 4264 GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Run tubing and spot 100 sx cement plug at top of the 5-1/2" casing stub at 5770'.
2. Pull tubing to 3790' and spot 100' cement plug in and out 8-5/8" casing shoe at 3740'.
3. Pull tubing, cut and pull 8-5/8" casing at free point.
4. Run tubing and spot 100' cement plug at top of 8-5/8" casing stub.
5. Pull tubing to 454' and spot 100' cement plug in and out 13-3/8" casing shoe at 404'.
6. Pull tubing and set 10 sx cement plug at surface and install marker showing operator and location.

NOTE: 9.5# mud is now in hole and will be left between cement plugs.

Work to begin immediately upon approval

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *J. Goodrich* TITLE Operator DATE October 18, 1978

APPROVED BY *[Signature]* TITLE Geologist DATE 12/1/78

CONDITIONS OF APPROVAL, IF ANY *[Signature]*