

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Sun Exploration and Production Co.

3. Address of Operator
P.O. Box 1861, Midland, Texas 79702

4. Location of well
UNIT LETTER H 1980 FEET FROM THE North LINE AND 990 FEET FROM
THE East LINE, SECTION 27 TOWNSHIP 9-S RANGE 36-E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name
U.D. Sawyer

9. Well No.
9

10. Field and Pool, or Wildcat
Crossroads, Penn

15. Elevation (Show whether DF, RT, GR, etc.)

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice. Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

OTHER ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. Install BOP. Rise RDG pkr at 10495'. Load hole w/9.5 ppg mud laden fluid. POH and LD 2-7/8 tbg and pkr.
2. RIH w/7" CIBP on 2-7/8 WS and set at 10500'. Spot 35' cmt on top of CIBP. PU tbg to 9300'.
3. Spot 100' CL C cmt plug from 9300'-9200' (top of Penn-9284'). POH w/2-7/8 tbg.
4. RU csg jacks, loc free point of 7" csg (TOC-9400'). Cut off csg, POH and LD 7" csg.
5. RIH w/2-7/8 tbg. Spot 100' CL C cmt plug in and out of csg stub. PU tbg to 4200'. WOC. tag top of plug. PU tbg to spot next plug.
6. If NOT able to isolate top of Abo-7690 w/csg stub plug, spot 100' CL C cmt plug from 7740'-7640'. PU tbg to 5560'.
7. Spot 100' CL C cmt plug from 5560'-5460'. (Top of Glorieta-5518'). PU tbg to 4290'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dee Ann Kemp TITLE Associate Acctg DATE 7-28-84

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT SUPERVISOR

TITLE

DATE

AUG - 1 1984

CONDITIONS OF APPROVAL, IF ANY:

U.D. Sawyer #9

8. Spot 100' CL C cmt plug across 9-5/8" shoe from 4290'-4190'. PU tbg, WOC, tag top of plug. PU tbg to 2250'.
9. Spot 100' CL C cmt plug from 2250'-2150', (top of Rustler-2197'). POH w/2-7/8 tbg.
10. Perf 9-5/8" csg at 350', 4 holes, w/4" csg gun, decentralized.
11. RIH w/2-7/8 WS and FB pkr, set pkr at 150'. Estb circ between 9-5/8 and 13-3/8 csg, obtain inj rate and press.
12. Circ cmt behind 9-5/8 csg and leave approx 100' cmt plug from 350'-250'. WOC. Rlse pkr and POH.
13. Spot 10 sx CL C cmt at surface. Place permanent marker in cmt. Cln up loc.