

N. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
L-274

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name -
2. Name of Operator Bridwell Oil Company	8. Farm or Lease Name N.M. 8 State
3. Address of Operator P.O. Box 2038 Abilene, Texas 79604	9. Well No. 2
4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>9-S</u> RANGE <u>33-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Flying "M" - San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4386 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug & Abandon Operations - Approximately April 1979. As follows:

1. Pull rods & tubing.
2. Set C.I.B.P. @ \pm 4400' w/35' cement on top.
3. RIH w/tubing. Circulate well w/10.2 ppg mud. POH.
4. Cut & recover 4 1/2" casing @ \pm 1950'.
5. RIH w/tubing to \pm 2000'. Set 100' (50 sxs.) cement plug. Tag plug.
6. Pull tubing to \pm 400'. Set 100' (75 sxs.) cement plug.
7. Set 15 sxs. cement plug in top of 8 5/8" w/4" steel pipe marker.

See attached sketch for well data & plug location.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Prod. Supt.</u>	DATE <u>1-17-79</u>
APPROVED BY <u>Jerry Sexton</u>	TITLE <u></u>	DATE <u>JAN 22 1979</u>
CONDITIONS OF APPROVAL, IF ANY <u>1. Supv</u>		

