

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ For ☒
5. State Oil & Gas Lease No.

Amended

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name Pruitt "D"
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>17</u> TOWNSHIP <u>9-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4298.6' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1133.

Propose to plug and abandon well as follows:

Move in service unit. Pull rods, pump, tubing anchor, and tubing. Run in hole with CIBP and set at 8750'. Pressure test CIBP to 500 PSI. Cap with 35' of cement. Run free point survey and cut 5½" casing 100' above free point. Pull 5½" casing. Fill hole to bottom of 8-5/8" casing (SA 3996') with plugging mud. Spot a 50 sack cement plug across the 5½" casing stub. Pull up and spot a 25 sack plug across the 8-5/8" casing shoe at 3996'. Run freepoint survey and cut 8-5/8" casing 100' above freepoint. Pull 8-5/8" casing. Fill hole to bottom of 12-3/4" casing with plugging mud. Spot a 50 sack plug across the 8-5/8" casing stub. Pull up and spot a 50 sack cement plug across 12-3/4" casing shoe. Spot a 10 sack surface plug. Weld on cap and erect PXA marker. (Use plugging mud between all plugs.)

100' PLUG FROM 400' TO 300'

0+5-NMOCD,H 1-HOU 1-W. Stafford,HOU 1-DMF

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Mark Freeman</u>	TITLE <u>Assist. Admin. Analyst</u>	DATE <u>12-17-82</u>
ORIGINAL SIGNED BY JERRY SEXTON		DEC 21 1982
APPROVED BY <u>DETROIT 1-1-1</u>	TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY: