	NEW MEXICO OIL CONSERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
U.S.G. S .		Sa. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		I-494
SUNDRY NOT (BO NOT USE THIS FORM FOR PROPOSALS TO USE "APPLICATION FOR PE	CES AND REPORTS ON WELLS D BAILL OR TO DEEPEN OR PLUG BACK TO A DIPPERENT RESERVOIR.	
, DIL X GAS WELL OTHER		7. Unit Agreement Name
WELL A WELL OTHER		
·		8. Farm or Lease Name
Stallworth Oil & Gas, Inc. . Address of Operator		Midwest-State
P. O. Box 479, Dallas, Tex	as 75221	2
. Location of Well		10. Field and Pool, or Wildcat
F 1980	FEET FROM THE West LINE AND 1980 FEET	Vada Penn
	FEET FROM THE LINE AND FEET	
THE North LINE, SECTION 2	TOWNSHIP 9-S RANGE 33-E N	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4341' GR iate Box To Indicate Nature of Notice, Report or	Lea
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CABING Plug and Abandonment X
CTHER	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
² EMPORARILY ABANDON ³ ULL OR ALTER CASING ³ Describe Proposed or Completed Operations (work) SEE RULE 1703. ³ Plugging Operations: 7/19/ cement on top of plug with casing to 63" stretch and s laying down casing. 7/21/7 6480.15' of 5-1/2" casing. stub. 7/22/76 - Loaded hol 6530' to 6430' with 30 sx c over Glorieta from 5245' to third 100' plug at 8-5/8" c plugs were spotted through placement. 7/23/76 - Remov casing. Shot 8-5/8" casing second shot at 1196', worke casing. Ran 2-7/8" tubing 45 sx of cement. Picked up shoe from 440' to 340' with	COMMENCE DRILLING OPNS.	<pre>PLUG AND ABANDONMENT wing estimated date of starting any proposed ' and placed 35' of 7/20/76 - Worked 5-1/2" ed loose and began d 158 joints, or ement plug at 5-1/2" ted 100' plug from d second 100' plug p tubing and spotted sx of cement. All t gel used for dis- began working 8-5/8" e. Performed r 1245.30' of 8-5/8" 46' to 1146' with</pre>
Describe Proposed or Completed Operations (work) SEE RULE 1703. Plugging Operations: 7/19/ cement on top of plug with casing to 63" stretch and s laying down casing. 7/21/7 6480.15' of 5-1/2" casing. stub. 7/22/76 - Loaded hol 6530' to 6430' with 30 sx of over Glorieta from 5245' to third 100' plug at 8-5/8" c plugs were spotted through placement. 7/23/76 - Remov casing. Shot 8-5/8" casing second shot at 1196', worke casing. Ran 2-7/8" tubing 45 sx of cement. Picked up shoe from 440' to 340' with Installed dry hole marker at	CHANGE PLANS CHANGE PLANS CHANGE PLANS Change PLANS Change PLANS Change Test and cement Jas other Clearly state all pertinent details, and give pertinent dates, inclu (76 - Set cast iron bridge plug at 9500 dump bailer. Loaded hole with water. Shot at 6484'. Circulated casing, work 76 - Completed pulling casing, recovered Began running 2-7/8" tubing to spot co le with brine water and salt gel. Spot of cement. Picked up tubing and spotted of 5145' with 30 sx of cement. Picked up easing shoe from 3950' to 3850' with 30 2-7/8" tubing with brine water and salt red casing head; welded lift nipple and g at 1518', but were unable to work free of casing loose and pulled 30 joints, on to 1246' and spotted 100' plug from 124 tubing and spotted second 100' plug at 65 sx of cement. Placed 10 sy coment	PLUG AND ABANDONMENT

BIGNED Allurray Contrelevent Inte Executive Vice-President	DATE 3/7/78
APPROVED OF APPROVAL, IF ANY:	-WH/LY 3 1978

RECENCED

.

t

MAR 91978

OIL CONSERVATION COMM. HOBBS, N. M.