

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL  
(Other instructions  
verse side)

FE  
re

Form approved.  
Budget Bureau No. 1004-1  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL

NM-0202771-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

SW-639

8. FARM OR LEASE NAME

Vada Pruitt

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Vada (Penn)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 1, T9S, R34E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐  
2. NAME OF OPERATOR  
Pyro Energy Corp  
3. ADDRESS OF OPERATOR  
6303 Harry Hines Blvd. Suite 206 Dallas, Texas 75235  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
Unit Letter I, 1980' FSL and 660 FEL, Section 1, T9S, R34E

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4321 gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐  
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐  
SHOOT OR ACIDIZE ☐ ABANDON\* ☐  
REPAIR WELL ☐ CHANGE PLANS ☐  
(Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
FRACTURE TREATMENT ☐ ALTERING CASING ☐  
SHOOTING OR ACIDIZING ☐ ABANDONMENT\* ☒  
(Other) ☐

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

P & A Report for the Vada Pruitt #2

- 1) MIRU
- 2) RIH w/ CIBP on 2 3/8 tbg and set @ 9713
- 3) Circ. hole w/ 9.5 #/gal mud
- 4) Spot 6 sx cement plug from 9713' - 9663'
- 5) PU to 8900' and spot 17 sx plug from 8900' to 8750'
- 6) PU to 6900' and spot 17 sx plug from 6900' to 6750'
- 7) PU to 5400' and spot 17 sx plug from 5400' to 5250'
- 8) POOH w tbg weld on pull nipple. Cut off 5 1/2 csg @ 3975'
- 9) POOH w/csg
- 10) GIH w/ 2 3/8 tbg and spot 18 sx plug from 4025' to 3925'. PU and w.o.c. for 3 hrs.
- 11) Tag plug, OK. POOH
- 12) Cut 8 5/8" csg @2100'. POOH.
- 13) GIH w/tbg and spot 56 sx plug from 2100'-2000'
- 14) PU and wait 3 hrs. Tag plug, Ok
- 15) PU and spot 74 sx plug from 453' to 353'. POOH
- 16) Set 50' plug to surface. Cut off Bradenhead, weld on plate and attach dryhole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Craig Ledbetter

TITLE Western District Engineer

DATE 6/10/86

(This space for Federal or State office use)

APPROVED BY Org. Spt. [Signature]

TITLE

DATE

8-20-86

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side