

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TWO
(Other instructions
reverse side)

ICATE*
OR RE

Budget Bureau No. 1004-1
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL

NM-0202771-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

SW-639

8. FARM OR LEASE NAME

Vada Pruitt

9. WELL NO.

2

10. FIELD AND POOL OR WILDCAT

Vada (Penn)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 1, T9S, R34E

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Pyro Energy Corp

3. ADDRESS OF OPERATOR

6303 Harry Hines Blvd. Suite 206 Dallas, Texas 75235

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

Unit Letter I, 1980' FSL and 660 FEL, Section 1, T9S, R34E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4321 gr.

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

P & A Report for the Vada Pruitt #2

- 1) MIRU
- 2) RIH w/ CIBP on 2 3/8 tbg and set @ 9713
- 3) Circ. hole w/ 9.5 #/gal mud
- 4) Spot 6 sx cement plug from 9713' - 9663'
- 5) PU to 8900' and spot 17 sx plug from 8900' to 8750'
- 6) PU to 6900' and spot 17 sx plug from 6900' to 6750'
- 7) PU to 5400' and spot 17 sx plug from 5400' to 5250'
- 8) POOH w tbg weld on pull nipple. Cut off 5 1/2 csg @ 3975'
- 9) POOH w/csg
- 10) GIH w/ 2 3/8 tbg and spot 18 sx plug from 4025' to 3925'. PU amd w.o.c. for 3 hrs.
- 11) Tag plug, OK. POOH
- 12) Cut 8 5/8" csg @2100'. POOH.
- 13) GIH w/tbg and spot 56 sx plug from 2100'-2000'
- 14) PU and wait 3 hrs. Tag plug, Ok
- 15) PU and spot 74 sx plug from 453' to 353'. POOH
- 16) Set 50' plug to surface. Cut off Bradenhead, weld on plate and attach dryhole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

Craig Ledbetter

TITLE

Western District Engineer

DATE

6/10/86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side