NO, DF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old C+102 and C+103
ANTAFE	NEW MEXICO O	IL CONSERVATION COMMISSION	Effective 1-1-65
ILE			
J.S.G.S.			5a. Indicate Type of Lease
AND OFFICE			State X Fee
PERATOR			5. State Oil & Gas Lease No.
	}		LG-2369
IDO NOT USE THIS FORM FOR	DRY NOTICES AND REPO	ON PLUG BACK TO A DIFFERENT RESERVOIR.	
			7. Unit Agreement Name
WELL WELL WELL	OTHER-		8. Form or Lease Name
-	Ing		Landreth - State
V-F Petroleum,		· · · · · · · · · · · · · · · · · · ·	9. Well No.
Address of Operator	· · · · · ·	20201	1 1
901 Vaughn Build	ding, Midland, Te	exas /9/01	
Location of Well			10. Field and Pool, or Wildcat
м	1100 FEET FROM THE	lest 330	Crossroads South De
UNIT LETTER		10-South 36 East	
THELINE, SEC		RANGE NN	**** <u> </u>
		w whether DF, RT, GR, etc.)	Lea
	4007 G	ـــــــــــــــــــــــــــــــــــــ	
	Ann and Ren To Ind	lineta Natura of Nation Papart of	Other Date
		licate Nature of Notice, Report or	
NOTICE OF	INTENTION TO:	SUBSEQUI	ENT REPORT OF:
			_
ERFORM REMEDIAL WORK	PLUG AND ABAI	NDON REMEDIAL WORK	ALTERING CASING
		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
EMPORARILY ABANDON			
ULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	Г
		OTHER	
OTHER	······································		
			······································
	Operations (Clearly state all per	tinent details, and give pertinent dates, inclu	ding estimated date of starting any propose
work) SEE RULE 1103.			
1. Drilled 7-7,	/8" hole to 12,23	39. TD. Ran I DST.	
			0'. Cemented string
2 + 6 + 5 - 1/2"	17# £ 20# N-80. T	T&C new csg @ 12,235.5	0'. Cemented string
2. Set 5-1/2"	17# & 20# N-80, I l set @ 7996', (	LT&C new csg @ 12,235.5 Cemented first stage wi	th 450 SX HOWCO LITE
2. Set 5-1/2" with DV too	17# & 20# N-80, I 1 set @ 7996'. ()	T&C new csg @ 12,235.5 Cemented first stage wi	owed with 200 sx of
2. Set 5-1/2" with DV too	17# & 20# N-80, I 1 set @ 7996'. ()	T&C new csg @ 12,235.5 Cemented first stage wi	owed with 200 sx of
<pre>2. Set 5-1/2" with DV too plus 8# sal class "H".</pre>	17# & 20# N-80, I l set @ 7996'. C t per sack plus C 2nd stage with J	LT&C new csg @ 12,235.5 Cemented first stage wi ).3% CFR2 per sack foll 1000 sx Howco Lite foll	owed with 200 sx of
2. Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.	17# & 20# N-80, I 1 set @ 7996'. O t per sack plus O 2nd stage with I at 9:25 A.M. 9-14	LT&C new csg @ 12,235.5 Cemented first stage wi ).3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77.	owed with 200 sx of owed with 50 sx Class
2. Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.	17# & 20# N-80, I 1 set @ 7996'. O t per sack plus O 2nd stage with I at 9:25 A.M. 9-14	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77.	th 450 sx Howco Lite owed with 200 sx of owed with 50 sx Class eld.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O t per sack plus O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h a & 4-7/8" bit. Drill	owed with 200 sx of owed with 50 sx Class eld. DV tool out, drilled
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up Bushee cleaned</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with I at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12.239'.	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well	owed with 200 sx fowco lite owed with 200 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well	owed with 200 sx fowco lite owed with 200 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up Be shoe cleane</li> <li>Swabbing 16 pumping uni</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O t per sack plus O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h t & water dispose	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up Be shoe cleane</li> <li>Swabbing 16 pumping uni</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O t per sack plus O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h t & water dispose	LT&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well al system 9-28-77.	owed with 200 sx of owed with 50 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77.
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up Be shoe cleane</li> <li>Swabbing 16 pumping uni</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O t per sack plus O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h t & water dispose	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well al system 9-28-77.	th 450 sx Howco Lite owed with 200 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77. shut in waiting on
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up Be shoe cleane</li> <li>Swabbing 16 pumping uni</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O t per sack plus O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h t & water disposa	LT&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well al system 9-28-77.	th 450 sx Howco Lite owed with 200 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77. shut in waiting on
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up Be shoe cleane</li> <li>Swabbing 16 pumping uni</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O t per sack plus O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h t & water disposa	T&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well al system 9-28-77.	th 450 sx Howco Lite owed with 200 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77. shut in waiting on
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up Be shoe cleane</li> <li>Swabbing 16 pumping uni</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O t per sack plus O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h t & water disposa	LT&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well al system 9-28-77.	th 450 sx Howco Lite owed with 200 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77. shut in waiting on
<ol> <li>Set 5-1/2" with DV too plus 8# sal class "H". "H". P.D.</li> <li>WOC 72 hrs</li> <li>Rigged up B shoe cleane</li> <li>Swabbing 16 pumping uni</li> </ol>	17# & 20# N-80, I 1 set @ 7996'. O t per sack plus O 2nd stage with J at 9:25 A.M. 9-14 & tested casing t OP and ran tubing d out to 12,239'. bbls fluid per h t & water disposa	LT&C new csg @ 12,235.5 Cemented first stage wi 0.3% CFR2 per sack foll 1000 sx Howco Lite foll 4-77. to 2000 psi, pressure h g & 4-7/8" bit. Drill . 3-1/2 O.H. swab test hr. Cut 10% oil. Well al system 9-28-77.	th 450 sx Howco Lite owed with 200 sx of owed with 50 sx Class eld. DV tool out, drilled 9-20-77. shut in waiting on