

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
POST OFFICE BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS)		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>	
		5. State Oil & Gas Lease No.	
1. OIL GAS WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name	
2. Name of Operator Read & Stevens, Inc.		8. Farm or Lease Name Fawn Charlie	
3. Address of Operator Post Office Box 1518, Roswell, New Mexico 88202-1518		9. Well No. 1	
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE. SECTION 26 TOWNSHIP 10S RANGE 36E NMPM		10. Field and Pool, or Wildcat Dickerson San Andres	
5. Elevation (Show whether DF, RT, GR, etc.) 4004' RKB		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input checked="" type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
OTHER	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		<input type="checkbox"/>
OTHER	<input type="checkbox"/>		<input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging and Abandoning Procedure

- 1) Notify NMOCD 24 hrs before plugging operations are started. 505/393-6161.
- 2) Circulate the hole w/10 lb/gal Brine w/salt gel (32-35 vis)
- 3) Spot a 100' plug 1/2 in & 1/2 out of 5 1/2" casing shoe @4945', 5000'-4900', total 25 sx class "C" cement.
- 4) Spot a 100' plug at the top of the San Andres @4208', 4208'-4108', total 25 sx "C" cement
- 5) Perf 4 shots at the top of the salt section @2322', establish rate into formation, pump 100 sx class "C" cement into perfs, displace cement to 2100'. W.O.C. 4 hrs, tag plug.
- 6) Run free pt, cut casing at \pm 1000', spot 100' plug 1/2 in & 1/2 out of casing stub, total 40 sx class "C" cement.
- 7) Spot 100' plug 1/2 in & 1/2 out 8-5/8" casing shoe @360', 410'-310', total 40 sx class "C" cement.
- 8) Spot 10 sx surface plug, 0'-20'.
- 9) Install dry hole marker, clean location, cut off anchors & prep for inspection.

PLUGGING PROCEDURE APPROVED BY PAUL KAUTZ, NMOCD, HOBBS, NM.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Kautz TITLE Drilling and Production Manager DATE October 24, 1986

APPROVED BY Paul Kautz TITLE Geologist DATE OCT 26 1986