Avery matrix Different Name OIL CONSERVATION DIVISION P.O. Box 2088 WELL APINO 30-025-27123 DITECT BO, Areals, NM 8220 Sama Pe, New Mexico B7504-2088 30-025-27123 Similar BD, Areals, NM 8220 Sama Pe, New Mexico B7504-2088 30-025-27123 SUNDENT BO, Areals, NM 8220 Sama Pe, New Mexico B7504-2088 Similar Base No. 20-025-27123 COO NOT USE THIS FORM COR PROGRAMS TO PERMET (FOW ACUTOR NOTICES AND REPORTS ON WELLS (FOO NOT USE THIS FORM COR PROGRAMS TO PERMET (FOW ACUTOR SOLE PERME	_	State of New Mexico		Form C-103	
DITING 11 OIL CONSERVATION DIVISION 20-023-27123 DITING 11 Santa Fe, New Mexico 87504-2088 Ditter 11 Contart 108 Santa Fe, New Mexico 87504-2088 New Mexico 87504-2088 Ditter 11	Submit 3 Copies to Appropriate	Energy, Minerals and Natural Resources Department		Revised 1-1-89	
DTTICT_IL Sama Fe, New Mexico 87504-2088 3. Indexe Type of Last TATE (x) DTTICT_IL Sama Fe, New Mexico 87504-2088 3. Indexe Type of Last TATE (x) FE DTTICT_IL SUNDRY NOTREES AND REPORTS ON WELLS 6. Sur ON a G a Law M. Number 1 (DO NOT USE THIS FORM FOR PERCENCE USE APPLICATION FOR PERMIT (PERMIT 16/2004) 7. Lass Name of Usia Agreement Name 7. Lass Name of Usia Agreement Name 1 Operation Wall (X) onea 8. Well No. 1 1 South 4th St., Artesia, NM 88210 8. Well No. 1 3. Indexe Type Operator South 4th St., Artesia, NM 88210 Will cant Morrow 4. Well came South 4th St., Artesia, NM 88210 Will cant Morrow 10. South 4th St., Artesia, NM 88210 Base 34E NMMM 4. Well came Comparing 10. South 4th St., Artesia, NM 88210 Will cant Morrow 4. Well came Comparing 10. South 4th St., Artesia, NM 88210 Will cant Morrow Will cant Morrow 4. Well came Comparing 10. South 4th St., Artesia, NM 88210 Will cant Morrow Will cant Morrow 10. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORTOF: 11. C	DISTRICT	P.O. Box 2088			
DETINGUE 6 Suc OI & Get Lase No. VA-2112 IDD RD DENS Rd. Aute, NM ET410 6 Suc OI & Get Lase No. VA-2112 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DELL OR TO DESPEN OF PLUE BACK TO A DIFFERENT RESERVIC. USE APPLICATION OF PERMIT (FORM C-101) FOR SUCH PROPOSALS) 7. Less Name of Usia Agreement Name 1. Type of Weil Weil (S) ones 1. Judison Address State Com 2. Name of Operation 8. Weil No. 1. 1. South 4th St., Artesia, XM 88210 1. South 4th St., Artesia, XM 88210 1. South 4th St., Artesia, XM 88210 Wildcat Morrow 4. 1. Address of Operation 1. 5. Count 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSECUENT REPORT OF: 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data Count 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data Counter of Subsect Of Subsect OF: PERFORM REBIAL WORK PLUG AND ABANDON CHAMGE PLANS Counter of Subsect Of Subsect OF: PERFORM REBIAL WORK PLUG AND ABANDON CHAMGE PLANS Counter of Subsect Of Subsect OF: PERFORM REBIAL WORK PLUG AND ABANDON CHAMGE PLANS Counter of Subsect Of Subsect OF: 10	DISTRICT			5. Indicate Type of Lease	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILLOR TO DEEPEN OF PLUB BACK TOA DEFERENT RESERVOR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS) 7. Laws Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS) 1. Type of Will Will Composed on the second property of the second property of the second property YATES FETROLEUM CORPORATION 8. Well No. 1 1. June of Openity YATES FETROLEUM CORPORATION 8. Well No. 1 1. Addies of Openity YATES FETROLEUM CORPORATION 9. Pool asme or Wildest WildCat Morrow 1. June of Openity YATES FETROLEUM CORPORATION 9. Pool asme or Wildest WildCat Morrow 1. Addies of Openity YATES FETROLEUM CORPORATION 9. Pool asme or Wildest WildCat Morrow 1. Addies of Openity YATES FETROLEUM CORPORATION 8. Well No. 1 1. Addies of Openity YATES FETROLEUM CORPORATION 9. Pool asme or Wildest WildCat Morrow 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSECUENT REPORT OF: REMEDIAL WORK ALTERING GASING 1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSECUENT REPORT OF: REMEDIAL WORK ALTERING GASING 1. Method Adamboon FILE Second on create of Notice Report, or Other Data NOTICE OF INTENTION TO: SUBSECUENT REPORT OF: REMEDIAL WORK ALTERING GASING 1. Mill Chalars and spudded on surface plug at Sido Orners. PLUG AND ABANDONMENT CAMEROCE OFILING OPON.				6. State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN CHPLOUG BUCK TOA 7. Lase Name of Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN CHPLOUG BUCK TOA 7. Lase Name of Unit Agreement Name (DO NOT USE THIS FORM USE AFENORI USE APPLOTION TO THE PRINT 1. Judson Add# State Com 1. Type of Weit 0000 1 201 0000 5. Pool mame of Unit Agreement Name 1. Address of Openator 5. Pool mame of Wildent 10. South 4th St., Artesia, NM 88210 3. Address of Openator 10. South 4th St., Artesia, NM 88210 9. Pool mame of Wildent 3. Address of Openator 10. Second 105 20. Pool mame of Wildent 3. Main Constor 10. Second 105 20. Pool mame of Wildent 4. Wail Loant of United To Prove The South 10. Second 105 20. Pool mame of Wildent 4. Wail Loant of United To Prove The South 10. Second 105 20. Pool mame of Wildent 10. Bernator State of Prove The South Indicate Nature of Notice, Report, or Other Data 10. Second 105 20. Pool mame of Prove The South Indicate Nature of Notice, Report, or Other Data 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 10. Second 1000 Prove The South Indicate Nature of Notice, Report OF: PERFORM REMEDIAL WORK PLUG AND ABANDON Chance South				VA-2112	
1. Type of wall: Weil X Judson wArder State Com 2. Name of Operator 9. Weil No. 1 3. Adding of Operator 9. Pool same of Wildcat 1 105 South 4th St., Artesia, NM 88210 9. Pool same of Wildcat 1 4. Weil Loadion 1 1. State American Million 2000 10. Section 1000 10. Section 1000 4. Weil Loadion 1. Section 26 Towester 100. Section 1000 34E NMPM Lea Section 26 Towester 100. Section (Scow whether DP, RKD, RT, CR. 4c.) 4175.48' CR 10. Section 1000 Commy 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING Commerce and the section 1000 of section 10000 of section 1000 of section 1000 of section 1000 of s	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"				
2 Name of Openior 8. Well No. 1 YATES PETROLEUM CORPORATION 9. Pool sume of Wildox Wildcat Morrow 105 South 4th St., Artesia, NM 88210 Wildcat Morrow 4 Will Leased 660 Feet From The		OTHER			
NATES PERIOLEON CONFORTION 105 South 4th St., Artesia, NM 88210 Wildcat Morrow 105 South 4th St., Artesia, NM 88210 Wildcat Morrow 104 Well Lossion Wildcat Morrow Wildcat Morrow 105 South Lise and	2. Name of Operator				
1. Address a Openan Wildcat Morrow 105 South 4th St., Artesia, NM 88210 Wildcat Morrow 4 Well Loadie List St., Artesia, NM 88210 Wildcat Morrow 4 Well Loadie List St., Artesia, NM 88210 Wildcat Morrow 4 Well Loadie List St., Artesia, NM 88210 Wildcat Morrow 4 Well Loadie List St., Artesia, NM 88210 Wildcat Morrow 9 List St., Artesia, NM 88210 List St., GR, etc.) 9 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data Commy 10. Elevator (Show whith OF, RKR, Rf, GR, etc.) SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Altering CASING 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: PULL OR ALTER CASING Commence DFalling OFNs. PLUG AND ABANDON OTHER: OTHER OTHER. Spud on re-entry; perforate & acidize X 12. Detribe Proposed or Completed Openations (Clearly state all periversi detail, and give periversi data, including estimated data of starting any proposed work) SEE KULE 110. On setting Clearly state all periversi detail, and give periversi data data of starting any proposed 12. Detribe Proposed or Completed Openations (Clearly state					
Unit Letter L 1980 Feet From The South Line and 660 Feet From The West Line Section 26 Township 10. Range 34E NMTM Lea County 10. Distribution (Skow website) DF, RKS, RT, GR, etc.) 4175. 81 CR, etc.) 4175. 81 County 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK AltERING CASING County Control CHANGE PLANS CCOMMENCE DFILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER OTHER OTHER Spud on re-entry; perforate & acidize X 12. Desche Propoed or Completed Operations (Clearly state all perioses desis, and give periosed date; including estimated date of starting any proposed 3-18-2000 - Moved in and rigged up pulling unit. Rigged up re-entry; perforate & acidize X 3-18-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738'. TIH and 12.0200 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no 3-23-2000 - Drilled cement to 3750'. Reached TD at					
Unit Lifer					
Section 26 Township 105 Range 341 Model 10 Elevation (Abov whether DF, RKB, RT, GR, etc.) 4175.8' GR 4175.8' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTENING CASING PULL OR ALTER CASING COMMENCE OFILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: DOTHER: Specific of Section (Completed Operations (Clearly state all periosen dessit, and give periosent date, including estimated date of staring any proposed work) SEE RULE 103. 3-18-2000 - Moved in and rigged up pulling unit. Rigged up re=entry equipment. TIH with bit 6 drift collars and spudded on surface plug at 5:00 PM 3-17-2000. TIH woth 1100' and shut down. 3-19-20-2000 - Finished TIH with 7-7/8'' bit and cleaned out plug at 1738'. TIH and tagged plug at 3730'. Tested casing to 10000 ⁶ , OK. Shut well in. 3-21-2000 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed and reamed to 12360'. 3-23-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. Washed and reamed to 12360'. 3-23-2000 - Resumed to 14350'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. Washed and reamed to 12360'.					
4175.8' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON GRAMMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILING OPNS. PLUG AND ABANDONMENT COMMENCE DRILING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: Spud on re-entry; perforate & acidize 12. Decribe Proposed or Completed Operstices (Clearly state all periment data:, and give periment data: including estimated data of staring ary proposed word) SEE ROLE 1003. OTHER: DTHER: Spud on re-entry; eprforate & acidize 13. Decribe Proposed or Completed Operstices (Clearly state all periment data:, including estimated data of staring ary proposed word) SEE ROLE 1003. OTHER: DTHER: Spud on re-entry; eprforate & acidize 14. Decribe Proposed or Completed Operstices (Clearly state all periment data: including estimated data of staring ary proposed word) SEE ROLE 1003. OTHER: DOUD - Moved in and rigged up pulling unit. Rigged up re-entry equipment. TIH with bit & drill collarts and spudded on surface plug at 5:00 PM 3-17-2000. TIH worth 1100' and chait down. Data data data data data data data data	Township 105 Range SHL NMPM				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: Describe Proposed or Completed Operations (Clearly state all periment datas), and give periment datas, including estimated date of staring any proposed Work) SEE RULE 1103. 3-18-2000 - Moved in and rigged up pulling unit. Rigged up re-entry equipment. TIH with bit & drill collars and spudded on surface plug at 5:00 PM 3-17-2000. TIH woth 1100' and shut down. 3-19-20-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738'. TIH and 3-21-2000 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed and reamed to 12360'. S-21-2000 - Washed and reamed to 8883'. 3-23-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. Washed and reamed to 12360'. 3-24-2000 - Washed and reamed to 12360'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. Washed and reamed to 4883'. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P-110 varn	4175.8' GR				
NOTICE OF INTERVIEW. PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT 12. Describe Proposed or Completed Operations (Clearly state all periment datas, and give periment datas, including estimated data of staring any proposed work) SEE RULE 1103. OTHER: OTHER: DOTHER: Specific and spudded on surface plug at 5:00 PM 3-17-2000. TIH worth 1100' and shut down. 3-18-2000 - Moved in and rigged up pulling unit. Rigged up re-entry equipment. TIH worth 1100' and shut down. 3-19-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738'. TIH and tagged plug at 3730'. Tested casing to 1000#, OK. Shut well in. 3-21-2000 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed and reamed to 12360'. TIH to 10200'. Circulate and condition mud. Washed and reamed to 12360'. TIH to 10200'. Circulate 3-24-2000 - Kashed and reamed to 13350'.					
PERFORM REMEDIAL WORK PLUG AND ARAMON PLUG AND ARAMON PLUG AND ARAMON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRULLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING OTHER: CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB OTHER: OTHER: COMMENCE DRULLING OPNS. PLUG AND ABANDONMENT 12 Describe Proposed or Completed Operations (Clearly state all perivent details, and give periment date, including estimated date of staring any proposed work) SEE RULE 103. 3-18-2000 - Moved in and rigged up pulling unit. Rigged up re-entry equipment. TIH with bit & drill collars and spudded on surface plug at 5:00 FM 3-17-2000. TIH woth 1100' and shut down. 3-19-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738'. TIH and tagged plug at 3730'. Tested casing to 1000#, OK. Shut well in. 3-21-2000 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed to 7700'. Mixed 60 bbls oil in mud. Washed and reamed to 8883'. 3-23-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2". It.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2". 11.6# S/P_110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe Ibrety cerly the submodes bore is the and contexe to the best of my twor					
TEMPORAALLY ABANDON CANNEL FORM CONNECTIONS Connection Connection Connection Casing TEST AND CEMENT JOB PULL OR ALTER CASING CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB Connection Casing TEST AND CEMENT JOB 12. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of staring any proposed THER: Spud on re-entry; perforate & acidize X 13. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of staring any proposed TH with the starting estimated date of staring any proposed 14. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of staring any proposed TH with start estimates and spudded on surface plug at 5:00 PM 3-17-2000. TIH woth 1100' and shut down. 3-19-20-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738'. TIH and tagged plug at 3730'. Tested casing to 1000#, OK. Shut well in. 3-21-2000 - Porilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed and reamed to 12360'. Second - Finished TIH with 7-7/8" bit and cleaned out plug at 1738'. TIH and tagged plug at 500'. Washed and reamed to 12360'. 3-24-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000. Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" li.6# casing as follows: 48 joints of 4-1/2" li.6# S/P-110 san					
OTHER: Spud on re-entry; perforate & acidize X I2. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of staring any proposed work) SEE RULE 1103. 3-18-2000 - Moved in and rigged up pulling unit. Rigged up re-entry equipment. TIH with bit & drill collars and spudded on surface plug at 5:00 PM 3-17-2000. TIH worth 1100' and shut down. 3-19-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738'. TIH and tagged plug at 3730'. Tested casing to 1000#, OK. Shut well in. 3-21-2000 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed to 7700'. Mixed 60 bbls oil in mud. Washed and reamed to 8883'. 3-23-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. Washed and reamed to 12360'. 3-24-2000 - Washed and reamed to 13350'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P_110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe Inverse restly to full information bown if and complete to the test of my travelete set best of SHATURE					
12. Describe Proposed or Completed Operations (Clearly state all periment datails, and give periment datas, including estimated date of starting any proposed work) SEE RULE 1103. 3-18-2000 - Moved in and rigged up pulling unit. Rigged up re-entry equipment. TIH with bit & drill collars and spudded on surface plug at 5:00 PM 3-17-2000. TIH worth 1100' and shut down. 3-19-20-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738'. TIH and tagged plug at 3730'. Tested casing to 1000#, OK. Shut well in. 3-21-2000 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed to 7700'. Mixed 60 bbls oil in mud. Washed and reamed to 8883'. 3-23-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. Washed and reamed to 12360'. 3-24-2000 - Washed and reamed to 13350'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P-110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe CONTINUED ON NEXT PAGE: SNNATURE Mathematics above is flog and complete to the bet of my trowledge and belief. CONTINUED ON NEXT PAGE: 3NNATURE Rusty Klein TREPHONENO. 505/748-147.					
work) SEE RULE 1103. 3-18-2000 - Moved in and rigged up pulling unit. Rigged up re-entry equipment. TIH with bit & drill collars and spudded on surface plug at 5:00 PM 3-17-2000. TIH worth 1100' and shut down. 3-19-20-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738'. TIH and tagged plug at 3730'. Tested casing to 1000#, OK. Shut well in. 3-21-2000 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed to 7700'. Mixed 60 bbls oil in mud. Washed and reamed to 8883'. 3-23-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. Washed and reamed to 12360'. 3-24-2000 - Washed and reamed to 13350'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P_110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe Intervy centry target information above is five and complete to the best of my throwing a belief. CONTINUED ON NEXT PAGE: SIGNATURE TITLE Operations Technician Date Marker NAME Rusty Klein TELEPHONE NO. 505/748-147.	Othen				
3-18-2000 - Moved in and rigged up pulling unit. Rigged up re-entry equipment. 11H with bit & drill collars and spudded on surface plug at 5:00 PM 3-17-2000. TIH woth 1100' and shut down. 3-19-20-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738'. TIH and tagged plug at 3730'. Tested casing to 1000#, OK. Shut well in. 3-21-2000 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed to 7700'. Mixed 60 bbls oil in mud. Washed and reamed to 8883'. 3-23-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. Washed and reamed to 12360'. 3-24-2000 - Washed and reamed to 13350'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P-110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe Interfy cently that the information above is fly and complete to the best of my twowledge and belief. SIONATURE					
bit & drill collars and spudded on surface plug at 5:00 FM 3=17=2000. This worth field and shut down. 3-19-20-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738'. TIH and tagged plug at 3730'. Tested casing to 1000#, OK. Shut well in. 3-21-2000 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed to 7700'. Mixed 60 bbls oil in mud. Washed and reamed to 8883'. 3-23-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. Washed and reamed to 12360'. 3-24-2000 - Washed and reamed to 13350'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P-110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe CONTINUED ON NEXT PAGE: SIGNATURE	a to poop W multiment rigged up pulling unit. Rigged up re-entry equipment. Ill will				
3-19-20-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738 . TIH and tagged plug at 3730'. Tested casing to 1000#, OK. Shut well in. 3-21-2000 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed to 7700'. Mixed 60 bbls oil in mud. Washed and reamed to 8883'. 3-23-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. Washed and reamed to 12360'. 3-24-2000 - Washed and reamed to 13350'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P_110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe Intersty cardiy the to information above is five and complete to the best of my knowledge and belief. SKONATURE	bit & drill collars and spudded on surface plug at 5:00 PM 3-17-2000. The work floo				
tagged plug at 3730'. Tested casing to 1000#, OK. Shut well in. 3-21-2000 - Drilled cement to 3775'. Washed down - no plug at 4255'. Washed down - no plug at 5500'. Washed to 7700'. Mixed 60 bbls oil in mud. Washed and reamed to 8883'. 3-23-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. Washed and reamed to 12360'. 3-24-2000 - Washed and reamed to 13350'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P_110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe I hereby certify the for formation above is file and complete to the best of my knowledge and belief. SNONATURE	2-19-20-2000 - Finished TIH with 7-7/8" bit and cleaned out plug at 1738 . The and				
plug at 5500'. Washed to 7700'. Mixed 60 bbls oil in mud. Washed and reamed to 5005'. 3-23-2000 - Resumed washing down. Drilled plug from 9540-10086'. TIH to 10200'. Circulate and condition mud. Washed and reamed to 12360'. 3-24-2000 - Washed and reamed to 13350'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P-110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe I hereby cartify that the information above is file and complete to the best of my knowledge and belief. SHONATURE	1 1	Tostod casing to 1000)#. OK. Shut v	well in.	
3-23-2000 - Resumed washing down. Drilled plug from 9540-10088°. Till to 10200°. Officiente and condition mud. Washed and reamed to 12360'. 3-24-2000 - Washed and reamed to 13350'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P-110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe I hereby cardiy that the information above is fly and complete to the best of my knowledge and belief. SHONATURE		. J L. 77001 Mired 60 1	hhle oil in mu	a. Washed and reamed to boos .	
3-24-2000 - Washed and reamed to 13350'. Reached TD at 11:00 AM 3-23-2000. Circulate and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P-110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe Ihereby certify that the information above is flue and complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE: SHONATURE Mathematical complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE: SHONATURE Mathematical complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE: SHONATURE Mathematical complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE: SHONATURE Mathematical complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE: SHONATURE Mathematical complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE: SHONATURE Mathematical complete to the best of my knowledge and belief. Continue c	3-23-2000 - Resumed	washing down. Drilled	plug from 9540	-10086'. TIH to 10200'. Circulate	
and condition mud. TOOH & laying down drillpipe. 3-25-2000 - Changed rams in BOP to 4-1/2". Ran 319 joints of 4-1/2" 11.6# casing as follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32') and 271 joints of 4-1/2" 11.6# S/P-110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe I hereby certify the the information above is flue and complete to the best of my knowledge and belief. SKONATURE	3-24-2000 - Washed and reamed to 13350'. Reached TD at 11:00 AM 3-23-2000. Circulate				
follows: 48 joints of 4-1/2" 11.6# S/P-110 sandblasted (2010.32") and 271 joints of 4 1/2 11.6# S/P-110 varnished (11340.08') (Total 13350.40') of casing set at 13349'. Float shoe Ihereby certify the information above is file and complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE: skonature Waty Thur The Operations Technician Date Date Date 0 TYPE OR FRINT NAME CF.C. Date Date	1 Jisting mud TOON & lowing down drillpipe.				
11.6# S/P-110 varnished (11340.08') (Total 13350.40') of casing set at 15549 . Float shot I hereby certify that the information above is the and complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE: skonature	(11) (2010.32) and (211.32) (11.6) (2010.32) and (211.32) (11.5) $(11$				
I hereby certify the the information above is five and complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE: SKONATURE Interestion Date Sept. 22, 2000 TYPE OR PRINT NAME Rusty Klein Operations Technician Date Sept. 22, 2000 TYPE OR PRINT NAME CF.C APPROVED BY Date	11.6# S/P-110 varnished (11340.08') (Total 13350.40') of casing set at 15349. Float shoe				
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-147. (This space for State Use) CF.C. Difference APPROVED BY Date	I hereby certify that the information above is into and complete to the beat of my knowledge and center.				
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-147. (This space for State Use) CF.C. DATE	SKINATURE Muster P	fen m	Operations		
APPROVED BY DATE DATE	Rusty Kle	in	·	теlерноме NO. 505/748-1471	
APPROVED BY DATE DATE	(This space for State Use)				
APPROVED BY	/t · · ·				
CONDITIONS OF AFFRICALL F ANY:		<u> </u>	NS <u>- i - i - i - i - i - i - i - i - i - </u>		

YATES PETROLEUM CORPORATION Judson AUU State #1 Section 26-T10S-R34E Lea County, New Mexico

SUNDRY NOTICE CONTINUED:

3

set at 13349'. Float collar set at 13306'. Bottom marker set at 10500'. Top marker set at 12000'. Pumped 150 bbls mud w/100 scf/bbl N2 and 500 gallons of mud flush ahead of 700 sacks 65-35-6 BJ Lite cement (yield 1.99, weight 12.4). Tailed in with 250 sacks Super Modified C (yield 1.63, weight 13.5). PD 10:50 PM 3-24-2000. Bumped plug to 2800 psi for 1 minute, OK. WOC. Displaced with 206 bbls 2% KCL water. Set slips with 115000#. Nippled down BOP and cut off stub. Nippled down spool. Nippled up 11-1/2" X 7-1/16" 5K tubinghead. Capped with B-1 adapter. Shut well in. WOC. 3-26-27-2000 - Cleaned location. Rigged down pulling unit and re-entry equipment. Waiting on completion unit.

5-6-8-2000 - Moved in and rigged up pulling unit. Rigged up wireline. TIH with logging tools and ran CBL/GRlog. TOOH with logging tools and rigged down wireline.
5-9-2000 - TIH with bit, scraper and tubing to 6000'. TOOH. TIH with bit, drill collars and tubing and tagged up at 13326' (tubing measurement). Nippled up BOP. Shut well in.
5-10-2000 - TOOH with bit, drill collars and tubing. Rigged up wireline. TIH with logging tools and ran GR/CNL log. TOOH with logging tools and rigged down wireline. TIH with bit, drill collars and tubing.
5-11-2000 - Rigged up swivel. Drilled float collar and 25' of shoe joint. Circulated clean. TOOH. Rigged up wireline. TIH with 3-3/8" casing guns and perforated 13292-13303'

w/22 .42" holes as follows: 13292-13294' and 13296-13303' (2 SPF - Woodford Sand). TOOH with casing guns and rigged down wireline. TIH with Arrowset packer with 1.81" on/ off tool and set at 13220'. Nippled down BOP and nippled up tree. Flanged up. Swabbed tubing down. Shut well in.

5-12-2000 - Swabbed. Rigged up treesaver. Acidized perforations 13292-13303' (Woodford Sand) with 1000 gallons 7-1/2% Morrow acid with 1000 scf/bbl N2. Rigged down treesaver. Swabbed & flow tested. Shut well in.

5-13-15-2000 - Bled well down. Swabbed. Shut well in. 5-16-2000 - Bled well down. Swabbed. Shut well in.

Operations Technician September 22, 2000