

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
V-16	
7. Unit Agreement Name	
8. Farm or Lease Name	
Susco Bough "C" Unit	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Inbe Permo Penn	
12. County	
Lea	

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: SWD	
2. Name of Operator	
Southern Union Exploration Company	
3. Address of Operator	
1217 Main Street, Suite 400	
4. Location of Well	
UNIT LETTER J 1980 FEET FROM THE East LINE AND 1980 FEET FROM THE South LINE, SECTION 35 TOWNSHIP 10S RANGE 33E NMPM.	

15. Elevation (Show whether DF, RT, GR, etc.)  
4196.5' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1509.

1. RIH & set a CIBP @ 9700'.
2. RIH & dump 2 sks cement on top of CIBP.
3. RIH w/tubing and circulate the hole w/9.5 ppg mud. POH.
4. RIH and cut off casing @ 5500'. POH w/casing.
5. RIH w/tubing and spot 50 sk plug from 5550-5450'.
6. Pull up and spot a 60 sk plug from 4040-3940'.
7. Pull up and spot a 65 sk plug from 450-350'. POH.
8. Dig out and cut off wellhead.
9. Spot 5 sk plug @ surface.
10. Install dry hole marker.
11. Clean up location.

ANTICIPATED PLUGGING DATE: 11/25/85

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED David W. Stevens Drilling and TITLE Production Engineer DATE November 1, 1985

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE NOV 5 - 1985

CONDITIONS OF APPROVAL, IF ANY: