

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	<u>30-025-27922</u>
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Santa Fe VC	
8. Well No.	<u>1</u>
9. Pool name or Wildcat	West Sawyer San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3975.6' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>G</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>East</u> Line Section <u>8</u> Township <u>10S</u> Range <u>37E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3975.6' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. NOTE: 25#/barrel salt gel mud between plugs.

Propose to plug and abandon well as follows:

1. Set CIBP in 4-1/2" casing at 4900' and cap with 35' of cement. Freepoint 4-1/2" casing and cut and pull. Expect to pull from 3600' by cement bond log.
2. GIH w/tubing. Spot 50 sack plug from 50' inside 4-1/2" stub. Tag this plug.
3. Spot 50 sack plug at 2950' (Base of Salt at 2870').
4. Freepoint and pull 7" casing. 7" casing was set at 2093' with no cement.
5. GIH w/tubing. Spot 75 sack plug from 2450'. Tag this plug at 2200' or higher (top of salt at 2363' and anhydrite at 2258').
6. If 7" has to be cut, will spot at 50 sack plug 50' inside 7" stub.
7. Spot 50 sack plug across 8-5/8" shoe at 560'. Tag this plug.
8. Set 15 sack surface plug. Install regulation abandonment marker.

NOTE: NOTIFY NMOCD (393-6161) 24 HOURS BEFORE COMMENCING OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE June 17, 1993
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 22 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 21 1993

CHOBBS
100