

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

Form C-103

Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P.O. Box 2088
SANTA FE, NEW MEXICO 87501

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

LH-1376

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-1011 FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/>		GAS WELL <input type="checkbox"/>		OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Read & Stevens, Inc.						8. Farm or Lease Name North Mescalero	
3. Address of Operator P.O. Box 1518, Roswell, NM 88201						9. Well No. 1	
4. Location of Well UNIT LETTER <u>L</u> 1980 FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE. SECTION <u>2</u> TOWNSHIP <u>10S</u> RANGE <u>32E</u> NMPM						10. Field and Pool, or Wildcat Wildcat Siluro Devonian	
5. Elevation(Show whether DF,RT,GR,etc.) 4279.1' GR						12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input checked="" type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set CIPB @ 4050'. Spot 35' cement on top of CIPB w/ Dump Baller.
- 2) Circulate hole w/ salt mud.
- 3) Cut casing @ 2000'. Pull casing.
- 4) Spot 35sx plug 1/2 in and 1/2 out of casing stub.
- 5) Spot 35sx plug @ 1600'-1500'. (Top of salt)
- 6) Spot 35sx plug @ 450'-350'. (Surface casing shoe.)
- 7) Spot 10sx surface plug w/ 10'X4" Dryhole marker.
- 8) Clean location and prep for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

Bruce Stollis

TITLE Drilling & Production Manager

DATE 8-29-83

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON

TITLE

DATE AUG 31 1983

CONDITIONS OF APPROVAL DISTRICT SUPERVISOR

THE COMPLETION DATE IS NOTIFIED 24 HOURS AHEAD TO THE BEGINNING OF THE NEXT OPERATIONS FOR THE CLOSURE TO BE ACHIEVED.

RECEIVED
AUG 30 1983
C.C.D.
HOBBS OFFICE