

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 30064
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2174
7. Lease Name or Unit Agreement Name State "26"
8. Well No. 1
9. Pool name or Wildcat Vada (Devonian)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4196 GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☐ OTHER Saltwater Disposal

2. Name of Operator  
Western Reserves Oil Co. Inc.

3. Address of Operator  
P. O. Box 993, Midland, TX 79702

4. Well Location  
Unit Letter N : 330 Feet From The south Line and 2310 Feet From The west Line  
Section 26 Township 10S Range 33E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRUSU. Remove tubing flange & NUBOP. Release injection packer. TOH w/tubing string.
2. TIH w/5½" CIBP & 2 7/8" tubing to 12,600'. Set CIBP. (Note: Perfs 12,646-12678')
3. Circ hole w/300 bbls 10# brine w/150 sks SW gel. Spot 10 sk cmt plug on CIBP.
4. Pick up tubing to 8,850' & spot 25 sk plug from 8,850'-8,600'. (Wolfcamp)
5. Pick up tubing to 5,400' & spot 25 sk plug from 5,400'-5,160'. (Glorieta)
6. TOH w/work string & free point casing. Anticipate free pipe at approx 4,350'. cut casing w/4" jet cutter & pull & LD casing.
7. RIH w/tubing to 4,400' & set 100 sk cmt plug from 4,400'-4,050'. Tag plug.
8. Pick up to 1,950' & spot 35 sk plug to 1,850'.
9. Pick up to 30' & spot 12 sk plug at surface.
10. clean up location. Cut off anchors. Install dry hole markers.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Christopher P. Renaud TITLE Engineer DATE 12-13-95  
TYPE OR PRINT NAME Christopher P. Renaud TELEPHONE NO. 915 683-5533

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_ DATE DEC 19 1995

02 01 11

