

WESTERN RESERVES OIL COMPANY INC.

CENTURY PLAZA
310 WEST WALL, SUITE 301

802 993
MIDLAND, TEXAS 79702

PHONE (915) 683-5533

WESTERN RESERVES OIL CO., INC.
STATE "26" NO. 2 SIDETRACK
SEC. 26, T10S, R33E, LEA CO., NM

PROCEDURE TO PLUG AND ABANDON

1. Notify the New Mexico Oil and Conservation Commission (505) 393-6161 24 hrs. prior to the commencement of abandonment work.
2. MIRU abandonment rig. Install and test BOP.
3. TOH w/LOK set packer & 2 7/8" tubing.
4. TIH w/5 1/2" CIBP on tubing. Set CIBP at 12,490' and cap w/10 sacks cement.
5. Load hole w/60 BBLs (12,490 - 10,000') of 10 lb brine w/a gel strength of 25 lbs per barrel.
6. TOH w/2 7/8" tubing.
7. Run free point survey. Assume free pipe at approximately 10,000' from cement bond log.
8. Pull & lay down 10,000' of 5 1/2" casing.
9. Set 100' or 25 sack cement plug 50' in and out of 5 1/2" casing stub at approx 10,000'. Tag cement plug.
10. Load hole w/726 BBLs (120%) of 10 lb brine w/a gel strength of 25 lbs per barrel.
11. Set 100' or 25 sk cement plug at 8,850'. (T/Wolfcamp)
12. Set 100' or 25 sk cement plug at 5410' (T/Glorietta)
13. Set 100' plug 50' in and 50' out of 8 5/8" shoe at 4262' - 4162'.
14. Set 100' plug at 1,950' (Top Rustler)
15. Set 10 sk surface plug. Cut casing off 3' below ground level.
16. Set a dry hole marker 4' above the ground level. The marker will be 4" pipe. On the marker will be the following information:

Operator Name and Number
Well Name
Section, Township, Range
Unit letter or footage from the section line

17. Clean up location. RDMO.

By: Christopher P. Renaud
Western Reserves Oil Co., Inc.

RECEIVED

MAR 8 1990

OCD
HOBBS OFFICE