

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.  
30 025 31059

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
V-2174

7. Lease Name or Unit Agreement Name  
State "26"

8. Well No.  
4

9. Pool name or Wildcat  
Vada (Devonian)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
Western Reserves Oil Co. Inc.

3. Address of Operator  
P. O. Box 993, Midland, TX 79702

4. Well Location  
Unit Letter F : 2310 Feet From The North Line and 2310 Feet From The West Line  
Section 26 Township 10S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Notify NM Oil Conservation Division (505)393-6161 24 hrs prior to commencement of abandonment work.
- 2) MIRU abandonment rig. Install & test BOP.
- 3) TOH w/SN & 146 jts 2 3/8" tubing
- 4) TIH w/4 1/2" CIBP on tubing. Set CIBP at 4565' and cap w/35' cmt (5sks)
- 5) Load hole w/10ppg brine w/a gel strength of 25 lbs/bbl.
- 6) TOH w/tbg.
- 7) Run free point survey on 4 1/2" csg. Est TOC at 4,000' +/- from vol calculation.
- 8) Pull & lay down approx 4,000' of 4 1/2" casing.
- 9) Set 100' cement plug 50' in and out of 4 1/2" casing stub. Tag cmt plug.
- 10) Set 100' plug at 1950' (Top Rustler)
- 11) Set 10 sk surface plug. Cut casing off 3' below ground level.
- 12) Set a dry hole marker 4' above the ground level. The marker will be 4" pipe. On the marker will be the following information: (see back)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Engineer

DATE

5/9/91

(915)

TYPE OR PRINT NAME

Christopher P. Renaud

TELEPHONE NO. 683-5533

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Operator Name and Number  
Well Name  
Section, Township, Range  
Unit Letter

13) Clean up location. RDNO.

MAY 9, 1991

WESTERN RESERVES OIL CO. INC.

STATE "ZL" No. 4

UNIT F, SEC ZL, T10S, R33E

LEA COUNTY, NM

WELLBORE DIAGRAM

