7				
Submit 3 Copies District Office	State of New M Energy, Minerals and Natural I		- Y - Y	Form C-103 Revised 1-1-89
NSTRICT I O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION		WELL API NO.	
	F.O. BOX 2088		30-025-33743	
O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.		
	TICES AND DEPORTS ON WE			
DO NOT USE THIS FORM FOR DIFFERENT RE	DTICES AND REPORTS ON WE PROPOSALS TO DRILL OR TO DEEPE SERVOIR. USE "APPLICATION FOR P & C-101) FOR SUCH PROPOSALS.)	N OR PLUG BACK TO A	7. Lease Name or Un	il Agreement Name
Type of Well: OL OAS WELL X WELL	OTHER		Quota	AQT State
Name of Operator			8. Well No.	
YATES PETROLEUM CORP	ORATION		9. Pool name or Wild	
. Address of Operator 105 South 4th St., A	rtesia, NM 88210			U Penn
Well Location		· · · · · · · · · · · · · · · · · · ·		
Unit Letter F :	1980 Feet From The North	Line and19		ł
Section 1	Township 9S	Range 32E	NMPM I	Lea County
77777777777777777777777777777777	10. Elevation (Show wheth	415' GR		
1. Chea	k Appropriate Box to Indicate	e Nature of Notice, R	Report, or Other L	Data
	ck Appropriate Box to Indicate		BSEQUENT RE	
		SUE	BSEQUENT RE	
	NTENTION TO: PLUG AND ABANDON	SUE		PORT OF: TERING CASING
		SUE REMEDIAL WORK COMMENCE DRILLIN		
NOTICE OF I	NTENTION TO: PLUG AND ABANDON CHANGE PLANS	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER:_ <u>Perfora</u>	BSEQUENT RE	PORT OF: TERING CASING
NOTICE OF I ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER: 12 Describe Proposed or Completed O work) SEE RULE 1103. 3-8-10-97 - Swabber 3-11-97 - Rigged u tool. TIH with 4" 9254, 55, 56, 59, (1 SPF - Bough). and capped CIBP wi and 2-7/8" tubing. 15% iron control H 1/2 bbl of flush 1 1400 psi. Acidize acid and ball seal 1700 psi. Could m Acidized perforati sealers. Straddle	NTENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS Perations (Clearly state all periment details, d. Unset packer. TOOH p wireline. TIH with C casing guns and perfor 60, 9315, 16, 17, 18, 3 TOOH with casing guns a th 35' of cement. TOOH Straddle perforations CL acid and ball sealer eft. Pulled up and str d perforations 9315-935 ers. Pulled up and str ot get perforations to ons 9254-9260' with 100 d perforations 9254-940	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Perfora and give pertinent dates, inclu- with tubing and IBP and set CIBP ated 9254-9409' 8, 39, 40, 41, 5 nd rigged down w with dump baile 9407-9409' and s. Communicated addled perforati 2' with 1000 gal addled perforati break down. Pre- 0 gallons 15% in 9'. Swabbing.	AL GOPNS. PL EMENT JOB te & acidize wing estimated date of sta packer. at 9500'. To w/19 .41" hole 50, 51, 52, 940 orreline. TIH er. TIH with L acidized with d with upper pl ions 9315-9352 Llons of 15% i ions 9254-9260 essured annulu	PORT OF: TERING CASING
NOTICE OF I ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER: 12 Describe Proposed or Completed O work) SEE RULE 1103. 3-8-10-97 - Swabber 3-11-97 - Rigged u tool. TIH with 4" 9254, 55, 56, 59, (1 SPF - Bough). and capped CIBP wi and 2-7/8" tubing. 15% iron control H 1/2 bbl of flush 1 1400 psi. Acidize acid and ball seal 1700 psi. Could m Acidized perforati sealers. Straddle	NTENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS Perations (Clearly state all periment details, d. Unset packer. TOOH wireline. TIH with C casing guns and perfor 60, 9315, 16, 17, 18, 3 TOOH with casing guns a th 35' of cement. TOOH Straddle perforations CL acid and ball sealer eft. Pulled up and str d perforations 9315-935 ers. Pulled up and str ot get perforations to ons 9254-9260' with 100 d perforations 9254-940 is true sad, complete to the best of my knowledge	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Perfora and give pertinent dates, inclu- with tubing and IBP and set CIBP ated 9254-9409' 8, 39, 40, 41, 5 nd rigged down w with dump baile 9407-9409' and s. Communicated addled perforati 2' with 1000 gal addled perforati break down. Pre- 0 gallons 15% in 9'. Swabbing.	AL AL AL AL AL AL AL AL AL AL	PORT OF: TERING CASING
NOTICE OF I ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER:	NTENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS Perations (Clearly state all periment details, d. Unset packer. TOOH p wireline. TIH with C casing guns and perfor 60, 9315, 16, 17, 18, 3 TOOH with casing guns a th 35' of cement. TOOH Straddle perforations CL acid and ball sealer eft. Pulled up and str d perforations 9315-935 ers. Pulled up and str ot get perforations to ons 9254-9260' with 100 d perforations 9254-940 is true and complete to the best of my knowledge	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Perfora and give pertinent dates, inclu- with tubing and IBP and set CIBP ated 9254-9409' 8, 39, 40, 41, 5 nd rigged down w with dump baile 9407-9409' and s. Communicated addled perforati 2' with 1000 gal addled perforati break down. Pre- 0 gallons 15% in 9'. Swabbing.	AL AL AL AL AL AL AL AL AL AL	PORT OF: TERING CASING
NOTICE OF I ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER: 12 Describe Proposed or Completed O work) SEE RULE 1103. 3-8-10-97 - Swabber 3-11-97 - Rigged ur tool. TIH with 4" 9254, 55, 56, 59, (1 SPF - Bough). and capped CIBP wi and 2-7/8" tubing. 15% iron control H 1/2 bbl of flush 1 1400 psi. Acidize acid and ball seal 1700 psi. Could m Acidized perforati sealers. Straddle I hereby certify that the faformation above SIONATURE TYPE OR PRINT NAME Rusty KI	NTENTION TO: PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS Perations (Clearly state all periment details, d. Unset packer. TOOH p wireline. TIH with C casing guns and perfor 60, 9315, 16, 17, 18, 3 TOOH with casing guns a th 35' of cement. TOOH Straddle perforations CL acid and ball sealer eft. Pulled up and str d perforations 9315-935 ers. Pulled up and str ot get perforations to ons 9254-9260' with 100 d perforations 9254-940 is true and complete to the best of my knowledge	SUE REMEDIAL WORK COMMENCE DRILLIN CASING TEST AND C OTHER: Perfora and give pertinent dates, inclu- with tubing and IBP and set CIBP ated 9254-9409' 8, 39, 40, 41, 5 nd rigged down w with dump baile 9407-9409' and s. Communicated addled perforati 2' with 1000 gal addled perforati break down. Pre- 0 gallons 15% in 9'. Swabbing.	AL AL AL AL AL AL AL AL AL AL	PORT OF: TERING CASING UG AND ABANDONMENT LUG AND ABANDONMENT AUG AND ABANDONMENT LUG AND ABANDONMENT AGE: DATE March 19, 1997



YATES PETROLEUM CORPORATION Quota AQT State #1 Section 1-T9S-R32E Lea County, New Mexico

SUNDRY NOTICE CONTINUED:

3-12-97 - Continue swabbing.
3-13-97 - Swabbed. Unset packer. Dropped down and unset RBP. TOOH with tubing, packer and RBP. Rigged up wireline. TIH with cement retainer and set retainer at 9240'. Rigged down wireline. TIH with 2-7/8" tubing to retainer at 9240'.
3-14-97 - Sting into retainer at 9240'. Established injection rate into perforations 9254-9409' of 2-1/2 BPM at 2250 psi. Pressured annulus to 1000 psi. Mixed and pumped 150 sacks Class H, .5% FL62 and 50 sacks H Neat. With 118 sacks of cement in formation, squeezed perforations 9254-9409' to 6500 psi. Sting out of retainer and reversed 85 sacks cement to pit. TOOH with tubing.
3-15-97 - Rigged up wireline. TIH with 4" casing guns and perforated 9056-9140' with 22 .41" holes as follows: 9056-9065', 9098, 99, 9100, 01, 06, 07, 08, 09, 37, 38, 39 & 9140' (1 SPF - Bough B, C & D). TOOH with casing guns. Rigged down wireline. TIH with RBP, packer and 2-7/8" tubing. Set RBP at 9178'. Acidized perforations 9137-9140' with 5000 gallons 15% iron control HCL and ball sealers. Communicated with upper perforations with 1 bbl of flush left. Pulled up and straddled perforations

9098-9109'. Acidized perforations with 1000 gallons 15% iron control HCL acid and ball sealers. Tried to unset packer - packer stuck. Pulled 100K on tubing to open by-pass. Pumped down tubing thru bypass on packer and out of annulus. Packer came loose. Could not reset packer. TOOH with tubing and packer. TIH with new packer and tubing. Unset RBP. Pulled up and straddled perforations 9056-9140'. Acidized with 1000 gallons 15% iron control HCL acid and ball sealers. Straddled perforations 9056-9140' and began swabbing.

3-16-17-97 - Swabbed. Shut well in.

3-18-97 - Swabbed. Dropped downand unset RBP. TOOH with tubing, packer and RBP. Released well to production department.

Rustly Klein

Operations Technician March 19, 1997

