Submit 3 Copies to Appropriate District Office		New Mexico atural Resources Department	Form C-103 Revised 1-1-89
<u>DISTRICT I</u> P.O. Box 1980, Hobba, NM 88240	P.O. I	ATION DIVISION Box 2088	WELL API NO. 30-025-34862
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New N	Mexico 87504-2088	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No. V-4834	
(DO NOT USE THIS FORM FOR DIFFERENT RE	OTICES AND REPORTS C PROPOSALS TO DRILL OR TO ESERVOIR. USE "APPLICATION IM C-101) FOR SUCH PROPOSAL	DEEPEN OR PLUG BACK TO A FOR PERMIT	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL WELL	X OTHER		East Sand Springs Unit
2. Name of Operator YATES PETROLEUM CORI			8. Well No. 2
3. Address of Operator 105 South 4th St., A			9. Pool name or Wildcat
4. Well Location	······································		Wildcat Mississippian
Unit Letter N :	660 Feet From The Sou	th Line and 17	00 Feet From TheWest Line
Section 24	Tewnship 11.S 10. Elevation (Show	Range 34E whether DF, RKB, RT, GR, etc.)	NMPM Lea County
11. Che	ck Appropriate Box to Ind	4143' GR dicate Nature of Notice	Report or Other Data
	INTENTION TO:		BSEQUENT REPORT OF:
	CHANGE PLANS		
	-1		
ULL OR ALTER CASING	-1	COMMENCE DRILL	NG OPNS.
PULL OR ALTER CASING	C HANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:Perfor	
PULL OR ALTER CASING THER: 12. Describe Proposed or Completed O work) SEE RULE 1103. 5-16-2000 - Cleaned 5-17-2000 - TIH with Nippled up BOP. Sh 5-18-2000 - Pickled 10 stands. Shut we 5-19-2000 - TOOH wir ran GR/CBL log. TO 12980' w/27 .42" ho wireline. TIH with 5-20-2000 - Finishe orations 12954-1298 Swabbed. Shut well 5-21-22-2000 - Bled	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:Perfor details, and give periment dates, inc norş. Moved in and cubing and tagged PE llons of 15% HCL aci Rigged up wireline ls. TIH with 4" cas sippian). TOOH with with 1.81" profile t nd tubing. Set pack s of 15% iron contro d. Shut well in. ow tested. Shut wel widge md belief.	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Tate & acidize Finding estimated date of starting any proposed rigged up pulling unit. BTD at 13146'. Pulled up 20'. Id. Reversed acid out. Pulled e. TIH with logging tools and sing guns and perforated 12954- n casing guns and rigged down to 6000'. Shut well in. Ker at 12906'. Acidized perf- ol HCL acid. Bled well down. 11 in. CONTINUED ON NEXT PAGE:
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. 5-16-2000 - Cleaned 5-17-2000 - TIH with Nippled up BOP. Sh 5-18-2000 - Pickled 10 stands. Shut we 5-19-2000 - TOOH wi ran GR/CBL log. TO 12980' w/27 .42" ho wireline. TIH with 5-20-2000 - Finishe orations 12954-1298 Swabbed. Shut well 5-21-22-2000 - Bled we 1 hereby certify the the information above SKONATURE	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Perfor details, and give periment dates, inc nors. Moved in and cubing and tagged PE llons of 15% HCL aci Rigged up wireline ls. TIH with 4" cas sippian). TOOH with with 1.81" profile to nd tubing. Set pack s of 15% iron contro d. Shut well in. ow tested. Shut wel	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Orwork) SEE RULE 1103. 5-16-2000 - Cleaned 5-17-2000 - TIH with Nippled up BOP. Sh 5-18-2000 - Pickled 10 stands. Shut we 5-19-2000 - TOOH with ran GR/CBL log. TO 12980' w/27 .42" how wireline. TIH with 5-20-2000 - Finished orations 12954-1298 Swabbed. Shut well 5-21-22-2000 - Bled well 5-23-2000 - Bled well Stonature WMATHE Rusty K1	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:Perfor details, and give periment dates, inc norş. Moved in and cubing and tagged PE llons of 15% HCL aci Rigged up wireline ls. TIH with 4" cas sippian). TOOH with with 1.81" profile t nd tubing. Set pack s of 15% iron contro d. Shut well in. ow tested. Shut wel widge md belief.	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB Tate & acidize Finding estimated date of starting any proposed rigged up pulling unit. BTD at 13146'. Pulled up 20'. Id. Reversed acid out. Pulled e. TIH with logging tools and sing guns and perforated 12954- n casing guns and rigged down to 6000'. Shut well in. Ker at 12906'. Acidized perf- ol HCL acid. Bled well down. 11 in. CONTINUED ON NEXT PAGE:
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed O work) SEE RULE 1103. 5-16-2000 - Cleaned 5-17-2000 - TIH with Nippled up BOP. Sh 5-18-2000 - Pickled 10 stands. Shut we 5-19-2000 - TOOH wi ran GR/CBL log. TO 12980' w/27 .42" ho wireline. TIH with 5-20-2000 - Finishe orations 12954-1298 Swabbed. Shut well 5-21-22-2000 - Bled we 1 hereby certify the the information above SKONATURE	CHANGE PLANS	COMMENCE DRILLS CASING TEST AND CASING TEST AND OTHER: Perfor details, and give periment dates, inc norş. Moved in and tubing and tagged PE llons of 15% HCL aci Rigged up wireline ls. TIH with 4" cas sippian). TOOH with with 1.81" profile to nd tubing. Set pack s of 15% iron contro d. Shut well in. ow tested. Shut well wiedge and belief. Operations	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB
PULL OR ALTER CASING DTHER: 12. Describe Proposed or Completed Orwork) SEE RULE 1103. 5-16-2000 - Cleaned 5-17-2000 - TIH with Nippled up BOP. Sh 5-18-2000 - Pickled 10 stands. Shut we 5-19-2000 - TOOH with ran GR/CBL log. TO 12980' w/27 .42" how wireline. TIH with 5-20-2000 - Finished orations 12954-1298 Swabbed. Shut well 5-21-22-2000 - Bled well 5-23-2000 - Bled well Stonature WMATHE Rusty K1	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: Perfor details, and give periment dates, inc norş. Moved in and cubing and tagged PE llons of 15% HCL aci Rigged up wireline ls. TIH with 4" cas sippian). TOOH with with 1.81" profile t nd tubing. Set pack s of 15% iron contro d. Shut well in. ow tested. Shut well wiedge and belief. Operations	NG OPNS. PLUG AND ABANDONMENT CEMENT JOB

YATES PETROLEUM CORPORATION East Sand Springs ASU State #2 Section 24-T11S-R34E Lea County, New Mexico

SUNDRY NOTICE CONTINUED:

5-24-31-2000 - Shut in. 6-1-2000 - Shut in. Swabbed. Shut well in. 6-2-2000 - Bled well down. 6-3-7-2000 - Shut in. 6-8-2000 - Bled well down. Loaded tubing with 7% fluorosurfactant. Released packer. Circulate annulus capacity with 7%. Nippled down tree. BO2 coupler gauled and pin of top joint. Could not make up pick up sub. Waited on tubing spear. Pulled top joint out and laid down. Nippled up BOP. TOOH with tubing. Shut well in. 6-9-2000 - Rigged up wireline. TIH with 3-3/8" casing guns and perforated 13084-13114' w/132 .42" holes as follows: 13084-13096' and 13104-13114' (6 SPF - Woodford Sand (Miss). TOOH with casing guns and rigged down wireline. TIH with packer with 1.87" on/off tool. Nippled down BOP and nippled up tree. Set packer at 13033'. Flanged up. Swabbed tubing dry. Shut well in. 6-10-12-2000 - Swabbed. Rigged up treesaver. Acidized perforations 13084-13114' (via 2-7/8" tubing) with 2000 gallons 7-1/2% Morrow acid with 25% methanol with 1000 scf/bbl N2. Rigged down treesaver. Flowing well to pit for cleanup. Shut well in. Swabbed & flow tested. Shut well in. 6-13-2000 - Bled well down. Swabbed & flow tested. Shut well in. 6-14-2000 - Bled well down. 6-15-21-2000 - Shut in. 6-22-2000 - Bled well down. Swabbed. Loaded tubing with 7% fluorosurfactant. Released packer. Nippled down tree and nippled up BOP. Started out of hole with tubing. Shut well in. 6-23-2000 - TOOH with tubing. Rigged up wireline. TIH with gauge ring and junk basket to 12920'. TOOH. TIH with 5-1/2" CIBP and set CIBP at 12900'. Capped CIBP with 35' of cement. Rigged down wireline. TIH with 2.25" seating nipple and tubing to 9500'. Shut down due to storm. 6-24-2000 - Finished TIH with tubing to 11000'. Swabbed tubing and annulus down to 9600'. Shut well in. 6-25-26-2000 - Swabbed tubing and casing to 10000'. Shut well in. 6-27-2000 - Rigged up wireline. TIH with 4" casing guns and perforated 12200-12258' w/148 .42" holes as follows: 12200-12208', 12012-12019', 12224-12228' & 12244-12258' (4 SPF -Morrow). TOOH with casing guns and rigged down wireline. Flowed well to pit. Trickled 50 bbls 7% fluorosurfactant down casing. TIH with Arrowset packer and tubing. Nippled down BOP and nippled up tree. Set packer at 12169'. Loaded and tested annulus to 1000 psi. Swabbed tubing down. Shut well in. . 6-28-2000 - Bled well down. Swabbed. Rigged up treesaver. Acidized perforations 12200-12258' with 2500 gallons of 7-1/2% Morrow acid with 1000 scf/bbl N2 and ball sealers. Rigged down treesaver. Flowing well to pit. Shut well in. 6-29-2000 - Bled well down. Swabbed & flow tested. Shut well in. 6-30-2000 - Flow tested. Shut well in. 7-1-3-17-2000 - Shut well in.

Rust√ Klein

Operations Technician July 31, 2000

