

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Hayes
8. Well No. 3
9. Pool name or Wildcat Allison Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator SMITH AND MARRS, INC.	3. Address of Operator 1110 N. Big Spring Midland, Tx 79701	4. Well Location Unit Letter L : 1980 Feet From The S Line and 660 Feet From The W Line Section 29 Township 8S Range 37E NMPM Roosevelt County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4054'
--	--	--	--	---

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. We will notify the OCD prior to beginning plugging operations

- 1) Rig up pulling unit
 - 2) Set CIBP at 9540' and cap with 35' cmt.
 - 3) Run free point on 5 1/2" casing
 - 4) Cut and pull 5 1/2" and set 100' plug across stub, 50' in and 50 out.
 - 5) Set 100' at top of Abo at 7708'
 - 6) Set 100' plug at 8 5/8" shoe, 50' in and 50' out.
 - 7) Set 100' plug at top of Salt at 2350'.
 - 8) Set 10 sx at surface and install dry hole marker, clean location.
- * Hole will be loaded with 10# gel.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael L. Pierce TITLE Agent DATE 5-8-91
TYPE OR PRINT NAME Michael L. Pierce TELEPHONE NO. 392-1915

(This space for State Use)
Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE MAY 13 1991

CONDITIONS OF APPROVAL, IF ANY: