

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-02218
2. NAME OF OPERATOR Tom L. Ingram		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR POB 1757, Roswell, New Mexico 88201		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 FNL and 660 FWL of Section 28, T8S, R37E		8. FARM OR LEASE NAME King Davis <i>fed</i>
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4027 DF		10. FIELD AND POOL, OR WILDCAT Allison-Pennsylvanian
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <i>Sec 28-8-37</i>
		12. COUNTY OR PARISH Roosevelt
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10/31 thru 11/9/74:

Set CIBP @ 6300'. Put a 35' cement plug on top. Shot 7" csg. @ 4293-4251-4029. Pulled 7" from 4029. Put 100' plug from 4225 to 4325 inside casing. Put 100' plug from 3979 to 4079 in & out of stub of 7" and in 9-5/8" csg. Shot 9-5/8" csg. @ 747' and pulled. Set 100' plug @ 700 to 800 in and out of stub of 9-5/8. Set 100' plug at 325 to 425 @ base of 13-3/8. Set 10 sack plug @ surface with marker. Mud laden brine used between all plugs.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Operator

DATE

11/14/74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
JUL 12 1976

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED

JUL 2 1976

OIL CONSERVATION COMM.
HOBBS, N. M.

