

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

HOBBS OFFICE O.C.C.
Nov 21 8 27 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - Water Disposal Well		7. Unit Agreement Name -
2. Name of Operator Sumray DX Oil Company		8. Farm or Lease Name Nancy Watson
3. Address of Operator P. O. Box 1416, Roswell, New Mexico		9. Well No. 2
4. Location of Well UNIT LETTER K , 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 8S RANGE 34E N.M.P.M.		10. Field and Pool, or Wildcat Clf San Andres
11. Elevation (Show whether DF, RT, GR, etc.) 4312 GR		12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Present PBTD @ 4622'.
2. Top of cmt behind 4 1/2" prod. csg @ 3770'. 8 5/8" surf csg set @ 356' w/220 sxs cmt circulated to surface. 4 1/2" prod csg set @ 4658' w/250 sxs cmt. Perfs @ 4582-89'; 4592-95'; 4599'-4601' and 4610-14'.
3. Load hole w/mud.
4. Place 25 sxs cmt plug (4382-4622) to cover perfs.
5. Cut off 4 1/2" prod csg @ approx 3700'. Pull prod. csg. Keep hole loaded w/mud.
6. Place 25 sx cmt plug (3650-3740') in & out of 4 1/2" stub.
7. Place 25 sxs cmt plug (326'-386') in & out of 8 5/8" surf csg.
8. Set 10 sxs cmt @ surface.
9. Install dryhole marker.
10. Remove surface equipment & clean up location.

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B.F. Brawley B.F. Brawley TITLE District Engineer DATE 11-17-66

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: