

N. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NM 8 12-000

Form 3160-5
(July 1989)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECD.
OFFICE FOR NUM.
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BLM Roswell District
Modified Form No.
NM60-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER ☐ WIW		3a. Area Code & Phone No. (817) 559-3355	
2. NAME OF OPERATOR Breck Operating Corp.		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR P.O. Box 911, Breckenridge, TX 76424		9. WELL NO. 11	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter "N"; 660' FSL & 1980' FWL		10. FIELD AND POOL, OR WILDCAT Milnesand (San Andres)	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 5, T-8S, R-35E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4243' (GR)		12. COUNTY OR PARISH Roosevelt	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6/19/91: MIRU Ice Well Service. Rel pkr & POOH w/ 146 jts 2-3/8" PC tbg & pkr. Set 4-1/2" CIBP on WL @ 4550'. RIH w/ tbg to 4550'. Load hole w/ 9.5# mud. Pmp 5 sx cmt on top of CIBP. POOH w/ tbg to 3900'. Pmp 25 sx cmt. POOH w/ tbg. RU to pull csg. Det csg free @ 450'. Shoot csg @ 450'. POOH w/ 14 jts 4-1/2" csg. RIH w/ tbg to 472'. Pmp 64 sx cmt. POOH w/ tbg. SDON.

6/20/91: Tag TOC w/ WL @ 258'. RIH w/ 1 jt tbg. Pmp 15 sx cmt to surf. POOH w/ tbg. Cut off csg 3' below GR & weld on plate. RDMO.

6/25/91: Const dry-hole markker. Clean up loc.

18. I hereby certify that the foregoing is true and correct

SIGNED Kevin G. Duncan
(This space for Federal or State office use)

TITLE Petroleum Engineer

DATE 7-3-91

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side