TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACTUIZE

REPAIR WELL

COPY TO O. G. C.

REPAIRING WELL ALTERING CASING

ABANDONMENT*

Form 9-331 May 1963)	UNITED STATES	SUBMIT IN TRIPLICATT Other instructions on	Form approved. Budget Bureau No. 42-R1424.			
	DEPARTMENT (THE INTERIO)R verse side)	5. LEASE DESIGNATION AND SERIAL NO.			
	GEOLOGICAL SURVEY		LC 060978			
(D9 not us	SUNDRY NOTICES AND REPORTS Of this form for proposals to drill or to coopen or plug back "APPLICATION FOR PERMIT—" for such pro-	ek to a different reservoir.	6. IS INDIAN, ALLOTTEE OR TRUSE NAME			
ī			7. UNIT AGREEMENT NAME			
	NELL OTHER		Milnesand Unit			
2. NAME OF OPERA	ATOR		8. FARM OR LEASE NAME			
IU	NION TEXAS PETROLEUM CORPORATION					
3. ADDRESS OF OP		-16)	9. WELL NO.			
1:	300 Wilco Building, Midland, Texas	79707 () [] [] []	39			
1. LOCATION OF W See also space	ELL (Report location clearly and in accordance with any S	The requirements	10. FIELD AND POOL, OR WILDCAT			
At surface	' / 1	4019	Milnesand San Andres 11. SEC, T, R, M, OR BLK. AND SURVEY OR AREA			
	980' FNL & 624' FWL	CFOLOGICAL SEXICO	Sec. 19, T-8-S, R-35-F			
14. PERMIT NO.	980' FNL & 624' FWL 15. ELEVATIONS (Show whether DF a) 4247.5' KB Check Appropriate Box To Indicate No.	HOBBS. NEW	Roosevelt New Mexico			
16.	Check Appropriate Box To Indicate No	iture of Notice, Report, or C	Other Data			
	1	arinano.	COVE DEDONG OF			

(Nore: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1. MIRUSU, install BOP PU pkr., SN & Tubing string.
- 2. Set 2 3/8" x 4½",10.5# pkr. @ 4540'+. Pump 12 bbls. crude oil and 2 drums Tretolite converter (SP-221) and $SI\overline{ON}$.

WATER SHUT-OFF

(Other) .

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

- 3. Pull equipment. GIH and latch onto fish and recover. Clean out rat hole to 4703'. Circ. hole w/2% KCL wtr.
- 4. Pull tools, PU pkr. SN and tbg. GIH, set pkr. @ 4550'.
- 5. Acidize w/1000 gal. 20% HCL and 40 gal. SP-205.
- 6. Pull equipment and run prod. tubing.

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

- 7. Test well, shot fluid levels.
- 8. Evaluate well for possible additional stimulation.

SIGNED Storad The foreging is true and correct	TITLE	Prod. Analyst		DATA	8/13/79	
(This space for Federal or State office use)		[ADI	ORO	VED		<u> </u>
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLL: _		3EP 4	1979 PATE	(U)	
*Se	e Instructi	ons on Reverse Side	G DISTRI	CT ENGINEE	R	